

Vehicle Inspection Report

Report No. TP-0153/01/19	Date of Report	: 14/03/2019
To : EQ Insurance Company Ltd	Date of Request	: 15/01/2019
5 Maxwell Road	Report requested by	: Mr. Joel Goh
17-00 Tower Block, MND Complex	Date of Inspection	: 16/01/2019
Singapore 069110	Date of Accident	: 14/01/2019
	Sum Insured	: -
Policy No :	Excess (S\$)	: N/A
Claim No : Third Party Claim	Insured Vehicle	: GBG 1695 C

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: JQB 737	Odometer Reading	: 195185 km
Make / Model	: Lexus ES250 (A)	Radio / CD	: Yes
Year of Manufacture	: 2014	Air-conditioner	: Yes
Colour	: Pearl White	Wing Mirror	: Yes
Engine Capacity	: 2494 cc	View Cam	: Yes
Engine No	: -	Seat Belts	: Yes
Chassis / Frame No	: JTHBJ1GGX020447747	Accessories	: Nil
Carrying Capacity	: 4		

TYRE CONDITION

Front Left	: 6mm	Front Right	: 6mm
Make	: Michelin	Make	: Michelin
Rear Left	: 6mm	Rear Right	: 6mm
Make	: Michelin	Make	: Michelin
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Tools	: Intact	Spare tyre	: Intact
-------	----------	------------	----------

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (static tests only)

General bodywork	: Good
Paintwork	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

ASSESSMENT

		Repairer's Estimate (S\$)	Our Recommendation (S\$)
Spare Parts	:	30,619.67	16,355.34
Labour Charges	:	3,460.00	1,250.00
Paint Work	:	2,000.00	1,200.00
Towing Charges	:	0.00	0.00
Others	:		
Totals	:	36,079.67	18,805.34

Reduction (S\$) : 21,579.67

Recommended Reserve (S\$) : 14,500.00 (Lump Sum)

Estimated Normal Period of Repairs : 8 working days

CONTRIBUTIONS BY INSURED

Excess (S\$) : N/A

Others :

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at M/s. JEC Auto Service, 1 Kaki Bukit Avenue 6, #02-11, Autobay @ Kaki Bukit, Singapore 417883.
Follow-up inspection has been conducted.

Point of Impact

At the front and rear portion.

Damages

Front : The bumper, bumper inner sponge, support panel, chrome grille, head lamps assembly, etc.
Rear : The boot lid, boot lid chrome garnish, boot lid lock, bumper, bumper reinforcement, bumper inner sponge, end panel, tail lamps assembly, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$18,805.34

Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$14,500.00


Pre-Accident Market Value : About RM130,000.00

We leave the decision of settlement to your good selves.

Assuring you of our best services always.

Very truly yours

PRIORITY SERVICES


JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : JQB 737 Lexus ES250 (A)

TP-0153/01/19

Workshop : JEC Auto Service

Description	Condition	Repairer's Estimate (S\$)	Dist %	Our Recommendation (S\$)	Dist %
To Supply :					
1 pc boot lid ✓	Dented	1,238.88		✓ 998.82	10
1 pc boot lid chrome moulding ✓	Cracked	385.85		151 325.12	10
1 pc boot lid centre emblem ✓	Necessary	66.88		✓ 66.88	10
1 pc boot lid 'Lexus' emblem ✓	Necessary	67.53		✓ 67.53	10
1 pc boot lid 'ES250' emblem ✓	Necessary	69.34		✓ 69.34	10
1 pc boot lid RH number plate lamp assy X SVC	Cracked	266.49		X 213.44	10
1 pc boot lid LH number plate lamp assy X SVC	Cracked	266.49		X 213.44	10
1 pc boot lid reverse camera SVC	Refit	1,261.26		0.00	10
1 pc boot lid lock ✓	Bent	367.86		✓ 367.86	10
1 pc boot lid lock catch X SVC	Bent	48.55		X 48.55	10
1 pc boot lid weatherstrip ✓	Bent	342.42		✓ 207.42	10
1 pc boot lid RH lamp assy X SVC	Cracked	763.74		X 643.77	10
1 pc boot lid LH lamp assy X SVC	Cracked	763.74		X 643.77	10
1 pc boot lid RH hinge X SVC	Bent / Repair	201.00		0.00	10
1 pc boot lid LH hinge X SVC	Bent / Repair	201.00		0.00	10
1 pc rear bumper ✓	Dented	1,376.38		✓ 706.28	10
1 set rear bumper clips ✓	Necessary	100.00		30 45.00	10
1 pc rear bumper RH side retainer ✓	Cracked	87.10		✓ 87.10	10
1 pc rear bumper LH side retainer ✓	Cracked	87.10		✓ 87.10	10
1 pc rear bumper RH side reflector X SVC	Cracked	58.03		X 58.03	10
1 pc rear bumper LH side reflector X SVC	Cracked	58.03		X 58.03	10
1 pc rear bumper RH side reverse sensor X SVC	Dented / Malfunctioned	526.78		X 456.94	10
1 pc rear bumper RH centre reverse sensor X SVC	Dented / Malfunctioned	526.78		X 456.94	10
1 pc rear bumper LH centre reverse sensor ✓	Dented / Malfunctioned	526.78		313 456.94	10
1 pc rear bumper LH side reverse sensor SVC	Refit	526.78		0.00	10
1 pc rear bumper reverse sensor wire harness SVC	Refit	1,136.60		0.00	10
1 pc rear sensor X SVC	Cracked	381.20		X 185.50	10
1 pc rear bumper inner sponge X SVC	Cracked	107.01		X 107.01	10
1 pc rear bumper reinforcement X SVC	Dented	519.42		X 519.42	10
1 pc RH tail lamp assy ✓	Cracked	810.57		654.1 810.57	10
1 pc RH tail lamp lower bracket X SVC	Cracked	105.78		X 105.78	10
1 pc RH tail lamp panel SVC	Dented / Repair	320.00		0.00	10
1 pc LH tail lamp assy X SVC	Cracked	810.57		X 810.57	10
1 pc LH tail lamp lower bracket X SVC	Cracked	105.78		X 105.78	10

Vehicle No : JQB 737 Lexus ES250 (A)

TP-0153/01/19

Workshop : JEC Auto Service

1 pc LH tail lamp panel SVC	Dented / Repair	320.00		0.00	10
1 pc end panel X repair	Dented	844.78	X	604.74	10
1 pc end panel inner garnish ✓	Deformed	394.38	248.1	330.38	10
1 pc spare tyre top board X SVC	Cracked	552.44	X	552.44	10
1 pc spare tyre RH sponge tool board X SVC	Cracked	145.99	X	145.99	10
1 pc spare tyre LH sponge tool board X SVC	Cracked	145.99	X	145.99	10
1 pc front bumper ✓	Dented / Cracked	1,001.84	✓	861.92	10
1 set front bumper clips ✓	Necessary	100.00	30	45.00	10
1 pc front bumper inner sponge X SVC	Cracked	146.70	X	146.70	10
1 pc front bumper centre grille X SVC	Cracked	204.84	X	204.84	10
1 pc front bumper RH fog lamp bracket X SVC	Cracked	127.78	X	127.78	10
1 pc front bumper LH fog lamp bracket X SVC	Cracked	127.78	X	127.78	10
1 pc front bumper number plate holder X SVC	Dented	111.91	X	111.91	10
1 pc front chrome grille ✓	Cracked	651.31	✓	281.87	10
1 pc front chrome grille emblem ✓	Broken / Dislodged / Missing	345.70	✓	78.50	10
1 pc RH head lamp assy X SVC	Cracked	3,448.06	X	2,588.77	10
1 pc LH head lamp assy X SVC	Cracked	3,448.06	X	2,588.77	10
1 pc support panel top garnish X SVC	Cracked	267.39	X	267.39	10
1 pc air con condenser SVC	Not Necessary	1,553.00		0.00	10
1 pc radiator assy SVC	Not Necessary	1,840.00		0.00	10
Sub-Total :		30,259.67		18,133.70	
Total Discount :		0.00		1,813.36	
		30,259.67		16,320.34	
				5306.2	
Special Nett :				-10%: 4775.58	
1 pc front number plate ✓	Cracked	180.00		35.00	
1 pc rear number plate	Refit	180.00		0.00	
Sub-Total :		360.00		35.00	
Total Discount :		0.00		0.00	
		360.00		35.00	
Total For Parts :		30,619.67		16,355.34	
Labour Charges :					
Labour charges on affected areas.		2,300.00	700	1,000.00	
Remove and refix air con condenser and pipes.		200.00		0.00	

Vehicle No : JQB 737 Lexus ES250 (A)

TP-0153/01/19

Workshop : JEC Auto Service

Remove and refix radiator, fan assy and pipes.		200.00		0.00	
Remove and replace rear inner trims and boards.		400.00		60 150.00	
Remove, replace and refix rear bumper reverse sensors and wire harness.		180.00		✓ 40.00	
Apply rust protection on affected areas.		180.00		✗ 60.00	
Spray Painting Charges :					
Putty and respray affected areas.		2,000.00		800 1,200.00	
Grand Total :		36,079.67		18,805.34	

Surveyor : LAWRENCE NG

6410.58

-20%: 5100

6 days