

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20006584/QBS3Q2

Date: 14/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SGV1627L	Insured Vehicle No :	SHA3402D
Date of Loss: 20/06/2020	Nature of Claim: TP	Claim No: MCT20060232

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV1627L		
Make & Model:	MAZDA 5 SP, 2.0 (A)	Engine No:	LF10275513
Reg. Date:	06/06/2007 (Man. Year: 2007)	Chassis No:	JM6CR10F170105110
Colour:	White	Odometer:	187600 km
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Arivo 6 mm	Rear Left Side:	Arivo 6 mm
Front Right Side:	Arivo 6 mm	Rear Right Side:	Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,697.80	1,739.76	8,958.04	83.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,620.00	1,780.00	2,840.00	61.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,317.80	3,519.76	11,798.04	77.02
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	15,317.80	2,800.00	12,517.80	81.72
+ GST 7.00/7.00% (\$\$)	1,072.25	196.00	876.25	81.72
Nett Amount (\$\$)	16,390.05	2,996.00	13,394.05	81.72
+ Car Rental (6.0 x S\$120.00/day) (\$\$)		720.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		3,752.45		
Global Sum Settlement (\$\$)		3,750.00		

INSPECTION

Date of Assignment:	23/06/2020	
Date Inspected:	24/06/2020	Inspected At:
		Vermogen Ace Pte Ltd (HQ)
		60 Jalan Lam Huat
		Singapore 737869
Estimated Period of Repair:	4.0 days	

Adjuster: OI SUN PIN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2020)
Parts:	M1-MPV	MAZDA 5 SP 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGV1627L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE WINDSCREEN MLDG	Serviceable	127.00 F	*- FL
2	1		*TAILGATE	Repair	3,197.30 F	*- FL
3	1		*TAILGATE INNER TRIM	Serviceable	161.20 F	*- FL
4	1		*SET TAILGATE INNER TRIM CLIPS	Serviceable	20.00 F	*- FL
5	1		*TAILGATE LOCK	Serviceable	356.80 F	*- FL
6	2		*TAILGATE DAMPER LH/RH	Serviceable	373.20 F	*- FL
7	1		*TAILGATE EMBLEM MAZDA 5	Necessary	70.00 F	*70.00 FL
8	1		*TAILGATE LOGO	Necessary	71.90 F	*71.90 FL
9	1		*TAIL LAMP LH	Serviceable	746.30 F	*- FL
10	1		*REAR BUMPER	Crumpled	944.30 F	*944.30 FL
11	1		*REAR BUMPER RETAINER LH	Broken	32.50 F	*32.50 FL
12	1		*SET REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
13	1		*REAR BUMPER SIDE GARNISH LH	Missing	127.50 F	*127.50 FL
14	1		*REAR BUMPER REFLECTOR LH	Missing	53.00 F	*53.00 FL
15	1		*REAR END PANEL OUTER	Dented	510.70 F	*410.00 FL
16	1		*REAR END PANEL INNER (NPA)	Serviceable	0.00 F	*- FL
17	1		*REAR END TOP GARNISH	Serviceable	122.10 F	*- FL
18	1		*SET REAR END TOP GARNISH CLIPS	Serviceable	20.00 F	*- FL
19	1		*REAR FENDER LH	Repair	1,627.50 F	*- FL
20	1		*REAR FENDER LOWER INNER TRIM LH	Serviceable	547.20 F	*- FL
21	1		*SET REAR FENDER LOWER INNER TRIM CLIPS	Serviceable	30.00 F	*- FL
22	1		*REAR FENDER MUDGUARD LH	Deformed	35.50 F	*35.50 FL
23	1		*REAR FENDER INNER SHIELD LH	Serviceable	37.40 F	*- FL
24	1		*SET REAR FENDER INNER SHIELD CLIPS	Serviceable	20.00 F	*- FL
25	1		*EXHAUST PIPE (END CHROME PIPE)	Dented	1,194.00 F	*150.00 FL
26	1		*EXHAUST MOUNTING	Serviceable	42.40 F	*- FL
27	1		*REAR END PANEL SEALANT (NPA)	Serviceable	0.00 F	*- FL
28	1		*REAR FENDER SEALANT (NPA)	Serviceable	0.00 F	*- FL
29	1		*SUNDRIES (NPA)	Serviceable	0.00 F	*- FL
30	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
31	1		*REAR NUMBER PLATE (NPA)	Serviceable	0.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,697.80	2,124.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	384.94
Total Parts (\$\$)	10,697.80	1,739.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA .REAR PORTION TAILGATE ,REAR BUMPER ,REAR BUMPER SIDE GARNISH LH ,REAR END PANEL,REAR FENDER LH ,REAR FENDER UPPER COVER LH	New	2,000.00	800.00
2	TO PUTTY ,RESPRAY PAINTING AND POLISH ACCIDENT AREA .REAR PORTION ,TAILGATE ,REAR BUMPER ,REAR BUMPER SIDE GARNISH LH ,REAR END PANEL,REAR FENDER LH ,REAR FENDER UPPER COVER LH	New	1,800.00	800.00
3	TO RUST PROOF AFFECTED AREAS	New	100.00	30.00
4	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	100.00	30.00
5	TO REMOVE AND REFIT REAR FENDER GLASS LH	New	150.00	0.00
6	TO REMOVE AND REFIT INTERIOR PARTS UPHOLSTERY TO GIVE WAY THE REPAIR	New	200.00	30.00
7	TO REMOVE AND REFIT REVERSE SENSOR	New	120.00	30.00
8	TO REMOVE AND REFIT EXHAUST PIPE	New	150.00	60.00
Gross Labour Cost (\$\$)			4,620.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >