

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20006592/KRS3Q2
Date: 20/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900251084
Claimant Vehicle No :	SHB9797U	Insured Vehicle No :	GBG9891A
Date of Loss:	22/06/2020	Nature of Claim:	TP
		Claim No:	9470823429SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9797U		
Make & Model:	TOYOTA ALPHARD, 2.4 (A)	Engine No:	2AR2221153
Reg. Date:	17/12/2019 (Man. Year: 2019)	Chassis No:	AYH300090004
Colour:	Metallic Pearl White	Odometer:	66020 km
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Goodyear 3 mm	Rear Left Side:	Goodyear 3 mm
Front Right Side:	Goodyear 3 mm	Rear Right Side:	Goodyear 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,058.52	5,609.83	6,448.69	53.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,350.00	1,760.00	6,590.00	78.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,408.52	7,369.83	13,038.69	63.89
+ GST 7.00/7.00% (S\$)	1,428.60	515.89	912.71	63.89

Nett Amount (S\$)	21,837.12	7,885.72	13,951.40	63.89
		+ Car Rental (9.0 x S\$81.13/day) (S\$)	730.17	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	8,623.34	

INSPECTION

Date of Assignment: 23/06/2020

Date Inspected: 23/06/2020

Estimated Period of Repair: 6.0 days

Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	2,078.20 FL	*1,780.57 FL
2	1		*BUMPER REAR COVER	Serviceable	290.30 FL	*- FL
3	1		*REAR END PANEL	Bent	781.70 FL	*781.70 FL
4	1		*TAILGATE	Bent	2,040.50 FL	*1,956.20 FL
5	1		*SUPPORT ,REAR BUMPER SIDE ,RH	Serviceable	240.00 FL	*- FL
6	1		*SUPPORT ,REAR BUMPER SIDE ,LH	Serviceable	240.00 FL	*- FL
7	1		*LAMP ASSY ,RR	Serviceable	932.90 FL	*- FL
8	1		*LOCK ASSY ,BACK DOOR	Dented	800.20 FL	*742.00 FL
9	1		*BOARD ASSY ,BACK DOOR TRIM	Dented	734.50 FL	*734.50 FL
10	1		*SET PARKING AID	Dented / Shorted	4,000.00 FS	*800.00 FS
11	2		*PARKING AID ,SENSOR ULTRASONIC	Serviceable	785.60 FS	*- FS
12	2		*PARKING AID ,SENSOR ULTRASONIC	Serviceable	785.60 FS	*- FS
13	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*80.00 FS
14	1		*SET REAR RH SIDE BUMPER SUPPORT CLIP	Not Necessary	35.00 FS	*- FS
15	1		*SET REAR LH SIDE BUMPER SUPPORT CLIP	Not Necessary	35.00 FS	*- FS
16	1		*PLATE ,BACK DOOR -ALPHARD	Necessary	52.00 FS	*52.00 FS
17	1		*PLATE ,BACK DOOR -E-FOUR	Necessary	41.00 FS	*41.00 FS
18	1		*EMBLEM SUB-ASSY	Necessary	72.40 FS	*72.40 FS
19	1		*PLATE ,BACK DOOR -TOYOTA LOGO	Necessary	68.20 FS	*68.20 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,093.10	7,108.57
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,034.58	1,498.74
Total Parts (\$\$)	12,058.52	5,609.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	60.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	80.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	700.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	660.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
9	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
11	TO CHECK ELELCTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
Gross Labour Cost (S\$)			8,350.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >