

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006595/KEA3Q2

Date: 01/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100420100-05

Claimant
Vehicle No : SMF893D **Insured Vehicle No :** SCU1546P

Date of Loss: 14/06/2020 Nature of Claim: TP Claim No: 1190460974SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF893D	Engine No:	2NR5285766
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3501153269
Reg. Date:	26/10/2018 (Man. Year: 2018)	Odometer:	34869 km
Colour:	Metallic Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	410.85	410.85	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	750.00	250.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,410.85	1,160.85	250.00	17.72
+ GST 7.00/7.00% (\$\$)	98.76	81.26	17.50	17.72
Nett Amount (\$\$)	1,509.61	1,242.11	267.50	17.72
+ Loss of Use (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		8.00		
Nett Liability (\$\$)		1,550.11		

INSPECTION

Date of Assignment: 23/06/2020

Date Inspected: 03/07/2020 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Distorted	423.10 FL	*423.10 FL
2	1		*FRONT BUMPER RH FOG LAMP GARNISH	Cut	103.70 FL	*103.70 FL
3	6		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	547.80	547.80
- List Item Discount on L Items 25.00/25.00% (S\$)	136.95	136.95
Total Parts (S\$)	410.85	410.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT BUMPER ASSY ,GRILLE ,FOG LAMPS ,CENTRE LOWER GRILLE ,KNOCK & REPAIR FRT RH FENDER & REALIGN THE SAME	New	500.00	350.00
2	PUTTY & RESPRAY ON FRT RH FENDER ,FRT BUMPER	New	500.00	400.00
Gross Labour Cost (\$\$)			1,000.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >