Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006596/UEA3Q2

Date: 26/11/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700055510 Claimant Insured Vehicle No: SKH920Y GBH7002H

Vehicle No:

Date of Loss: 19/06/2020 Nature of Claim: TP Claim No: 1242590517SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**GBH7002H** Reg No:

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2814724

Reg. Date: 05/09/2018 (Man. Year: 2018) Chassis No: JTFAT35Y30K211183

Colour: Odometer: 37680 km Silver

**Engine Capacity:** 2982 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: No Pre-accident Condition: Handbrake (Serviceable):

**CONDITION OF TYRES** 

Front Tyre Size: 195/75R15 Rear Tyre Size: 155R12 (D)

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm Bridgestone 6/6 mm Front Right Side: Bridgestone 6 mm Rear Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,970.52	2,854.35	4,116.17	59.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	1,570.00	3,080.00	66.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,620.52	4,424.35	7,196.17	61.93
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	11,620.52	3,500.00	8,120.52	69.88
+ GST 7.00/7.00% (S\$)	813.44	245.00	568.44	69.88
Nett Amount (S\$)	12,433.96	3,745.00	8,688.96	69.88
+ Loss of Use (4.0 x S\$10	00.00/day) (S\$)	400.00		
Ne	tt Liability (S\$)	4,145.00		

**INSPECTION** 

23/06/2020 Date of Assignment:

Date Inspected: 24/06/2020 Inspected At: **AUTOMOBILE INTEGRATED** 

MANAGEMENT PTE LTD (AIM) 23 KAKI BUKIT AVE 5 #04-01

(SOUTH WING) SINGAPORE 415933

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*TAILGATE	Repair	1,265.50 FL	*- FL	
2	1		*TAILGATE STICKER TOYOTA	Necessary	181.90 FL	*181.90 FL	
3	1		*TAILGATE STICKER DYNA	Necessary	48.60 FL	*48.60 FL	
4	1		*TAILGATE LOWER MEMBER	Bent	491.60 FL	*491.60 FL	
5	2		*TAILGATE STOPPER RUBBERS	Serviceable	85.20 FL	*- FL	
6	1		*TAILLAMPS-L/R	O/s Cracked	583.00 FL	*291.50 FL	
7	1		*TAILLAMP PANELS-L/R	O/s Bent	383.20 FL	*191.60 FL	
8	1		*REAR SIDEGATE-RH	Repair	1,865.50 FL	*- FL	
9	1		*REAR SIDEGATE LOCK HINGES-L/R	O/s Bent	363.20 FL	*181.60 FL	
10	1		*REAR SIDEGATE LOCK HINGE BRACKETS	O/s Bent	252.20 FL	*126.60 FL	
11	1		*REAR EXHAUST PIPE	Dented/Bent	716.90 FL	*716.90 FL	
12	2		*REAR EXHAUST MOUNTINGS	Not Necessary	57.20 FL	*- FL	
13	1		*REAR SPARE WHEEL CARRIER	Not Necessary	421.60 FL	*- FL	
14	1		*REAR LICENCE LAMP	Not Necessary	89.60 FL	*- FL	
15	1		*REAR LICENCE PLATE PANEL	Bent	195.50 FL	*195.50 FL	
16	1		*REAR STICKER 6 PAX	Necessary	10.00 FS	*10.00 FS	
17	1		*REAR STICKER 70KM/H	Necessary	10.00 FS	*10.00 FS	
18	1		*REAR NO PLATE	Bent	40.00 FS	*15.00 FS	
19	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS	
20	1		*REAR UNDERDRUM ASSY	Distorted	1,200.00 FS	*800.00 FS	
21	1		*SET REAR CANOPY BOLT	Not Necessary	180.00 FS	*- FS	
F=Fra	anchise	part. S=Spcl	Nett. L=ListItemDisc.				
				Sub Total (S\$)	8,720.70	3,460.80	
	- List Item Discount on L Items 25.00/25.00% (S\$)				1,750.18	606.45	
				Total Parts (S\$)	6,970.52	2,854.35	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE, REFIX REAR EXHAUST SYSTEMS	New	120.00	60.00
3	TO REMOVE,REFIX REAR REVERSE SENSOR	New	80.00	40.00
4	REMOVE & REINSTALL REAR CANOPY TO ASSIST REPAIR	New	650.00	0.00
5	TO STRAIGHTEN,REPAIR & REALIGN REAR CHASSIS FRAME MEMBER	New	1,200.00	0.00
6	TO RESPRAY UNDERCOATING	New	150.00	50.00
7	TO RESPRAY PAINTING AND ETC	New	1,200.00	600.00
8	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	1,200.00	800.00
	Gross Labour Cost (S\$)		4,650.00	1,570.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.