

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006597/GPA3Q2
Date: 16/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800102012	
Claimant Vehicle No :	SMD7645T	Insured Vehicle No :	SMD5585X	
Date of Loss:	20/06/2020	Nature of Claim:	TP	Claim No: 7730469978SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD7645T		
Make & Model:	MASERATI GRANTURISMO, 4.7 Cambiocorsa (A)	Engine No:	M145146687
Reg. Date:	24/03/2009 (Man. Year: 2009)	Chassis No:	ZAMHH45C000046765
Colour:	White	Odometer:	82714 km
Engine Capacity:	4691 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	285/35Z R20	Rear Tyre Size:	285/35Z R20
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,603.29	13,351.73	9,251.56	40.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,470.00	1,310.00	47.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,383.29	14,821.73	10,561.56	41.61
Approved Total (Overridden) (S\$)		11,700.00		

(S\$)	25,383.29	11,700.00	13,683.29	53.91
+ GST 7.00/7.00% (S\$)	1,776.83	819.00	957.83	53.91
Nett Amount (S\$)	27,160.12	12,519.00	14,641.12	53.91
+ Loss of Use (7.0 x S\$180.00/day) (S\$)		1,260.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		13,815.45		
Global Sum Settlement (S\$)		13,800.00		

INSPECTION

Date of Assignment: 22/06/2020

Date Inspected: 23/06/2020

Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
 Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	4,650.25 F	*4,650.25 FL
2	2		*REAR BUMPER BRACKET	Not Necessary	98.34 F	*- FL
3	1		*REAR BUMPER TOP GARNISH	Broken	285.50 F	*285.50 FL
4	1		*REAR REINFORCEMENT	Not Necessary	1,280.00 F	*- FL
5	1		*REAR BOOT	Cracked	6,750.15 F	*6,202.68 FL
6	1		*REAR BOOT WEATHERSTRIP	Twisted	175.85 F	*175.85 FL
7	1		*LHS REAR BOOT INNER TAILLAMP	Not Necessary	450.00 F	*- FL
8	1		*RHS REAR BOOT INNER TAILLAMP	Not Necessary	450.00 F	*- FL
9	1		*REAR BOOT LOGO	Necessary	93.20 F	*93.20 FL
10	1		*END PANEL	Repair	1,035.00 F	*- FL
11	1		*END PANEL TOP GARNISH (NPA)	Not Necessary	0.00 F	*- FL
12	1		*RHS EXHAUST MUFFLER	Bent	4,050.00 F	*3,000.00 FL
13	10		*REAR BUMPER CLIP	Necessary	250.00 FS	*20.00 FS
14	1		*REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
15	1		*REAR BOOT SPOILER	Not Necessary	2,500.00 FS	*- FS
16	1		*REAR BOOT STICKER	Necessary	150.00 FS	*150.00 FS
17	1		*REAR NO PLATE	Necessary	35.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,603.29	14,792.48
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,440.75
Total Parts (\$\$)	22,603.29	13,351.73

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE ,REPLACE ,CUT ,WELD KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS	New	1,200.00	600.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT	New	1,000.00	800.00
3	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	80.00	30.00
4	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	0.00
5	RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	80.00	0.00
6	TO SUPPLY UNDER COATING /PUTTY ON PARTS REPLACED	New	60.00	0.00
7	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	150.00	0.00
8	TO REMOVE & REFIT REAR BUMPER SENSOR	New	60.00	40.00
9	TO REMOVE AND REPLACE WINDSCREEN	New	100.00	0.00
Gross Labour Cost (\$\$)			2,780.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >