

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006616/QES3Q2

Date: 07/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700078343

Claimant
Vehicle No : SLE9223X **Insured Vehicle No :** SLU1145G

Date of Loss: 22/06/2020 Nature of Claim: TP Claim No: 2594102161SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE9223X		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Engine No:	L15B3533219
Reg. Date:	05/08/2016 (Man. Year: 2015)	Chassis No:	GK81002667
Colour:	Black	Odometer:	336766 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,515.76	2,404.16	1,111.60	31.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,120.00	1,020.00	47.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,655.76	3,524.16	2,131.60	37.69
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	5,655.76	2,800.00	2,855.76	50.49
+ GST 7.00/7.00% (S\$)	395.90	196.00	199.90	50.49
Nett Amount (S\$)	6,051.66	2,996.00	3,055.66	50.49
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,238.00		

INSPECTION

Date of Assignment: 24/06/2020

Date Inspected: 24/06/2020 Inspected At:

Lion City Rentals Pte Ltd (HQ)
60 Jalan Lam Huat, #04-35/36 Carros
Centre
Singapore 737569

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,850.00 FL	*1,193.00 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*120.00 FL
3	1		*REAR TAILGATE WEATHERSTRIP	Cut	255.00 FL	*255.00 FL
4	1		*REAR TAILGATE HONDA EMBLEM	Necessary	81.30 FL	*81.30 FL
5	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	88.40 FL	*88.40 FL
6	1		*REAR BUMPER	Crumpled	1,350.00 FL	*980.00 FL
7	1		*SET REVERSE SENSOR	Shorted	260.00 FS	*200.00 FS
8	1		*SET BUMPER CLIPS	Necessary	120.00 FS	*30.00 FS
9	1		*SET END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,279.70	2,947.70
- List Item Discount on L Items 20.00/20.00% (\$)	763.94	543.54
Total Parts (\$)	3,515.76	2,404.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE REAR TAILGATE ,REAR BUMPER ,END PANEL OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS AND ALSO STRAIGHTEN SPARE TYRE PANEL INCLUDE CUTTING/WELDING OF DAMAGED PARTS	New	900.00	500.00
2	TO RESPRAY REAR BUMPER ,END PANEL,SPARE TYRE PANEL AND TAILGATE	New	900.00	400.00
3	TO REMOVE & INSTALL REAR WINDSCREEN	New	160.00	120.00
4	TO APPLY RUSTPROOFING /TUFFCOATING TREATMENT TO REPLACED PARTS	New	80.00	40.00
5	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
Gross Labour Cost (\$\$)			2,140.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >