



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. FD 8811G

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
1	SET SIDE MIRROR	CUT	55.00
1	HANDLE BAR	BENT	95.00
1	BRAKE LEVER LH	CUT	38.00
1	BAR END LH	MISSING	28.00
1	HANDLE GRIP	TORN	45.00
1	FULL SET FAIRING	CUT	480.00
1	REAR PILLIOM FOOTREST LH	CUT	58.00
1	AIR BOX COVER	CUT	58.00
1	CVT COVER	CUT	80.00
1	MAIN STAND	CUT	85.00
1	FRONT FORK (COMPLETE)	BENT	580.00
1	SIDE COVER PANEL LH	CUT	58.00
1	SIDE COVER LH	CUT	65.00
1	FOOTBOARD LH	CUT	65.00
			1,790.00
	<b><u>LABOUR</u></b>		
	LABOUR CHARGE.		480.00
	TOWING.		60.00
			540.00
	<b>GRAND TOTAL</b>		<b>2,330.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>	<b>2,330.00</b>
------------------------------------	-----------------

Report Ref No. CS3/LAW20006629/Etf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.