



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. FD 8811G

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	FRONT WING MIRROR	BROKEN	110.00
1	STEERING CONE	NECESSARY	90.00
1	HANDLE BAR	BENT	20.00
1	HANDLE BAR GRIP	TORN	30.00
1	HANDLE BAR BALANCER LH	MISSING	60.00
1	HAND BRAKE LEVER (LH)	CUT	40.00
1	SIDE FAIRING (LH)	CUT	180.00
1	CENTER FAIRING (FRONT)	CUT	140.00
1	FAIRING LOWER (LH)	CUT	200.00
1	SIDE STAND	CUT	150.00
1	MAIN STAND	CUT	240.00
1	REAR FOOT REST (LH)	CUT	70.00
1	STICKER	NECESSARY	200.00
1	AIR FILTER PROTECTOR COVER	CUT	185.00
1	ENGINE PROTECTOR COVER	CUT	250.00
	LESS 10% DISCOUNT		-196.50
			1,768.50
	<u>LABOUR</u>		
	LABOUR.		300.00
	PAINT.		300.00
			600.00
	GRAND TOTAL		2,368.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	1,900.00
---	-----------------

Report Ref No. CS3/LAW20006629/Etf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.