



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

YEO PERUMAL MOHIDEEN LAW CORPORATION
1 COLEMAN STREET
#05-10 THE ADELPHISINGAPORE 179803

Ref: CS3/LAW20006629/Etf3e2

Date: 20-07-2020



Code: L109

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	FBN 4297L	Veh. Inspected	FD 8811G
Policy No.		Coverage (\$)	0.00
Claim No.	PA.8507.20.KR.	Excess (\$)	0.00
Assign From	SUBRAMANIAN DIVYASHNI	Assign Date	24/06/2020

2. Vehicle Particulars & Condition

Make & Model	YAMAHA AEROX	c.c	155
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3SG4640KJ049009	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/70-14	PIRELLI	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70-14	PIRELLI	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/05/2020	Inspect Date / Time	25/06/2020 (12:35 PM)
Survey held at	FUEL GARAGE-1 KAKI BUKIT RD1 #01-11		
Repairer	-		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------