

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20006630/AGS3Q2

Date: 14/08/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00005068-01

Claimant
Vehicle No : GV2993Y **Insured Vehicle No :** SJD2894J

Date of Loss: 23/06/2020 Nature of Claim: TP Claim No: 1202000018657

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GV2993Y		
Make & Model:	NISSAN CABSTAR, 2.0 (M)	Engine No:	QD32154771
Reg. Date:	21/03/2002 (Man. Year: 2001)	Chassis No:	JN1SF4F23Z0844420
Colour:	Silver	Odometer:	408004 km
Engine Capacity:	3153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,066.30	2,684.03	2,382.27	47.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,190.00	1,310.00	52.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,566.30	3,874.03	3,692.27	48.80
Approved Total (Overridden) (\$\$)		3,000.00		
Nett Amount (\$\$)	7,566.30	3,000.00	4,566.30	60.35
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		3,362.00		
Global Sum Settlement (\$\$)		3,350.00		

INSPECTION

Date of Assignment: 24/06/2020

Date Inspected: 25/06/2020 Inspected At:

Sm Automotive - Kaki Bukit (HQ)
BLOCK C - 1, KAKI BUKIT AVE 6,
#01-43
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Jul 2020)	
Parts:	N/A	NISSAN CABSTAR 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GV2993Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,399.70 F	*1,399.70 FL
2	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*10.00 FS
3	1		*REAR TAILGATE 13 PAX STICKER	Necessary	65.00 FS	*10.00 FS
4	2		*REAR TAILGATE LOWER SIDE LOCK	Not Necessary	96.40 F	*- FL
5	1		*REAR TAILGATE LOWER HINGE (CENTRE)	Centre Bent	450.90 F	*150.30 FL
6	2		*REAR TAILGATE LOWER SIDE BRACKET	Not Necessary	271.00 F	*- FL
7	2		*REAR TAILGATE LOWER SIDE BRACKET STOPPER RUBBER	Not Necessary	51.60 F	*- FL
8	1		*REAR TAILGATE LOWER MEMBER	Dented	418.80 F	*418.80 FL
9	1		*REAR TAILGATE ALUMINIUM PANEL	Not Necessary	580.00 F	*- FL
10	2		*REAR TAIL LAMP	Cracked	497.20 F	*497.20 FL
11	2		*REAR TAIL LAMP BRACKET	Bent	222.40 F	*222.40 FL
12	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
13	2		*REAR REVERSE SENSOR	Not Necessary	700.00 F	*- FL
14	1		*REAR SPARE TYRE LOCK	Damaged	238.30 F	*238.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,066.30	2,976.70
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	292.67
Total Parts (\$\$)	5,066.30	2,684.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT REAR REVERSE SENSOR	New	100.00	0.00
2	TO CHECK WIRING	New	50.00	30.00
3	TUFF KOTE	New	150.00	60.00
4	PANEL BEATING	New	1,200.00	600.00
5	SPRAY PAINTING	New	1,000.00	500.00
Gross Labour Cost (\$\$)			2,500.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >