



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2006396
INV Date 16/09/2020
Reference CC3/CTI20006636/Kds3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHD 678D
Insured Veh. SKU 6050A
Claim No. SNM20D202192
Policy No. DMPCSN3054631904
Accident Date 18/06/2020
Inspection Date 22/06/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI20006636/Kds3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 16-09-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKU 6050A	Veh. Inspected	SHD 678D
Policy No.	DMPCSN3054631904	Coverage (\$)	0.00
Claim No.	SNM20D202192	Excess (\$)	0.00
Assign From		Assign Date	22/06/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES E220 (A)	c.c	2143
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2120012B221528	Colour	WHITE
Odometer	604743	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 ZR16	GITI	9 mm
L/H Front Tyre	225/55 ZR16	GITI	9 mm
R/H Rear Tyre	225/55 ZR16	GITI	8 mm
L/H Rear Tyre	225/55 ZR16	GITI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/06/2020	Inspection Date	22/06/2020
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 678D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED / DENTED	3,105.00	1,510.00
1	REAR BUMPER LOWER	SERVICEABLE	1,080.00	-
1	REAR BUMPER CENTRE PAD	SERVICEABLE	307.83	-
1	REAR BUMPER SIDE PAD	SERVICEABLE	186.33	-
1	REAR BUMPER TOW HOOD COVER	SERVICEABLE	63.00	-
1	REAR LH BUMPER BRACKET	SERVICEABLE	66.50	-
1	REAR RH BUMPER BRACKET	SERVICEABLE	66.50	-
1	REAR BUMPER INNER FRAME	SERVICEABLE	297.00	-
1	REAR BUMPER BOTTOM BRACKET LH	TO REPAIR SEE LABOUR	68.80	-
1	REAR BUMPER BOTTOM BRACKET RH	TO REPAIR SEE LABOUR	68.80	-
1	REAR BUMPER TOP BRACKET	SERVICEABLE	129.00	-
1	REAR BUMPER INNER BRACKET LH	TO REPAIR SEE LABOUR	198.00	-
1	REAR BUMPER INNER BRACKET RH	TO REPAIR SEE LABOUR	198.00	-
1	REAR BUMPER BEAM	TO REPAIR SEE LABOUR	1,215.00	-
1	REAR BUMPER BEAM BRACKET LH	TO REPAIR SEE LABOUR	307.50	-
1	REAR BUMPER BEAM BRACKET RH	TO REPAIR SEE LABOUR	307.50	-
1	REAR BUMPER BRACKET CENTRE	SERVICEABLE	461.75	-
1	REAR BUMPER MOUNTING SUPPORT BRACKET	SERVICEABLE	480.50	-
1	REAR BUMPER RETAINER BRACKET GUIDE RAIL LH	SERVICEABLE	202.50	-
1	REAR BUMPER RETAINER BRACKET GUIDE RAIL RH	SERVICEABLE	202.50	-
1	REAR BUMPER MOULDING	SERVICEABLE	205.70	-
1	BOOTLID	TO REPAIR SEE LABOUR	4,140.00	-
1	BOOTLID "E220" BADGE	NOT NECESSARY	153.00	-
1	BOOTLID "CLUETEC" BADGE	NOT NECESSARY	153.00	-
1	BOOTLID CENTRE LOGO BADGE	NOT NECESSARY	153.00	-

Report Ref No. CC3/CTI20006636/Kds3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID PROTECTOR GARNISH WITH CHROME	SERVICEABLE	732.00	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	360.00	-
1	BOOTLID LOCK-TOP	SERVICEABLE	300.00	-
1	BOOTLID LOCK-BOTTOM	SERVICEABLE	216.00	-
1	BOOTLID LOCK ACTUATOR	SERVICEABLE	420.00	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	240.00	-
1	BOOTLID MOTOR DRIVE UNIT COVER	SERVICEABLE	210.00	-
1	BOOT HINGE CABLE DUCT COVER RH	SERVICEABLE	185.60	-
1	BOOT HINGE CABLE DUCT COVER LH	SERVICEABLE	185.60	-
1	BOOTLID HANDLE TRIM MOULDING	SERVICEABLE	340.00	-
1	BOOTLID INTERIOR TRIM LAMP	SERVICEABLE	145.00	-
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	1,971.00	-
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	324.00	-
1	REAR END PANEL INNER TRIM	SERVICEABLE	630.00	-
1	REAR END PANEL INNER TRIM FLAP	SERVICEABLE	360.00	-
1	REAR LAMP RH	SERVICEABLE	1,170.00	-
1	REAR LAMP PANEL OUTER RH	TO REPAIR SEE LABOUR	382.95	-
1	REAR LAMP LH	SERVICEABLE	1,170.00	-
1	REAR LAMP PANEL OUTER LH	TO REPAIR SEE LABOUR	382.95	-
1	REAR LH TRUNK LID LAMP	SERVICEABLE	1,190.00	-
1	REAR RH TRUNK LID LAMP	SERVICEABLE	1,190.00	-
	LESS 10% DISCOUNT		-2,592.18	-151.00
			23,329.63	1,359.00
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER PARKING SENSOR (SN)	SERVICEABLE	1,200.00	-
1	SET BOOTLID INNER TRIM CLIP (SN)	NOT NECESSARY	90.00	-
1	SET REAR END PANEL INNER TRIM CLIP (SN)	NOT NECESSARY	90.00	-
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	101.54	101.54
1	SET LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	225.00	-
1	TYRE MECHANICAL JACK (SN)	SERVICEABLE	605.48	-

Report Ref No. CC3/CTI20006636/Kds3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TYRE MECHANICAL JACK HOLDER BRACKET (SN)	SERVICEABLE	177.98	-
1	BOOT CHROME MOLDING CLIP (SN)	NOT NECESSARY	55.00	-
1	REAR LAMP CLIP LH (SN)	NOT NECESSARY	45.00	-
1	REAR LAMP CLIP RH (SN)	NOT NECESSARY	45.00	-
1	SET REAR BUMPER LOWER CLIP (SN)	NOT NECESSARY	90.00	-
1	SET REAR BUMPER BRACKET CLIP (SN)	NOT NECESSARY	85.00	-
1	SET REAR BUMPER PROTECTOR (SN)	NECESSARY	120.00	30.00
			2,930.00	131.54
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER BOTTOM BRACKET LH,REAR BUMPER BOTTOM BRACKET RH,REAR BUMPER INNER BRACKET LH,REAR BUMPER INNER BRACKET RH,REAR BUMPER BEAM,REAR BUMPER BEAM BRACKET LH,REAR BUMPER BEAM BRACKET RH,BOOTLID,REAR END PANEL OUTER,REAR END PANEL INNER,REAR LAMP PANEL OUTER RH AND REAR LAMP PANEL OUTER LH.		6,500.00	220.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	120.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,500.00	250.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	270.00	-
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF END PANEL FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO RESEAL SEALANT ON GAP.	NOT NECESSARY	170.00	-
			14,580.00	530.00

Report Ref No. CC3/CTI20006636/Kds3q2



GRAND TOTAL		40,839.63	2,020.54
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CC3/CTI20006636/Kds3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 678D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

