

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TM120006641/KYF3E2  
**Date:** 20/07/2020

#### REFERENCE

|  |                      |                       |
|--|----------------------|-----------------------|
| Handling Insurer: Tokio Marine Insurance Singapore Ltd | Policy No:           | MK001059              |
| Claimant Vehicle No : SHC5127A                         | Insured Vehicle No : | GX1678D               |
| Date of Loss: 23/06/2020                               | Nature of Claim:     | TP Claim No: M2003098 |

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | SHC5127A                          | Engine No:  | M9R8839C000865    |
| Make & Model:               | RENAULT LATITUDE, 2.0 L (A)       | Chassis No: | VF1ABL15AUC276541 |
| Reg. Date:                  | 27/12/2013 (Man. Year: 2013)      | Odometer:   | 310429 km         |
| Colour:                     | Metallic White/Red                |             |                   |
| Engine Capacity:            | 1995 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

#### CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 215/60 R16  | Rear Tyre Size:  | 215/60 R16  |
| Front Left Side:  | Sailun 9 mm | Rear Left Side:  | Sailun 8 mm |
| Front Right Side: | Sailun 9 mm | Rear Right Side: | Sailun 8 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's       | Adjuster's      | Difference       | Diff %       |
|--|------------------|-----------------|------------------|--------------|
| Parts                                    | 19,958.18        | 5,996.98        | 13,961.20        | 69.95        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00             |              |
| Labour                                   | 18,430.00        | 1,520.00        | 16,910.00        | 91.75        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00             |              |
| Towing                                   | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>38,388.18</b> | <b>7,516.98</b> | <b>30,871.20</b> | <b>80.42</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>6,000.00</b> |                  |              |
| <b>(S\$)</b>                             | 38,388.18        | 6,000.00        | 32,388.18        | 84.37        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 2,687.17         | 420.00          | 2,267.17         | 84.37        |
| <b>Nett Amount (S\$)</b>                 | <b>41,075.35</b> | <b>6,420.00</b> | <b>34,655.35</b> | <b>84.37</b> |

#### INSPECTION

|                             |                          |   |
|-----------------------------|--------------------------|---|
| Date of Assignment:         | 25/06/2020               |   |
| Date Inspected:             | 24/06/2020 Inspected At: | Trans Cab Auto Services Pte Ltd - Amk (HQ)<br>No 2 Ang Mo Kio St 63<br>Singapore 569111 |
| Estimated Period of Repair: | 5.0 days                 |   |

---

**Adjuster:** KENNETH KONG

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|  |  |
|--|--|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 19 Jul 2020)  |
| <b>Parts:</b> 143  | RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SHC5127A) |  |
| <b>Validity:</b>   | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>   | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition         | Repairer's  | Reference | Amount       |
|-----|-----|----------|-------------------------------|-------------------|-------------|-----------|--------------|
| 1   | 1   |          | *BUMPER COVER REAR            | Buckled / Cracked | 561.70 FL   | -         | *561.70 FL   |
| 2   | 1   |          | *BUMPER LOWER REAR            | Missing           | 411.90 FL   | -         | *411.90 FL   |
| 3   | 1   |          | *BUMPER BRACKET CTR REAR      | Distorted         | 98.10 FL    | -         | *98.10 FL    |
| 4   | 1   |          | *BUMPER BRACKET SIDE RH REAR  | Serviceable       | 82.10 FL    | -         | *- FL        |
| 5   | 1   |          | *BUMPER RETAINER RH REAR      | Serviceable       | 59.80 FL    | -         | *- FL        |
| 6   | 1   |          | *BUMPER REFLECTOR RH          | Cracked           | 16.60 FL    | -         | *16.60 FL    |
| 7   | 1   |          | *BUMPER BRACKET SIDE LH REAR  | Serviceable       | 80.80 FL    | -         | *- FL        |
| 8   | 1   |          | *BUMPER RETAINER LH REAR      | Serviceable       | 54.20 FL    | -         | *- FL        |
| 9   | 1   |          | *BUMPER REFLECTOR LH          | Serviceable       | 16.60 FL    | -         | *- FL        |
| 10  | 1   |          | *BUMPER BEAM REAR             | Bent              | 547.80 FL   | -         | *547.80 FL   |
| 11  | 1   |          | *BUMPER BEAM BRACKET LH REAR  | Distorted         | 114.50 FL   | -         | *114.50 FL   |
| 12  | 1   |          | *BUMPER BEAM BRACKET RH REAR  | Bent              | 100.90 FL   | -         | *100.90 FL   |
| 13  | 1   |          | *BUMPER BLOCK LH REAR         | Serviceable       | 75.70 FL    | -         | *- FL        |
| 14  | 1   |          | *BUMPER BLOCK RH REAR         | Serviceable       | 76.50 FL    | -         | *- FL        |
| 15  | 1   |          | *BUMPER HARNESS REAR          | Serviceable       | 301.10 FL   | -         | *- FL        |
| 16  | 1   |          | *BOOT REAR                    | Bent              | 1,677.20 FL | -         | *1,677.20 FL |
| 17  | 1   |          | *BOOT FINISHER                | Serviceable       | 344.70 FL   | -         | *- FL        |
| 18  | 1   |          | *BOOT WEATHERSTRIP            | Serviceable       | 178.20 FL   | -         | *- FL        |
| 19  | 1   |          | *BOOT REFLECTOR LAMP LH       | Serviceable       | 277.70 FL   | -         | *- FL        |
| 20  | 1   |          | *BOOT REFLECTOR LAMP RH       | Cut               | 277.70 FL   | -         | *277.70 FL   |
| 21  | 1   |          | *BOOT BADGE RENAULT           | Necessary         | 82.40 FL    | -         | *82.40 FL    |
| 22  | 1   |          | *BOOT BADGE                   | Necessary         | 95.80 FL    | -         | *95.80 FL    |
| 23  | 1   |          | *BOOT STRUT LH                | Serviceable       | 145.10 FL   | -         | *- FL        |
| 24  | 1   |          | *BOOT STRUT RH                | Serviceable       | 145.10 FL   | -         | *- FL        |
| 25  | 1   |          | *BOOT HINGE LH                | Repair            | 254.20 FL   | -         | *- FL        |
| 26  | 1   |          | *BOOT HINGE RH                | Repair            | 253.80 FL   | -         | *- FL        |
| 27  | 1   |          | *BOOT TRIM BOARD              | Serviceable       | 611.00 FL   | -         | *- FL        |
| 28  | 1   |          | *BOOT LOCK                    | Repair            | 246.60 FL   | -         | *- FL        |
| 29  | 1   |          | *BOOT LOCK CATCH              | Repair            | 41.70 FL    | -         | *- FL        |
| 30  | 2   |          | *BOOT RUBBER PLUG             | Serviceable       | 139.30 FL   | -         | *- FL        |
| 31  | 1   |          | *BOOT SWITCH                  | Serviceable       | 113.00 FL   | -         | *- FL        |
| 32  | 1   |          | *BOOT LOCK LINKAGE HOLDER     | Serviceable       | 99.50 FL    | -         | *- FL        |
| 33  | 2   |          | *LICENCE PLATE LAMP           | Serviceable       | 26.30 FL    | -         | *- FL        |
| 34  | 1   |          | *TAILLAMP RH                  | Cracked           | 401.40 FL   | -         | *401.40 FL   |
| 35  | 1   |          | *TAILLAMP PANEL RH            | Repair            | 401.40 FL   | -         | *- FL        |
| 36  | 1   |          | *TAILLAMP LH                  | Mtg Cracked       | 401.40 FL   | -         | *401.40 FL   |
| 37  | 1   |          | *TAILLAMP PANEL LH            | Repair            | 401.40 FL   | -         | *- FL        |
| 38  | 1   |          | *OUTER PANEL REAR (END PANEL) | Bent              | 745.80 FL   | -         | *745.80 FL   |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                              | Condition     | Repairer's  | Reference | Amount     |
|-----|-----|----------|--|---------------|-------------|-----------|------------|
| 39  | 1   |          | *OUTER PANEL REAR (END PANEL) TRIM       | Dented        | 404.56 FL   | -         | *404.56 FL |
| 40  | 1   |          | *SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) | Repair        | 1,229.40 FL | -         | *- FL      |
| 41  | 1   |          | *SPARE WHEEL PANEL TRIM                  | Serviceable   | 612.21 FL   | -         | *- FL      |
| 42  | 1   |          | *SPARE WHEEL PANEL BRACKET LH L70Y       | Repair        | 70.60 FL    | -         | *- FL      |
| 43  | 1   |          | *SPARE WHEEL PANEL BRACKET RH L70Y       | Repair        | 69.20 FL    | -         | *- FL      |
| 44  | 1   |          | *SPARE TYRE BOARD                        | Serviceable   | 680.90 FL   | -         | *- FL      |
| 45  | 1   |          | *EXHAUST REAR                            | Repair        | 5,263.60 FL | -         | *- FL      |
| 46  | 1   |          | *EXHAUST CAP REAR                        | Repair        | 125.40 FL   | -         | *- FL      |
| 47  | 1   |          | *SET PARKING AID                         | Shorted       | 700.00 FS   | -         | *400.00 FS |
| 48  | 1   |          | *SET REAR BUMPER CLIP                    | Necessary     | 69.00 FS    | -         | *69.00 FS  |
| 49  | 1   |          | *SET BUMPER BRACKET CTR CLIP             | Not Necessary | 40.00 FS    | -         | *- FS      |
| 50  | 1   |          | *SET BUMPER BRACKET SIDE CLIP RH RR      | Not Necessary | 35.00 FS    | -         | *- FS      |
| 51  | 1   |          | *SET BUMPER RETAINER RH CLIP RR          | Not Necessary | 45.00 FS    | -         | *- FS      |
| 52  | 1   |          | *SET BUMPER BRACKET SIDE CLIP LH RR      | Not Necessary | 35.00 FS    | -         | *- FS      |
| 53  | 1   |          | *SET BUMPER RETAINER CLIP LH RR          | Not Necessary | 45.00 FS    | -         | *- FS      |
| 54  | 1   |          | *SET BUMPER LOWER REAR RIVET             | Not Necessary | 38.00 FS    | -         | *- FS      |
| 55  | 1   |          | *SET BUMPER LOWER REAR CLIP              | Necessary     | 69.00 FS    | -         | *69.00 FS  |
| 56  | 2   |          | *END PANEL SEAM SEALANT                  | Serviceable   | 170.00 FS   | -         | *- FS      |
| 57  | 1   |          | *SET BOOT FINISHER CLIP                  | Not Necessary | 40.00 FS    | -         | *- FS      |
| 58  | 1   |          | *BOOT STICKER TRANS-CAB                  | Necessary     | 65.00 FS    | -         | *30.00 FS  |
| 59  | 1   |          | *EXHAUST MOUNTING REAR                   | Serviceable   | 40.00 FS    | -         | *- FS      |
| 60  | 1   |          | *EXHAUST BRACKET REAR                    | Serviceable   | 40.00 FS    | -         | *- FS      |
| 61  | 1   |          | *EXHAUST PIPE CLAMP                      | Serviceable   | 68.80 FS    | -         | *- FS      |
| 62  | 1   |          | *SET FENDER INNER TRIM CLIP              | Not Necessary | 40.00 FS    | -         | *- FS      |
| 63  | 1   |          | *BOOT STICKER 6555-3333                  | Necessary     | 65.00 FS    | -         | *30.00 FS  |
| 64  | 1   |          | *BOOT TRIM BOARD CLIP                    | Not Necessary | 45.00 FS    | -         | *- FS      |
| 65  | 1   |          | *SPARE TYRE RIM (ROUE 7J 16H 2547)       | Serviceable   | 385.00 FS   | -         | *- FS      |
| 66  | 1   |          | *SPARE TYRE                              | Serviceable   | 330.00 FS   | -         | *- FS      |
| 67  | 1   |          | *TAILLAMP CLIP RH                        | Necessary     | 30.00 FS    | -         | *5.00 FS   |
| 68  | 2   |          | *REAR WINDSCREEN SEALANT                 | Not Necessary | 150.00 FS   | -         | *- FS      |
| 69  | 1   |          | *WINDSCREEN MOULDING                     | Not Necessary | 180.00 FS   | -         | *- FS      |
| 70  | 1   |          | *REAR WINDSCREEN INNER SPONGE SEAL       | Not Necessary | 120.00 FS   | -         | *- FS      |
| 71  | 1   |          | *TAILLAMP CLIP LH                        | Necessary     | 30.00 FS    | -         | *5.00 FS   |
| 72  | 1   |          | *REAR BUMPER PROTECTOR                   | Not Necessary | 150.00 FS   | -         | *- FS      |
| 73  | 1   |          | *SET REAR LICENCE PLATE WITH HOLDER      | Dented        | 120.00 FS   | -         | *45.00 FS  |
| 74  | 1   |          | *SET END PANEL INSULATION PAD            | Not Necessary | 200.00 FS   | -         | *- FS      |
| 75  | 1   |          | *SET REAR END PANEL INNER TRIM CLIP      | Not Necessary | 40.00 FS    | -         | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                  |                 |
|--|------------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>21,799.67</b> | <b>6,590.76</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$)</b> | 1,841.49         | 593.78          |
| <b>Total Parts (\$)</b>                                  | <b>19,958.18</b> | <b>5,996.98</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars   | Lab.Type | Repairer's       | Amount          |
|--------------------------------|---|----------|------------------|-----------------|
| <b>Labour Items</b>            |   |          |                  |                 |
| 1                              | TO REMOVE AND REFIT REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR   | New      | 170.00           | 0.00            |
| 2                              | PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME | New      | 7,500.00         | 600.00          |
| 3                              | TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING   | New      | 380.00           | 0.00            |
| 4                              | TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST                               | New      | 380.00           | 60.00           |
| 5                              | TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST   | New      | 170.00           | 60.00           |
| 6                              | TO REPAIR AND REALIGN REAR EXHAUST PIPE   | New      | 170.00           | 0.00            |
| 7                              | TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST   | New      | 380.00           | 0.00            |
| 8                              | TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST  | New      | 170.00           | 0.00            |
| 9                              | TO RUST-PROOFING OF THE AFFECTED AREAS  | New      | 170.00           | 60.00           |
| 10                             | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION  | New      | 7,500.00         | 660.00          |
| 11                             | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR  | New      | 380.00           | 0.00            |
| 12                             | TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING   | New      | 170.00           | 0.00            |
| 13                             | TO REINSTALL REAR BUMPER PARKING SENSOR   | New      | 170.00           | 60.00           |
| 14                             | TO CHECK ELECTRICAL LIGHTING CONCERNED  | New      | 170.00           | 20.00           |
| 15                             | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR                            | New      | 380.00           | 0.00            |
| 16                             | TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE                                       | New      | 170.00           | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |   |          | <b>18,430.00</b> | <b>1,520.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >