

ASS. REC. BY:

REF: TM1/

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Trans Cab  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: S1465127A Yr Regn: 12, 13  
 Type: M.Car / M.Cycle / Bus / Van / Lorry /  Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Renault Latitude c.c. 1995  
 Colour M. White / Red A/C: Insured / Std / NI / NA  
 Sp. Reading 310.429 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: VFIABL15AUC 276541  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or  
 Brake:  In order / Jammed / Leaked / Burnt or  
 Mod:  M / S/Rlm / STD A/Rlm or  
 Tyre Size: F: 215/60R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Pailon  
 Front R/Bal. 9 mm Rear R/Bal. 8 mm  
 L/Bal. 9 mm L/Bal. 8 mm  
 D.O.A. 23/6/20 D.O.I. 24/6/2020  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt /  Rear / OIS / NIS / UIC / Rooftop or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 26,100/-  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>61 Imp @ 5800</u>

Date/Time, File Pass to?  : Prell. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?  
 1) \_\_\_\_\_  
 2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation:	_____ \$ - RS. _____ \$
Fuel/Oil:	_____
Others:	_____
TOTAL	_____

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5127A**

AAD2006-061

*Not Authorised*  
*61 Sup & 5800*

Vehicle No.:  
Chassis No.:  
Vehicle Make: **24 JUN 2020**  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

**SHC 5127A**  
VF1ABL15AUC276541  
RENAULT  
LATITUDE  
23.6.2020  
**TOKIO MARINE**  
27/12/2013

- |   | <b>PART</b>                 |
|---|-----------------------------|
| 1 | BUMPER COVER REAR           |
| 1 | BUMPER LOWER REAR           |
| 1 | BUMPER BRACKET CTR REAR     |
| 1 | BUMPER BRACKET SIDE RH REAR |
| 1 | BUMPER RETAINER RH REAR     |
| 1 | BUMPER REFLECTOR RH         |
| 1 | BUMPER BRACKET SIDE LH REAR |
| 1 | BUMPER RETAINER LH REAR     |
| 1 | BUMPER REFLECTOR LH         |
| 1 | BUMPER BEAM REAR            |
| 1 | BUMPER BEAM BRACKET LH REAR |
| 1 | BUMPER BEAM BRACKET RH REAR |
| 1 | BUMPER BLOCK LH REAR        |
| 1 | BUMPER BLOCK RH REAR        |
| 1 | BUMPER HARNESS REAR         |
| 1 | BOOT REAR                   |
| 1 | BOOT FINISHER               |
| 1 | BOOT WHEATERSTRIP           |
| 1 | BOOT REFLECTOR LAMP LH      |
| 1 | BOOT REFLECTOR LAMP RH      |
| 1 | BOOT BADGE 'RENAULT'        |
| 1 | BOOT BADGE                  |
| 1 | BOOT STRUT LH               |
| 1 | BOOT STRUT RH               |
| 1 | BOOT HINGE LH               |
| 1 | BOOT HINGE RH               |
| 1 | BOOT TRIM BOARD             |
| 1 | BOOT LOCK                   |
| 1 | BOOT LOCK CATCH             |

<b>LIST</b>	
\$	<i>Buc/CM</i> 561.70 ✓
\$	<i>MIS</i> 411.90 ✓
\$	<i>D/I</i> 98.10 —
\$	<i>SW</i> 82.10 X
\$	<i>SW</i> 59.80 X
\$	<i>CM</i> 16.60 ✓
\$	<i>SW</i> 80.80 X
\$	<i>SW</i> 54.20 X
\$	<i>SW</i> 16.60 X
\$	<i>B</i> 547.80 ✓
\$	<i>D/I</i> 114.50 —
\$	<i>B</i> 100.90 —
\$	<i>SW</i> 75.70 X
\$	<i>SW</i> 76.50 X
\$	<i>SW</i> 301.10 X
\$	<i>B</i> 1,677.20 ✓
\$	<i>SW</i> 344.70 X
\$	<i>SW</i> 178.20 X
\$	<i>SW</i> 277.70 X
\$	<i>CM</i> 277.70 ✓
\$	<i>ME</i> 82.40 —
\$	<i>ME</i> 95.80 —
\$	<i>SW</i> 145.10 } X
\$	<i>SW</i> 145.10 }
\$	<i>R</i> 254.20 }
\$	<i>R</i> 253.80 }
\$	<i>SW</i> 611.00 }
\$	<i>R</i> 246.60 }
\$	<i>R</i> 41.70 }

**Trans-cab Auto Services Pte Ltd**

AAD2006-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5127A

2	BOOT RUBBER PLUG	\$	SL	139.30	X
1	BOOT SWITCH	\$	SL	113.00	X
1	BOOT LOCK LINKAGE HOLDER	\$	SL	99.50	X
2	LICENCE PLATE LAMP	\$	SL	26.30	X
1	TAILLAMP RH	\$	CM	401.40	✓
1	TAILLAMP PANEL RH	\$	R	401.40	X
1	TAILLAMP LH	\$	my CM	401.40	✓
1	TAILLAMP PANEL LH	\$	R	401.40	X
1	OUTER PANEL REAR (End Panel)	\$	R	745.80	✓
1	OUTER PANEL REAR (End Panel) TRIM	\$	no	404.56	✓
1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	1,229.40	} X
1	SPARE WHEEL PANEL TRIM	\$	SL	612.21	
1	SPARE WHEEL PANEL BRACKET LH L70Y	\$	R	70.60	
1	SPARE WHEEL PANEL BRACKET RH L70Y	\$	R	69.20	
1	SPARE TYRE BOARD	\$	SL	680.90	
1	EXHAUST REAR	\$	R	5,263.60	
1	EXHAUST CAP REAR	\$	R	125.40	
<b>TOTAL</b>		<b>\$</b>		<b>18,414.87</b>	
<b>10%</b>		<b>\$</b>		<b>1,841.49</b>	
		<b>\$</b>		<b>16,573.38</b>	

**Special Nett**

1SET	PARKING AID	\$	shop	700.00	4000-
1SET	REAR BUMPER CLIP	\$	na	69.00	✓
1SET	BUMPER BRACKET CTR CLIP	\$	na	40.00	X
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	35.00	X
1SET	BUMPER RETAINER RH CLIP RR	\$	na	45.00	X
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	35.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	na	45.00	X
1SET	BUMPER LOWER REAR RIVET	\$	na	38.00	X
1SET	BUMPER LOWER REAR CLIP	\$	na	69.00	✓
2	END PANEL SEAM SEALANT	\$	SL	170.00	X
1SET	BOOT FINISHER CLIP	\$	na	40.00	X
1	BOOT STICKER "Trans-cab"	\$	na	65.00	3000-
1	EXHAUST MOUNTING REAR	\$	SL	40.00	X
1	EXHAUST BRACKET REAR	\$	SL	40.00	X

**Trans-cab Auto Services Pte Ltd**

AAD2006-061

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5127A

1 EXHAUST PIPE CLAMP	\$	Sn	68.80 X
1SET FENDER INNER TRIM CLIP	\$	Nn	40.00 X
1 BOOT STICKER "6555-3333"	\$	Nn	65.00 301N
1 BOOT TRIM BOARD CLIP	\$	Nn	45.00 X
1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00 X
1 SPARE TYRE	\$	Sn	330.00 X
1 TAILLAMP CLIP RH	\$	Nn	30.00 5.01N
2 REAR WINDSCREEN SEALANT	\$	Nn	150.00 X
1 WINDSCREEN MOULDING	\$	Nn	180.00 X
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	Nn	120.00 X
1 TAILLAMP CLIP LH	\$	Nn	30.00 5.01N
1 Rear Bumper Protector	\$	Nn	150.00 X
1SET Rear licence plate with holder	\$	Nn	120.00 451N
1SET END PANEL INSULATION PAD	\$	Nn	200.00 X
1SET REAR END PANEL INNER TRIM CLIP	\$	Nn	40.00 X
<b>TOTAL</b>	<b>\$</b>		<b>3,384.80</b>

<b>TOTAL PARTS</b>	<b>\$</b>		<b>19,958.18</b>
--------------------	-----------	--	------------------

**LABOUR**

To remove and refit rear windscreen glass to facilitate bodywork repair.	\$	Nn	170.00 X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		7,500.00 6002
To supply and re-do rear luggage floor panel insulation padding.	\$	Nn	380.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$		380.00 602
To transfer of bootlid fittings, attachments and perform water seepage test.	\$		170.00 602
To repair and realign rear exhaust pipe.	\$	Nn	170.00 X

**Trans-cab Auto Services Pte Ltd**

**AAD2006-061**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5127A**

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$		170.00	<i>601</i>
Putty And Spray Painting Of The Affected Portion.	\$		7,500.00	<i>6601</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>601</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i>	170.00	<i>X</i>
<b>TOTAL</b>	<b>\$</b>		<b>18,430.00</b>	
<b>Over All Total</b>	<b>\$</b>		<b>38,388.18</b>	

**(LUMP SUM) Repair Days**

**25 DAYS**

*3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/06/2020 09:34
Date Of Accident	23/06/2020 06:55
Exact Location Of Accident	JURONG TOWN HALL ROAD SLIP ROAD TOWARDS PIE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5127A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	2XXXXX878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

### Driver

Name of Driver	LEONG SHIH YI
NRIC No	SXXXX1311
Date Of Birth	21/02/1955
Occupation	OUTDOOR
Date Of Driving Pass	19/12/1975
Driving Experience	44 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91834078
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address BLK 394 TAMPINES AVENUE 7  
#07-267

Postcode 520394

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions RAINING

Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : UNKNOWN  
GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

**Circumstances of Accident**

On 23.06.2020 at about 0655hours, I was travelling along Jurong Town Hall Road slip road towards PIE when I made a stop to check for oncoming vehicle, suddenly I felt an impact. Vehicle B (GX1678D) hit onto my taxi's rear portion.

**Attachment(s)**

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GX1678D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category GOODS VEHICLE

Name of Driver

NRIC/Passport Number


Contact Number

Address

Postcode

Insurance Company Name

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach GM Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: