

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20006644/QBA3Q2

**Date:** 13/01/2021

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> FBM4861M	<b>Insured Vehicle No :</b>	SHA5745B
Date of Loss: 21/06/2020	Nature of Claim:	TP Claim No: MCT20060225

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM4861M		
Make & Model:	HONDA CB190X, 184cc	Engine No:	WH161FMK17J01026
Reg. Date:	30/11/2017 (Man. Year: 2017)	Chassis No:	LWBPCL1A8H1000726
Colour:	Black	Odometer:	76379 km
Engine Capacity:	184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	110/70-17	Rear Tyre Size:	110/70-17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,016.70	1,979.70	3,037.00	60.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	340.00	890.00	72.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,246.70</b>	<b>2,319.70</b>	<b>3,927.00</b>	<b>62.87</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>437.27</b>	<b>162.38</b>	<b>274.89</b>	<b>62.87</b>
<b>Nett Amount (S\$)</b>	<b>6,683.97</b>	<b>2,482.08</b>	<b>4,201.89</b>	<b>62.87</b>
<b>+ Loss of Use (3.0 x S\$40.00/day) (S\$)</b>		120.00		
<b>+ Doc/Search Fee (S\$)</b>		29.00		
<b>Nett Liability (S\$)</b>		<b>2,631.08</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,600.00</b>		

#### INSPECTION

Date of Assignment:	24/06/2020	
Date Inspected:	24/06/2020 Inspected At:	Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands Singapore 737856

Estimated Period of Repair: 2.0 days

---

**Adjuster:** OI SUN PIN

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 Dec 2020)	
<b>Parts:</b>	N/A	HONDA CB190X 184cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBM4861M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIDE FAIRING LH	Cracked	474.00 FL	*220.00 FL
2	1		*FRONT SIDE FAIRING RH	Scratched	474.00 FL	*220.00 FL
3	1		*FRONT SIDE INNER FAIRING LH	Serviceable	455.00 FL	*- FL
4	1		*FUEL TANK FAIRING LH	Cracked	308.00 FL	*115.00 FL
5	1		*FRONT SIDE INNER FAIRING INNER PROTECTOR LH	Cracked	290.00 FL	*180.00 FL
6	1		*CENTRE TOP FAIRING LH	Scratched	341.00 FL	*195.00 FL
7	1		*CENTRE BOTTOM FAIRING LH	Cracked	307.00 FL	*185.00 FL
8	1		*FRONT HANDLE BAR	Repair	508.00 FL	*- FL
9	1		*FRONT HANDLE BAR HAND GUARD LH	Scratched	165.00 FL	*100.00 FL
10	1		*FRONT HANDLE BAR HAND GUARD RH	Cracked	165.00 FL	*100.00 FL
11	1		*FRONT FOOT LEVER LH	Broken	145.00 FL	*98.78 FL
12	1		*REAR FOOT REST LH	Scratched	45.00 FL	*45.00 FL
13	1		*REAR FOOT REST BRACKET LH	Scratched	165.00 FL	*97.00 FL
14	1		*SIDE STAND	Serviceable	120.00 FL	*- FL
15	1		*FRONT FORK LH	Serviceable	374.00 FL	*- FL
16	1		*FRONT FORK RH	Serviceable	374.00 FL	*- FL
17	1		*FRONT FOOT REST BRACKET LH	Bent	195.00 FL	*195.00 FL
18	1		*FUEL TANK FAIRING RH	Cracked	308.00 FL	*160.00 FL
19	1		*REAR BOX	Scratched	260.00 FS	*260.00 FS
20	1		*REAR BOX TRAY	Repair	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,538.00</b>	<b>2,170.78</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	521.30	191.08
<b>Total Parts (\$\$)</b>	<b>5,016.70</b>	<b>1,979.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS ,REPLACE DAMAGED PARTS	New	20.00	20.00
2	TO DISMANTLE AND REFIT FRONT UNDERCARRIAGE	New	220.00	0.00
3	TO CONDUCT WHEEL BALANCING	New	60.00	40.00
4	TO REMOVE AND RELACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	480.00	250.00
5	TO CARRY OUT BODY CAVITY PRESERVATION	New	70.00	30.00
6	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,230.00</b>	<b>340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >