

ASS. REC. BY:

C9/40120006646/Dsg 3


OE July 2021

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 CR / TP / WS / TP RES / CR RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: QZ 74832 Yr Reg: 2006 Ang
 Type: M/Car / M/Cycle / Bus / Van / Com / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Dyna c.c. 2986
 Colour: SILVER A/C: Insured / Std / NI / NA
 Sp. Reading: 487595 T/Radio: Insured / Std / NI / NA
 Eng/No: 5L6657653
 Ch/No: JTFUF34Y303012120
 Gen. Cond: Good Fair / Poor / Burnt
 Steering: Good Jammed / Leaked / Burnt or
 Brake: Good Jammed / Leaked / Burnt or
 Mod: NI / S/Rim / STD A/Rim or
 Tyre Size: F: 185 R14C
 R: 155 R12C (double)
 BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: Michelin Rear: Falken
 R/Bal. S mm R/Bal. S/S mm
 L/Bal. S mm L/Bal. S/S mm
 D.O.A. 22/06/2020 D.O.I. 25/06/2020
 Survey held at: Goh Lee Hwa AMK
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Front & Rear
 The UIC / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: 10 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT




Date / Time	Action / Instruction
	UOI 9P6496H
	MV 151C Request for OI GVA repair.
	LTA 4.8K
	HL 10.2K 4prs well pan damaged. Invoice attached in GVA report.
	10

15/07/20 pinan RIS 8400/- with 10 days of rep.
~~13,111~~ (\$13,111.60 Red 61%)
 Days Of Repair: 10

Date/Time, File Pass to? : Prel. Report
 1) 15/07/20 : Final Report
 Date/Time, File Return to? _____
 2) _____
 Report Format: _____
 Lump Sum / I.B.I: (% 8,400/- RIS)

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S+RS \$ _____
 Photos _____
 Others _____
 TOTAL _____



GOH LEE HWA AUTOMOBILE PTE LTD
 Block 5033 Ang Mo Kio Industrial Park 2
 #01-255 Singapore 569536
 Tel No: (65) 6482 5168
 Fax No. (65) 6482 4452
 Email: ghauto66@gmail.com
 Co.reg no. 200808259H

Reference No: 230620
 Date: 23.06.2020

Aik Chin Hin Machinery Co.
 Blk 5022 Ang Mo Kio Industrial Park 2 #01-31
 Singapore 569525
 Toyota Dyna 150 D

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Estimated Repair Cost for Vehicle Reg. No: GZ 7483 Z

REPLACEMENT OF DAMAGED PANELS / PARTS

1 Pc. Rear Carriage Floor Panel	Dented / St		2,350.00 (S.Nett.)	✓
2 Pc. Rear Carriage Side Panel	Repair	@ 1,351.00	2,702.00 (S.Nett.)	X
4 Pcs. Rear Carriage Side Panel Hinger	St	@ 48.00	192.00 (S.Nett.)	✓
1 Pc. Rear Aluminum Floor Panel	St		950.00	✓
1 Pc. Rear Aluminum Standing Panel	NH		300.00	X
1 Set Rear Carriage Side Protector	St		400.00	✓
10 Pcs. Rear Carriage Lock Nut	NH	@ 32.00	320.00 (S.Nett.)	X
1 Set Rear Toyota Sticker	Nec		99.10	✓
1 Pc. Rear 70 KM/H Sticker	Nec		10.00	✓
1 Pc. Rear Dyna Sticker	Nec		68.00	✓
1 Pc. Rear 3 Pax Sticker	Nec		10.00	✓
1 Pc. Front Panel Top	Dented		310.60	✓
1 Pc. Front Panel Garnish	cut / mostly broken		299.50	✓
2 Pcs. Front Corner Panel Garnish	St / cut	@ 199.30	398.60	✓
1 Pc. Front Panel	Dented		1,049.00	✓
1 Pc. Front Logo	Nec		105.40	✓
1 Pc. Front Dyna Sticker	Nec		49.50	✓
1 Pc. Front Grille	cut / broken		299.00	✓
10 Pcs. Front Grille Clips	Nec	@ 5.50	55.00	✓
2 Pcs. Front Head Lamp Assy.	broken	@ 699.10	1,398.20	✓
2 Pcs. Rear Lamp	NH	@ 290.00	580.00	X
1 Pc. Rear Tail Gate	Dented		1,130.00	✓
1 Pc. Front Bumper	Dented		489.90	✓
1 Pc. Front Windscreen Rubber	Nec		338.50	✓
2 Pcs. Front & Rear Number Plate	Front St New NH	@ 30.00	60.00	LL 15/- SH
2 Pcs. Tailgate Lock	St	@ 185.00	397.00	✓

GOH LEE HWA AUTOMOBILE PTE LTD
 Block 5033 Ang Mo Kio Industrial Park 2
 #01-255 Singapore 569536
 Tel No: (65) 6482 5168
 Fax No. (65) 6482 4452
 Email: glhauto66@gmail.com
 Co.reg no. 200808259H

1 Pc. Rear End Panel	<i>Debris</i>	499.80	✓
1 Pc Air con Bowler ASSY	<i>namely broken</i>	920.50	✓
2 Pc Engine mounting	@ 358.00	716.00	X
2 Pc Gear Box mounting	@ 262.00	524.00	X

Total (Panels / Parts): 17021.60 (SGD)

9277.60
 25% 6958.20
 SH ~~5257.00~~
 2557.00

LABOR CHARGES

To check wiring & refit carriage wiring.	200.00	40/-	
To straightening repair & renew carriage & all accident affected area.	1,400.00	1200/-	
To remove & refit front windscreen.	130.00	120/-	
To remove & refit dashboard & air-con blower, top up Gas & oil.	480.00	180/-	
To respray painting on all accident affected area.	1,500.00	1000/-	
To rust proof all accident affected area.	200.00	60/-	2600/-
To remove and refit renew engine and gear box mounting	580.00	Nil	

Total (Labor Charges): 4,490.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS

Parts 9515.20
 labor 2600.00
 12115.20
 17,021.60
 7/5 8400/-



GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2
#01-255 Singapore 569536
Tel No: (65) 6482 5168
Fax No. (65) 6482 4452
Email: ghauto66@gmail.com
Co.reg no. 200808259H

LABOR CHARGES 4490.00

Grand Total: 21511.60 (SGD)

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'GOH LEE HWA AUTOMOBILE PTE LTD'

Handwritten signature

GOH LEE HWA AUTOMOBILE PTE LTD [WITHOUT PREJUDICE SAVE AS TO COSTS]

*25/06/2020 @ 10am
Not Actual
L/Sum 10 days.*

*Handwritten signature
LKK Auto*

*Check MV
Repair limit.*

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: