

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20006649/AGA3Q2

Date: 06/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800084934

Claimant
Vehicle No : SMP6729D **Insured Vehicle No :** SMC7075T

Date of Loss: 21/06/2020 Nature of Claim: TP Claim No: 5847872098SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP6729D		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR2D77782
Reg. Date:	08/10/2019 (Man. Year: 2019)	Chassis No:	ZWR800389719
Colour:	Grey	Odometer:	51829 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Crucero 6 mm	Rear Left Side:	Crucero 6 mm
Front Right Side:	Crucero 6 mm	Rear Right Side:	Crucero 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,871.70	12,444.92	6,426.78	34.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,790.00	2,570.00	2,220.00	46.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,661.70	15,014.92	8,646.78	36.54
Approved Total (Overridden) (S\$)		12,000.00		
(S\$)	23,661.70	12,000.00	11,661.70	49.29
+ GST 7.00/7.00% (S\$)	1,656.32	840.00	816.32	49.29
Nett Amount (S\$)	25,318.02	12,840.00	12,478.02	49.29
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		13,669.00		

INSPECTION

Date of Assignment: 23/06/2020

Date Inspected: 23/06/2020 Inspected At: Mg Solution Pte Ltd - Kaki Bukit (HQ)
25 Kaki Bukit Road 4 #04-01
Singapore 41800

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,055.30 FL	*985.00 FL
2	1		*BONNET OUTER PROTECTOR	Cracked	380.00 FL	*248.00 FL
3	2		*BONNET HINGE	Bent	180.00 FL	*180.00 FL
4	1		*FRONT BUMPER	Distorted	855.90 FL	*855.90 FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	220.00 FL	*220.00 FL
6	1		*FRONT BUMPER FOGLAMP COVER RH	Deformed	130.00 FL	*130.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	822.60 FL	*432.00 FL
8	1		*FRONT BUMPER REINFORCEMENT SPONGE	Cracked	255.60 FL	*255.60 FL
9	2		*HEADLAMP HID	Cracked	7,710.60 FL	*6,003.00 FL
10	1		*HEADLAMP HID OUTER GARNISH RH	Cracked	90.00 FL	*90.00 FL
11	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	80.00 FL	*- FL
12	1		*HEADLAMP SIDE PANEL RH	Buckled	388.50 FL	*388.50 FL
13	1		*FRONT CENTRE GRILLE LOGO	Necessary	98.50 FL	*98.50 FL
14	1		*FRONT CENTRE GRILLE (TOP)	Cracked	922.30 FL	*798.00 FL
15	1		*FRONT CENTRE GRILLE (BELOW)	Cracked	954.20 FL	*455.00 FL
16	1		*WASHER TANK	Deformed	230.00 FL	*230.00 FL
17	1		*AIR CLEANER BOX ASSY	Deformed	455.90 FL	*455.90 FL
18	1		*FRONT FENDER	Distorted	885.20 FL	*804.00 FL
19	1		*FRONT FENDER INNER COWLING	Torn	280.00 FL	*280.00 FL
20	1		*FRONT FENDER INNER PROTECTOR	Deformed	190.00 FL	*85.00 FL
21	1		*FRONT FENDER HYBRID	Necessary	90.00 FL	*90.00 FL
22	1		*FRONT LOWER ARM	Bent	420.00 FL	*420.00 FL
23	1		*FRONT KNUCKLE ARM	Damaged	499.30 FL	*499.30 FL
24	1		*FRONT KNUCKLE BEARING	Necessary	533.60 FL	*398.00 FL
25	1		*FRONT STABILIZER LINK	Not Necessary	160.00 FL	*- FL
26	1		*FRONT TIE ROD END	Not Necessary	130.00 FL	*- FL
27	1		*FRONT ABSORBER	Bent	533.20 FL	*533.20 FL
28	1		*FRONT ABS SENSOR	Not Necessary	444.30 FL	*- FL
29	1		*FRONT DOOR	Repair	2,255.60 FL	*- FL
30	2		*FRONT DOOR HINGE	Not Necessary	180.00 FL	*- FL
31	1		*FRONT DOOR CHECKER	Not Necessary	180.00 FL	*- FL
32	1		*AIR CON PIPE (H)	Bent	285.00 FL	*285.00 FL
33	1		*WASHER TANK NECK	Deformed	80.00 FL	*80.00 FL
34	1		*SET FRONT BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
35	1		*SET FRONT FENDER INNER COWLING CLIP	Necessary	20.00 FS	*20.00 FS
36	1		*WHEEL RIM	Cut	1,800.00 FS	*680.00 FS
37	1		*WHEEL TYRE	Punctured	550.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	24,365.60	16,269.90
- List Item Discount on L Items 25.00/25.00% (\$)	5,493.90	3,824.98
Total Parts (\$)	18,871.70	12,444.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT,REMOVE AND REPLACE PARTS	New	2,000.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,200.00
3	TUFF COAT	New	180.00	80.00
4	WIRING CHECK	New	150.00	30.00
5	TO REMOVE AND REFIX FRONT DOOR MECHANISM	New	180.00	0.00
6	TO REMOVE UNDERCARRIAGE	New	180.00	180.00
7	WHEEL ALIGHMENT	New	100.00	80.00
Gross Labour Cost (\$\$)			4,790.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >