

NTUC-4S  
LKK - Taufik Kh.

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305406848  
 REGN NO : SHC1852R  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ  
 DATE OF REGN : 31.01.2017  
 DATE/TIME IN : 24.06.2020 09:45  
 ACCIDENT DATE : 23.06.2020

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|                        |                          |      |        |       |        |       |
|------------------------|--------------------------|------|--------|-------|--------|-------|
| 0001 04-01-0104-2282-G | REAR BUMPER              | 1    | 459.40 | 20.00 | 367.52 | Rx    |
| 0002 04-01-0104-2533-G | REAR BUMPER CENTRE-Black | 1    | 451.25 | 20.00 | 361.00 | cut ✓ |
| 0003 04-01-0104-2370-G | REAR BUMPER FOGLAMP      | 1    | 201.50 | 20.00 | 161.20 | X u u |
| 0004 04-01-0101-0111-G | REAR BUMPER CLIPS        | 10 L | 22.00  | 20.00 | 17.60  | X u u |
| 0005 09-01-9999-0068-A | REVERSE SENSOR           | 1    | 180.00 | 10.00 | 162.00 | X u u |

SUB-TOTAL : 1,069.32

361

## JOB NATURE

|         |                    |        |     |
|---------|--------------------|--------|-----|
| 0000 PB | PANEL BEATING      | 350.00 | 320 |
| 0001 SP | SPRAYPAINT CHARGE  | 250.00 | 200 |
| 0002 L  | R/I REVERSE SENSOR | 120.00 | 30  |

SUB-TOTAL : 720.00

911  
4/5/750 #  
02 days

Taufik 97495749  
 'WP'  
 02 days 24/6/20 @ 4pm  
 bumpers  
 Resurvey after repair  
 Taufik @ lkkauto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: