

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20006669/AQF3E2

**Date:** 06/07/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30434219000	
Claimant Vehicle No :	SMJ4672C	Insured Vehicle No :	YN646S	
Date of Loss:	22/06/2020	Nature of Claim:	TP	Claim No: SNM20D202237/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ4672C			
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UCT3090	
Reg. Date:	29/12/2015 (Man. Year: 2015)	Chassis No:	MMBSTA13AFH018514	
Colour:	White	Odometer:	103585 km	
Engine Capacity:	1193 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,142.73	3,592.73	1,550.00	30.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,280.00	1,220.00	48.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,642.73</b>	<b>4,872.73</b>	<b>2,770.00</b>	<b>36.24</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
<b>(S\$)</b>	7,642.73	2,800.00	4,842.73	63.36
<b>+ GST 7.00/7.00% (S\$)</b>	534.99	196.00	338.99	63.36
<b>Nett Amount (S\$)</b>	<b>8,177.72</b>	<b>2,996.00</b>	<b>5,181.72</b>	<b>63.36</b>

### INSPECTION

Date of Assignment:	30/06/2020			
Date Inspected:	25/06/2020	Inspected At:	N-51 Automotive Pte Ltd (HQ)	
			2 KAKI BUKIT AVE 2	
			#01-17 KAKI BUKIT AUTOHUB	
			SINGAPORE 417921	
Estimated Period of Repair:	5.0 days			

---

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 05 Jul 2020)	
<b>Parts:</b>	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMJ4672C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	732.50 FL	*732.50 FL
2	1		*FRONT BONNET INSULATOR MAT	Not Necessary	161.00 FL	*- FL
3	1		*FRONT BONNET MECHANISM LOCK	Not Necessary	65.00 FL	*- FL
4	1		*FRONT BUMPER	Deformed	699.30 FL	*699.30 FL
5	1		*FRONT BUMPER GRILLE	Not Necessary	156.00 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Dented	150.00 FL	*150.00 FL
7	2		*FRONT BUMPER SIDE RETAINER L/R	Necessary	35.00 FL	*35.00 FL
8	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	29.00 FL	*- FL
9	1		*FRONT BUMPER UPPER COVER	Cracked	113.00 FL	*113.00 FL
10	2		*FRONT FENDER MOULDING L/R	Not Necessary	118.00 FL	*- FL
11	1		*FRONT GRILLE	Cut	551.00 FL	*551.00 FL
12	1		*FRONT GRILLE LOGO EMBLEM	Necessary	49.00 FL	*49.00 FL
13	2		*FRONT HEADLAMP L/R	Cracked	1,450.00 FL	*1,450.00 FL
14	1		*FRONT SUPPORT PANEL	Repair	999.00 FL	*- FL
15	1		*FRONT SUPPORT PANEL SIDE AIR GUIDE L/R	N/S Cracked	44.00 FL	*22.00 FL
16	1		*FRONT SUPPORT PANEL UPPER GARNISH	Cracked	112.35 FL	*112.35 FL
17	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
18	1		*FRONT NUMBER PLATE	Not Necessary	25.00 FS	*- FS
19	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
20	1		*RADIATOR COOLANT	Necessary	50.00 FS	*40.00 FS
21	1		*SET FRONT BONNET INSULATOR MAT CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,689.15</b>	<b>3,984.15</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	546.42	391.42
<b>Total Parts (\$\$)</b>	<b>5,142.73</b>	<b>3,592.73</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE, REINSTALL AIR CON PARTS, VACUUMS, REFILL AIR CON GAS. (TO FR)	New	120.00	120.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING (TO FR)	New	50.00	30.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,150.00	600.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	30.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,100.00	500.00
<b>Gross Labour Cost (S\$)</b>			<b>2,500.00</b>	<b>1,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >