

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20006680/KRA3Q2
Date: 19/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994025
Claimant Vehicle No :	SHD9628P	Insured Vehicle No :	SLW9864B
Date of Loss:	21/06/2020	Nature of Claim:	TP
		Claim No:	1175248580SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9628P	Engine No:	2ZR2C34919
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU203082066
Reg. Date:	27/06/2019 (Man. Year: 2018)	Odometer:	58339 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,483.92	1,424.17	6,059.75	80.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,510.00	1,230.00	13,280.00	91.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,993.92	2,654.17	19,339.75	87.93
+ GST 7.00/7.00% (S\$)	1,539.57	185.79	1,353.78	87.93

Nett Amount (S\$)	23,533.49	2,839.96	20,693.53	87.93
	Global Sum Settlement (S\$)		0.00	

INSPECTION

Date of Assignment: 24/06/2020

Date Inspected: 24/06/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Trans-Cab Services Pte Ltd (HQ)
 2 Ang Mo Kio Street 63
 Singapore 569111

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MOULDING ASSY ,BODY ROCKER PANEL ,LH	Repair	594.80 FL	*- FL
2	1		*PANEL SUB-ASSY ,QUARTER LH	Repair	871.50 FL	*- FL
3	1		*REAR FENDER LINER	Serviceable	139.80 FL	*- FL
4	1		*DUCT ASSY ,QUARTER VENT ,LH	Serviceable	67.00 FL	*- FL
5	1		*SEAL ,REAR BUMPER SIDE ,LH	Serviceable	88.50 FL	*- FL
6	1		*REAR BUMPER	Serviceable	442.60 FL	*- FL
7	1		*REAR BUMPER UNDER COVER (BLACK)	Serviceable	576.30 FL	*- FL
8	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	*- FL
9	1		*TAILLAMP LOWER LH	Serviceable	502.00 FL	*- FL
10	1		*TAILLAMP UPPER LH	Cut	451.80 FL	*451.80 FL
11	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*- FL
12	1		*PANEL SUB-ASSY ,REAR DOOR ,LH	Bent	1,294.90 FL	*1,294.90 FL
13	1		*HANDLE ASSY ,REAR DOOR OUTSIDE ,LH	Serviceable	97.40 FL	*- FL
14	1		*TAPE BLACK OUT ,NO.1 LH	Necessary	21.90 FL	*21.90 FL
15	1		*TAPE BLACK OUT ,NO.2 LH	Necessary	34.90 FL	*34.90 FL
16	1		*TAPE BLACK OUT ,NO.3 LH	Necessary	15.40 FL	*15.40 FL
17	1		*WEATHERSTRIP ,REAR DOOR ,LH	Serviceable	180.10 FL	*- FL
18	1		*LOCK ASSY ,REAR DOOR W/MOTOR ,LH	Repair	561.90 FL	*- FL
19	1		*REAR WHEEL RIM	Serviceable	1,879.40 FL	*- FL
20	1		*REAR WHEEL RIM COVER	Serviceable	211.50 FL	*- FL
21	1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	*60.00 FS
22	1		*SET REAR BUMPER CLIP	Not Necessary	75.00 FS	*- FS
23	2		*REAR WINDSCREEN SEALANT	Not Necessary	140.00 FS	*- FS
24	1		*WINDSCREEN MOULDING	Not Necessary	180.00 FS	*- FS
25	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	120.00 FS	*- FS
26	1		*SET REAR FENDER LINER CLIP	Not Necessary	40.00 FS	*- FS
27	1		*REAR TYRE 195/65/15	Serviceable	350.00 FS	*- FS
28	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	40.00 FS	*- FS
29	1		*SET ROCKER PANEL MOULDING CLIP	Not Necessary	45.00 FS	*- FS
30	1		*SET TAILLAMP LOWER CLIP	Not Necessary	35.00 FS	*- FS
31	1		*SET TAILLAMP UPPER CLIP	Not Necessary	35.00 FS	*- FS
32	1		*REAR BUMPER PROTECTOR	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,551.90	1,878.90
- List Item Discount on L Items 25.00/25.00% (\$)	2,067.98	454.73

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (\$)	7,483.92	1,424.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST }	New	170.00	60.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR }	New	380.00	0.00
3	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
4	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO TRANSFER OF REAR BIG WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
6	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	400.00
7	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
8	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
9	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
10	TO TRANSFER OF REAR SMALL WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
11	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	660.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
13	TO RUST PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
14	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
Gross Labour Cost (S\$)			14,510.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >