

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006693/KEA3Q2
Date: 16/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993949
Claimant Vehicle No :	SLH4092Z	Insured Vehicle No :	GBK3417E
Date of Loss:	23/06/2020	Nature of Claim:	TP
		Claim No:	9519037356SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH4092Z		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B4034738
Reg. Date:	01/11/2016 (Man. Year: 2016)	Chassis No:	RU11114728
Colour:	Metallic Pearl White	Odometer:	56981 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,911.28	2,911.28	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,090.00	1,500.00	590.00	28.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,001.28	4,411.28	590.00	11.80
Approved Total (Overridden) (S\$)		3,500.00		

(S\$)	5,001.28	3,500.00	1,501.28	30.02
+ GST 7.00/7.00% (S\$)	350.09	245.00	105.09	30.02
Nett Amount (S\$)	5,351.37	3,745.00	1,606.37	30.02
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	25/06/2020		
Date Inspected:	29/06/2020	Inspected At:	City Auto Pte Ltd (Sin Ming) (HQ) Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est Singapore 575643
Estimated Period of Repair:	8.0 days		

Adjuster:	KENNETH KONG	Manager:	Asher Sng Rong Yi
-----------	--------------	----------	-------------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR FENDER	Bent	1,863.60 FL	*1,863.60 FL
2	1		*RH REAR FENDER GARNISH	Dented	192.10 FL	*192.10 FL
3	1		*LH REAR FENDER GARNISH	Dented	192.10 FL	*192.10 FL
4	1		*TAIL LAMP -LH	Cracked	491.50 FL	*491.50 FL
5	1		*REAR BUMPER	Dented / Cut	518.60 FL	*518.60 FL
6	2		*REAR BUMPER LOWER COVER	Buckled / Dented	381.20 FL	*381.20 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,639.10	3,639.10
- List Item Discount on L Items 20.00/20.00% (\$)	727.82	727.82
Total Parts (\$)	2,911.28	2,911.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	COMPUTERISED WHEEL ALIGNMENT	New	60.00	0.00
2	TO REMOVE AND INSTALL REAR QUATER GLASS	New	80.00	0.00
3	TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING ,WELDING ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	850.00	700.00
4	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	1,100.00	800.00
Gross Labour Cost (\$\$)			2,090.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >