



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EL 818K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER CHROME (CONSISTENT)	SCRATCHED	90.00	90.00
1	FRONT BUMPER MOULDING (CONSISTENT)	DENTED	169.00	169.00
1	FRONT BUMPER (CONSISTENT)	BUCKLED / DENTED	1,980.00	1,209.00
1	BONNET GRILLE RIGHT (CONSISTENT)	SERVICEABLE	176.00	-
1	HEADLAMP XENON RIGHT (CONSISTENT)	CUT	3,200.00	2,614.00
	LESS 5% DISCOUNT		-	-204.10
			5,615.00	3,877.90
	<u>SPECIAL NETT ITEMS</u>			
1	NO PLATE (CONSISTENT)(SN)	BENT	50.00	45.00
			50.00	45.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIX NEW PARTS.		300.00	250.00
	TO PUTTY AND SPRAY PAINT ON REAR PANEL AND NEW PARTS.		500.00	300.00
			800.00	550.00
	GRAND TOTAL		6,465.00	4,472.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,550.00

Report Ref No. CC4/ASM20006695/Kba3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.