

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20006705/QTF3E2

Date: 08/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800088992	
Claimant Vehicle No : SKR7221H	Insured Vehicle No :	SMC9395G	
Date of Loss: 23/06/2020	Nature of Claim:	TP	Claim No: 1929940965SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR7221H		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZR491261
Reg. Date:	04/03/2015 (Man. Year: 2015)	Chassis No:	MR053REH104527086
Colour:	White	Odometer:	113812 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,207.83	3,321.45	2,886.38	46.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,430.00	170.00	10.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,807.83	4,751.45	3,056.38	39.15
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	7,807.83	3,800.00	4,007.83	51.33

INSPECTION

Date of Assignment:	25/06/2020		
Date Inspected:	29/06/2020	Inspected At:	Yong Chin Chern Motor Works (HQ) 38 Woodland Industrial Park E1 #05-07 Singapore 757700
Estimated Period of Repair:	4.0 days		

Adjuster: OI SUN PIN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	785.24 FL	*785.24 FL
2	2		*REAR BOOT HINGE	Bent	338.14 FL	*220.00 FL
3	1		*REAR BOOT LOCK	Jammed	375.48 FL	*375.48 FL
4	1		*REAR BOOT WEATHER STRIP	Crumpled	148.60 FL	*148.60 FL
5	1		*REAR BUMPER	Crumpled	689.68 FL	*689.68 FL
6	2		*REAR UPPER L/R RETAINER	Serviceable	172.48 FL	*- FL
7	1		*REAR BUMPER CENTER PAD	Necessary	3.00 FL	*3.00 FL
8	2		*REAR BUMPER L/R FENDER RETAINER	Serviceable	280.62 FL	*- FL
9	2		*REAR BUMPER L/R SEAL	Serviceable	196.06 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	396.97 FL	*396.97 FL
11	2		*REAR L/R BUMPER REINFORCEMENT ARM	Serviceable	179.48 FL	*- FL
12	1		*REAR END PANEL MOULDING	Crumpled	295.36 FL	*295.36 FL
13	1		*REAR BOOT GARNISH	Serviceable	278.90 FL	*- FL
14	1		*REAR END PANEL	Repair	721.60 FL	*- FL
15	1		*REAR SPARE TYRE PANEL	Serviceable	807.90 FL	*- FL
16	2		*REAR L/R FLOOR SIDE PANEL	Serviceable	372.86 FL	*- FL
17	1		*SET BOOT TOYOTA EMBLEM	Necessary	70.86 FL	*70.86 FL
18	1		*SET BOOT ALTIS EMBLEM	Necessary	107.76 FL	*73.84 FL
19	1		*SET BOOT TOYOTA LOGO EMBLEM	Necessary	75.41 FL	*75.41 FL
20	1		*BOOT TAILLAMP LEFT	Serviceable	327.64 FL	*- FL
21	1		*BOOT TAILLAMP RIGHT	Scratched	327.64 FL	*327.64 FL
22	1		*FENDER TAILLAMP LEFT	Serviceable	358.90 FL	*- FL
23	1		*FENDER TAILLAMP RIGHT	Cracked	358.90 FL	*358.90 FL
24	1		*SET REVERSE SENSOR	Shorted	386.72 FS	*386.72 FS
25	20		*BUMPER CLIP	Necessary	26.00 FS	*26.00 FS
26	10		*BOOT CLIP	Necessary	13.00 FS	*13.00 FS
27	1		*TUBS SILICONE SEALANT	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,125.20	4,276.70
- List Item Discount on L Items 25.00/25.00% (\$)	1,917.37	955.25
Total Parts (\$)	6,207.83	3,321.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS / PANEL BEATING	New	600.00	600.00
2	TO APPLY RUST PROOFING ON ADJACENT PANELS	New	100.00	50.00
3	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	800.00	750.00
4	TO REMOVE AND RENEW BUMPER SENSOR (S) WITH CHECK	New	100.00	30.00
			Gross Labour Cost (S\$)	1,430.00
			1,600.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >