

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GST Reg. No. 19-900/190-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	INSURANCE (S) PL	Re	ef:	CS/AGI20006706/Acf3n2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	15/06/2021	
			Co	ode:	AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLX 1087A	Veh. Inspected		GBJ 6345P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10006406	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		05/06/2020	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HIACE	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTFHT02P900249179	Colour		WHITE	
	Odometer	21145 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15	BRIDGESTONE		6 mm	
	L/H Front Tyre	195 R15	BRIDGESTONE		6 mm	
	R/H Rear Tyre	195 R15	BRIDGESTONE		6 mm	
	L/H Rear Tyre	195 R15	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	04/06/2020	Inspection Date		05/06/2020	
	Survey held at	DYNAMIC AUTOWORK PTE LTD				
		8 KAKI BUKIT AVE 4 #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.		Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

18 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: