ESTIMATED ACCIDENT REPAIR COST

POSMI - LKK ANTO,



	11 11110			1	
ACCIDENT TIME REPORTED	16:35hrs	BUS REGISTRATION NUMBER	\$B\$3333	ix	
ACCIDENT DATE	19-Jun-20	BUS TYPE (SD/DD)	DD		
BUS CAPTAIN NAME	WEE HAN CHING	BUS ROUTE NUMBER			
THIRD PARTY CLAIM AGAINST				N	
SECTION 1: PARTS	S & CONSUMABLE ITEMS (MATERIAL COST)				
NO.	Part or Item Description		Quantity	Total Cost	
1	O/S/R PANEL LIGHT CA		1	\$996.22	
2	LAMP REVERSED LED 60	1	\$216.30		
3	SIKAFLEX BLACK		1	\$32.00	
4	REAR ROUND REFLECTOR VOLVO		1	\$9.20	
5	O/S/R ADVERTISMENT STICKER		* SPECIAL NETT *	600 \$700.00	

\$192.76 7% GST PARTS TOTAL COST \$2,946.48

600 \$700.00

\$800.00

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

REAR ENGINE DOOR STICKER

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
TO DISMANTLE & REPLACE DAMAGED PARTS		975 \$1,850.00
TO PERFORM REPAIR WORKS ON REAR ENGINE DOOR		\$650.00
TO REMOVE & REPLACE ADVERTISEMENT STICKERS BY CONTRACTOR	* SPECIAL NETT *	300 \$600.00
	7% GST	\$224.00
	LABOUR TOTAL COST	\$3,424.00

SPRAY PAINTING \$640 PER PANEL LABOUR CHARGES \$650 PER DAY

6

7

PAGE 1

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	
	1

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

			DATE IN	26/6/2020
			DATE & TIME SURVEY	26/6/2020
			DATE OUT	
BUS TYPE (SD / DD)	DD		TOTAL NUMBER OF DAYS	
LOSS OF USE COST			\$2,000.00	

SUMMARY			
SECTION NO.	COST		
1	\$2,946.48		
2	\$3,424.00		
3	-		
4	\$2,000.00		
TOTAL	\$8,370.48		

PAGE 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pasul
Hp 90010068
4 days
26/06/2000 & 1210
Reas after report
include danage paints