



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877 Contact No	Cust No/Name	KCV15407/Ms Lau Wan Heok
	Reg No/Reg Date	SMS2849B / 20/02/2020
	Date In/Mileage	06/07/2020/ 6761
	Chassis No	GF7W0601806
	Engine No	4J11BG2848
	Make/Model	MIT/19MY OUTLANDER 2.0 ELEG (995)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000034	Credit	11/07/2020/ 08:27	DS	218 / MarsLer	47198			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
S	MIPNT88088							280.00
REVERSE SENSOR SET								
S	MIPNT88088							250.00
DIAGNOSTIC / SCANNING								
S	MIPNT88088							80.00
TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS								
S	MIPNT88088							1200.00
TO REPLACE REAR BUMPER,ETC								
-TO REPAIR REAR END PANEL								
-TO REPAIR LHR OTR QTR PANEL								
STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS								
S	MIPNT98088							1260.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS								
X	JJ6410D734RA	FACE,RR BUMPER	1.00	1008.00	0.00	1008.00		
X	JJ6415A090HA	EXTENSION,RR BUMPER	1.00	360.00	0.00	360.00		
X	JJ6512A681	CLIP, RR BUMPER	30.00	6.00	0.00	180.00		
X	JJMR200300	CLIP, RR BUMPER	10.00	4.00	0.00	40.00		
X	JJ6410D336	LH SIDE BRACKET, RR	1.00	12.00	0.00	12.00		
X	JJ7407A317	LH MOULDING, RR BUMP	1.00	106.00	0.00	106.00		
X	JJ7407A647	LH MOULDING,RR WHEEL	1.00	160.00	0.00	160.00		
X	JJ8330B173	RR LH LAMP ASSY, COM	1.00	600.00	0.00	600.00		
Z	NOTES							
ACCIDENT ON 23/06/2020 ALONG TUNNEL OF CTE								
OWNER CLAIMING THIRD PARTY								
REQUIRED REPLACEMENT CAR (CHAN'S)								
TP # SHD3247U TP INS : MS FIRST CAPITAL								
Confirm & accepted by								
Finalization								
Authorized signatory and company stamp								
				Parts	2,466.00			
				Labour	0.00			
				Standard Menu	0.00			
				Specialist Job	3,070.00			
				Others(Lub,etc)	0.00			
				Sundry	0.00			
				Total(w/o GST)	5,536.00			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.