Berveyer Bryan	REF: CS/ MSG 200	067211 Daf3	Special Instruction:
rom (Person): Xi YA		MENT (Office) imbers とんしか	45350.00 Third Parties:
stimated Cost:	Bill to:		Claimant: Con stant Appraisar S
	ar v des	g j	Surveyor:
DTP Re-inspection	Car 7, 7, 0		Workshop: J. L Car Auto Service
o Inspect Vehicle No:	GBE 7476 P	Insured: GBH 12	JK
Workshop m/s J.L.	Car Auro Servicus	_ Tel: 63670790	
	#101-18 Kranji Industria	1 Estata	
licy No: MSIG.1	9.0493.WT	Claim No:59	94502
m Insured:		Excess:	
ake of Veh:		D.O.A. 24.5. 201	19
lient's Record) Rolly	spection: 13. July 2020 11	0.00 a·m	
			H.O.D. Endorsement/Date:
	Person Contacted:		
Date/Time:	Confirmed with Fin	al Fig,da	ys (Red \$/_%; Original_4 days)
Pate/Time:	Submit Final Fig	,days (Red \$	/%; Originaldays)
ate/Time Action/Ins			
GBE 74	The state of the s		
GB4 1	12R - X	•	
Billing to	MSIG but also can mail	to Willy Tay's Cham	bers
401 200 (0)	31 bmilt 4/5 2500/-	-it 4 days of	12. Clad to 2850, 53/1)
Hote:	Tailgate found in	h dendu mark.	at Some offe.
	Most Parts indurale	d as fare sho	~ signs of the not change
	dwing physial re.	inspection and	Ax repair This by Constant
	and VP.	1	, 0 1
	- STM	\\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
ara(1) : Parts four	1 1 1		
u. a(1) . 1 a) ts 10th	id not replaced (To hi	ghlight R or UE	3, LR, Etc)
ara(2) · Comment	c on congicton a. C 1	(D. 1. W. 6	
(-) . Comment	s on consistency of dam	ages (Parts Not Co	nsistent: NC)
	4 Mys Siver - 1	V. F. J. V. V. V. J. V.	
	01171	1.5 day Dr stroke	<u></u>
		5 dry for lan	<u> </u>
	N	3-2 days for s	My Penday.
ara(3) : Nett Valu	P	100000	
- Cylinder Value			le e
Market V	alue :	Incoorded	Fee Charged; Date:
		Inspected/ Evaluated by:	Basic & Add Transport
Salvage 1	Value :	and the second s	Photos
Nett Val	10		Others
	-20		Total
Date/Time W 22	110.000	2) Date/Time	File Return to
) Date/Time	File Pass to	4) Date/Time	File Return to
) Date/Time	File Pass to	6) Date/Time	File Return to

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters Blk 2 Rivervale Link, #09-02 Singapore 545040 Tel/Fax: 6886 1106 Mobile: 9007 5234 Email: constant as@yahoo.com.sg RCB No. 53138015K

Automobile Inspection Report

To: EDL Pte Ltd

c/o Blk 4, Kranji Loop #01-18

Kranji Industrial Estate Singapore 739540

Date

: 19/07/2019

Reference No : CAS/19-07/031

General Information

Registration No. Accident Date

GBE 7476 24/05/2019

Particulars of Damaged Vehicle

Colour

White

Make & Model

: Nissan Cabstar

Engine Capacity

: 2953 cc

Pre-Accident Condition : Good

Mileage (KM)

: 109897

Engine No. Steering

: ZD30009268N : In Order

Chassis No. Registration Date : 17/03/2016

: JN1SC2F24Z0858234

Brake

: In Order

Tyre Condition

Size

Make

Balance

R/H Front Tyre

195R15

MICHELIN

90%

L/H Front Tyre

195R15

MICHELIN

90%

R/H Rear Tyre

165R13 (D)

BRIDGESTONE

90% / 90%

L/H Rear Tyre

165R13 (D)

BRIDGESTONE

90%/90%

Inspection

Repairer

: J. L. Car Auto Service

Blk 4, Kranji Loop #01-18, Kranji Industrial Estate, Singapore 739540

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$9,453.69

: \$5,350.00

Revised Amount Less Excess

300

Nett Total

: \$5,350.00

Remarks

(A) Survey was done of 30/05/2019

(B) Re-survey after repair was done on 18/07/2019

(C) The survey was conducted entirely on WIFHOUT PREJUDICE basis.

(D) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Constant Appraiser Services

Vehicle No : GBE 7476P

Adjustment On Repair Costs And Replacement Of Parts:

Our ref: CAS/19-07/031

/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
		PARTS REPLACEMENT - NETT ITEMS				
1	1pc	Rear tailgate	Dented/Twisted	1,695.50	1,695.50	72
2 lpc 3 3pcs 4 lpc	Rear tailgate lower member	Dented/Twisted Bent Repair	645.50 55.50 2,201.50	645.50 55.50	P	
	Rear tailgate lock pin @ \$18.50				1 P	
	Rear sidegate LH				2	
5	lpc	Rear sidegate lower member LH	Dented/Buckled	878.50	878.50	R
6	5pcs	Rear sidegate lock pin @ \$18.50	Not Necessary	92.50	le.	
7 lpc		Rear sidegate lock hinge LH	Dented/Bent	189.50	189.50	r
		Rear taillamp panel LH	Dented/Twisted	168.40	168.40	-
9	lpc	Rear taillamp LH	Broken	219.80	219.80	L
10	2pcs	Rear tailgate rubber stopper LH @ \$51.20	Missing/Deformed	102.40	102.40	-
11	1pc	Rear tailgate rubber stopper bracket LH	Dented/Twisted	105.00	105.00	L
	2	785 10		6,354.10	4,060.10	
		Less 10% 706-59		(635.41)	(406.01)	
			Sub total	5,718.69	3,654.09	
		PARTS REPLACEMENT – SPECIAL NETT ITEMS				
1	lset	Reverse sensor	Broken	250.00	220,00	L
2	1pc	Rear sticker '70km/h'	Necessary	15.00	12.00	1
	lpc	Rear company wording & advertisement	Necessary	850.00	650.00	L
		LABOUR & MISC. CHARGES	Sub total	6,833.69	4,536.09	
1		To check rear electrical wiring		40.00	20,00	1
2		To remove, renew reverse sensor		80.00	60.00	1
3		To respray undercoating		100.00	60.00	1
4		To respray painting & etc	1012	1,200.00	1,000.00	1
5		Panel beating, remove & replacing above	1540.00	1,200.00	1,000.00	+ 4
		parts	Grand total	9,453.69	6,676.09	1
Recor	mended c	ost of lump sum repair			5,350.00	

312839 4 sags. 4/5 2500/-

Constant Appraiser Services

Vehicle No : GBE 7476P Our ref : CAS/19-07/031

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$5,350.00 on a contractual basis. Under normal circumstances, the repair period would be about 4 (Four) working days.

Yours faithfully,

Constant Appraiser Services

Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

MSAAA

(