

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

· · · · · · · · · · · · · · · · · · ·					
Affiliated to Federation Internationale Des Experts En Automobile					
MSIG INSURANCE (SINGAPORE) PTE LTD Ref : CS/LAW20006721/Dqf3e2					
C/O: WILLY TAY'S CHAMBERS 70 SHENTON WAY #17-02 EON SHENTON SINGAPORE 079118			Date: 04-08-2020		
			Code: MSG		
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	GBH 122R	Veh. Inspected	GBE 7476P	
	Policy No.	MSIG.19.0493.WT	Coverage (\$)	0.00	
	Claim No.	594502	Excess (\$)	0.00	
	Assign From	XI YEN	Assign Date	26/06/2020	
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN CABSTAR	c.c	2953	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JN1SC2F24Z0858234	Colour	WHITE	
	Odometer	137904	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
	L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
	R/H Rear Tyre	165 R13 (D)	BRIDGESTONE	5/5 mm	
	L/H Rear Tyre	165 R13 (D)	BRIDGESTONE	5/5 mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION	REPAIR CONDITION SEE DETAILS.			
5.	General Information				
	Accident Date	24/05/2019	Inspection Date	13/07/2020	
	Survey held at	J.L.CAR AUTO SERVICE			
		BLK 4 KRANJI LOOP #01-18 KRANJI INDUSTRIAL ESTATE SINGAPORE 739540			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				