

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006722/AES3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070005241
Claimant
Vehicle No : GBJ2524R **Insured Vehicle No :** SMS631A
 Date of Loss: 24/06/2020 Nature of Claim: TP Claim No: 1079870738SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ2524R**
 Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2841602
 Reg. Date: 01/03/2019 (Man. Year: 2018) Chassis No: JTFAT35Y90K212578
 Colour: Silver Odometer: 29968 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/75R15 Rear Tyre Size: 155 R12C
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,900.32	2,526.72	4,373.60	63.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,180.00	2,850.00	70.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,930.32	3,706.72	7,223.60	66.09
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	10,930.32	2,900.00	8,030.32	73.47
+ GST 7.00/7.00% (S\$)	765.12	203.00	562.12	73.47
Nett Amount (S\$)	11,695.44	3,103.00	8,592.44	73.47
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		3,532.00		

INSPECTION

Date of Assignment: 26/06/2020
 Date Inspected: 01/07/2020 Inspected At: Dynamic Autowork Pte. Ltd (HQ)
 8 Kaki Bukit Ave 4, #08-09 Premier @
 Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,100.00 FL	*1,100.00 FL
2	1		*TAILGATE STICKER TOYOTA	Necessary	138.10 FL	*138.10 FL
3	4		*TAILGATE HINGE	Bent (2 PCS ONLY)	660.40 FL	*370.20 FL
4	2		*TAILGATE SIDE LOCK	Not Necessary	279.20 FL	*- FL
5	1		*REAR NUMBER PLATE HOLDER	Bent	184.00 FL	*184.00 FL
6	2		*REAR NUMBER PLATE LAMP	Not Necessary	90.00 FL	*- FL
7	2		*TAIL LAMP	Cut	490.00 FL	*490.00 FL
8	2		*TAIL LAMP SUPPORT BRACKET	Not Necessary	370.00 FL	*- FL
9	1		*REAR END PANEL	Dented	910.40 FL	*455.00 FL
10	1		*REAR STICKER DYNA	Necessary	45.00 FL	*45.00 FL
11	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
12	1		*TAIL GATE 70KM/H STICKER	Necessary	40.00 FS	*15.00 FS
13	1		*TAIL GATE 6 PAX STICKER	Necessary	40.00 FS	*15.00 FS
14	1		*REAR END PANEL SEALANT	Not Necessary	200.00 FS	*- FS
15	1		*REAR FLOOR PANEL TOP COVER BOARD (WOODEN)	Not Necessary	2,800.00 FS	*- FS
16	1		*REAR STEP BAR (SPECIAL TYPE)	Bent	350.00 FS	*180.00 FS
17	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,967.10	3,222.30
- List Item Discount on L Items 25.00/25.00% (\$)	1,066.78	695.58
Total Parts (\$)	6,900.32	2,526.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD ,CUT ,ADJUST ,KNOCK	New	1,800.00	600.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX	New	1,600.00	450.00
3	TUFF COAT	New	250.00	50.00
4	WIRING AND BULB CHECK	New	80.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR	New	120.00	50.00
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			4,030.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >