

# Dynamic Autowork Pte.Ltd.

( ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 01.07.20

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBJ2524R**  
 MODEL : TOYOTA DYNA *Achias*  
 DATE OF ACCIDENT : 24.06.20  
 TIME OF ACCIDENT : 16:55HRS

WE APPEND HEREUNDER THE ESTIMATED

### CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,100.00	\$ 1,100.00 ✓
2	TAILGATE STICKER 'TOYOTA' <i>new</i>	1	\$ 138.10	\$ 138.10 ✓
3	TAILGATE HINGE <i>2 pieces bent.</i>	4	\$ 165.10	\$ <del>660.40</del> <i>370.20</i>
4	TAILGATE SIDE LOCK <i>all in</i>	2	\$ 139.60	\$ 279.20 +
5	REAR NUMBER PLATE HOLDER <i>Bent</i>	1	\$ 184.00	\$ 184.00 ✓
6	REAR NUMBER PLATE LAMP <i>all in</i>	2	\$ 45.00	\$ 90.00 +
7	TAIL LAMP <i>cut</i>	2	\$ 245.00	\$ 490.00 ✓
8	TAIL LAMP SUPPORT BRACKET <i>all in</i>	2	\$ 185.00	\$ 370.00 +
9	REAR END PENEL <i>Dented</i>	1	\$ 910.40	\$ <del>910.40</del> <i>455</i>
10	REAR STICKER 'DYNA' <i>new</i>	1	\$ 45.00	\$ 45.00 ✓

*2782.30*

*2086.72*

TOTAL PRICE \$ 4,267.10  
 LESS 25% \$ 1,066.78  
**SUB TOTAL PRICE \$ 3,200.33**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ <del>50.00</del> <i>30</i>
2	TAIL GATE '70KM/H' STICKER <i>free</i>	1	\$ 40.00	\$ <del>40.00</del> <i>15</i>
3	TAIL GATE '6PAX' STICKER	1	\$ 40.00	\$ <del>40.00</del> <i>15</i>
4	REAR END PENEL SEALANT <i>new</i>	1	\$ 200.00	\$ 200.00 +
5	REAR FLOOR PANEL TOP COVER BOARD (WOODEN) <i>all in</i>	1	\$ 2,800.00	\$ 2,800.00 +
6	REAR STEP BAR (SPECIAL TYPE) <i>Bent</i>	1	\$ 350.00	\$ <del>350.00</del> <i>180</i>
7	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ <del>220.00</del> <i>200</i>

*440*

**TOTAL \$ 3,700.00**

### CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ <del>1,800.00</del>	<i>600</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ <del>1,600.00</del>	<i>450</i>

TO : **AIG** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **GBJ2524R**  
 MODEL : **TOYOTA DYNA**  
 DATE OF ACCIDENT : 24.06.20  
 TIME OF ACCIDENT : 16:55HRS

3	TUFF COAT	\$	<del>250.00</del>	50
4	WIRING AND BULB CHECK	\$	<del>80.00</del>	30
5	REMOVE AND REFIX REVERSE SENSOR	\$	<del>120.00</del>	50
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	180.00	X

**TOTAL**                    \$            **4,030.00**      1180

**ESTIMATE REPORT**

TOTAL PARTS COST : \$            6,900.33  
 TOTAL LABOUR COST : \$            4,030.00  
 TOTAL REPAIR COST : \$            10,930.33

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

*ABBY*

SERVICE ADVISOR  
 ABBY  
 HP : 9856 4815

*Adrian Lj  
 r/s 01/07/20  
 04 exp*

*total: 3706.72  
 r/s 2.9K.*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: