

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20006757/UTF3E2

Date: 15/07/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00053492002
Claimant Vehicle No :	SJC6780H	Insured Vehicle No :	SGW4100P
Date of Loss:	27/06/2020	Nature of Claim:	TP
		Claim No:	SNM20D202276/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC6780H	Engine No:	R18A13025610
Make & Model:	HONDA CIVIC, 1.8 (A)	Chassis No:	JHMF16308S213232
Reg. Date:	26/02/2008 (Man. Year: 2007)	Odometer:	221471 km
Colour:	Purple		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,356.40	3,855.52	4,500.88	53.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	2,650.00	1,480.00	35.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,486.40	6,505.52	5,980.88	47.90
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	12,486.40	5,200.00	7,286.40	58.35
+ GST 7.00/7.00% (S\$)	874.05	364.00	510.05	58.35
Nett Amount (S\$)	13,360.45	5,564.00	7,796.45	58.35

INSPECTION

Date of Assignment:	29/06/2020		
Date Inspected:	29/06/2020	Inspected At:	2 Kaki Bukit Ave 2 #01-03
			Repairer : Stytech Auto Pte Ltd (HQ)
Estimated Period of Repair:	7.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jul 2020)

Parts: 143 HONDA CIVIC 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJC6780H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Badly Dented	778.40 F	*610.70 FL
2	1		*REAR BOOTLID HONDA EMBLEM	Necessary	35.60 F	*35.60 FL
3	2		*REAR BOOTLID REFLECTOR (LEFT & RIGHT)	Cracked	409.60 F	*409.60 FL
4	1		*REAR BOOTLID CIVIC PLATE	Necessary	35.10 F	*35.10 FL
5	1		*REAR BOOTLID 1.8 I-VTEC PLATE	Necessary	42.80 F	*42.80 FL
6	1		*REAR BOOTLID LOCK	Twisted	191.80 F	*191.80 FL
7	1		*REAR BOOTLID NUMBER PLATE WITH CASING	Scratched	45.00 FS	*40.00 FS
8	1		*REAR BOOTLID INNER GARNISH CHIPS	Not Necessary	25.00 FS	*- FS
9	2		*REAR TAILLAMP (LEFT & RIGHT)	Cracked	734.80 F	*530.00 FL
10	2		*REAR TAILLAMP BRACKET (LEFT & RIGHT)	Not Necessary	63.60 F	*- FL
11	1		*REAR BUMPER	Distorted	732.90 F	*638.00 FL
12	1		*REAR BUMPER CHIPS	Necessary	30.00 FS	*30.00 FS
13	2		*REAR BUMPER RETAINER (LEFT & RIGHT)	Bent	85.60 F	*41.00 FL
14	1		*REAR END PANEL	Badly Dented	596.80 F	*316.00 FL
15	1		*REAR END PANEL GARNISH	Twisted	95.80 F	*95.80 FL
16	1		*WHEATHER STRIPE	Twisted	283.40 F	*145.00 FL
17	1		*SPARE TYRE CUPBOARD	Warped	158.40 F	*158.40 FL
18	1		*SPARE TYRE PANEL	Crumpled / Buckled	971.40 F	*911.40 FL
19	1		*REAR TAILLAMP PANEL (RIGHT)	Repair	125.70 F	*- FL
20	1		*REAR FENDER (RIGHT)	Repair	984.80 F	*- FL
21	1		*REAR FENDER INNER GARNISH (RIGHT)	Deformed / Twisted	133.20 F	*133.20 FL
22	1		*REAR FENDER INNER GARNISH CHIPS	Not Necessary	25.00 FS	*- FS
23	1		*EXHAUST PIPE CHROME	Dented	659.40 FS	*100.00 FS
24	1		*GLASS RUBBER	Not Necessary	89.60 F	*- FL
25	1		*GLASS SEALANT	Not Necessary	60.00 FS	*- FS
26	1		*PANEL JOINT SEALANT	Necessary	80.00 FS	*50.00 FS
27	1		*SET REVERSE SENCER	Shorted	200.00 FS	*200.00 FS
28	1		*REAR FENDER SIDE CHASSIS PANEL (RIGHT)	Repair	682.70 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,356.40	4,714.40
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	858.88
Total Parts (\$\$)	8,356.40	3,855.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT REAR GLASS	New	150.00	0.00
2	REMOVE & REFIT EXHAUST PIPE	New	80.00	60.00
3	INTERIOR UPHOLSTERY	New	100.00	80.00
4	ANTI RUST PROOFING	New	100.00	80.00
5	CHECK WIRING	New	100.00	30.00
6	PANEL BEATING	New	1,800.00	1,200.00
7	PAINT WORK	New	1,800.00	1,200.00
Gross Labour Cost (S\$)			4,130.00	2,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >