

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20006758/GQF3Q2

Date: 01/12/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : FBQ4082Z	Insured Vehicle No :	SH8551G
Date of Loss: 18/06/2020	Nature of Claim: TP	Claim No: MCT20060176

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ4082Z		
Make & Model:	YAMAHA AEROX GDR155A, 155cc CVT ABS	Engine No:	G3J8E0105182
Reg. Date:	28/09/2019 (Man. Year: 2019)	Chassis No:	MH3SG4640KJ056047
Colour:	Black	Odometer:	0 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70-14	Rear Tyre Size:	150/70-14
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,143.00	4,285.90	5,857.10	57.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	600.00	820.00	57.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	11,563.00	4,885.90	6,677.10	57.75

INSPECTION

Date of Assignment:	29/06/2020	
Date Inspected:	29/06/2020 Inspected At:	Am Motor Werkz (HQ) 50 SERANGOON NORTH AVE 4, #05-10 FIRST CENTRE Singapore 555856
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Nov 2020)	
Parts:	N/A	YAMAHA AEROX GDR155A 155cc CVT ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBQ4082Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHS REAR FAIRING (MATTE BLACK)	Cut	180.00 FL	*60.00 FL
2	1		*LHS CENTRE PANEL (GLOSS BLACK)	Deformed	150.00 FL	*150.00 FL
3	1		*LHS FOOT PLATFORM UNDERCOVER	Cut	150.00 FL	*50.00 FL
4	1		*LHS FRONT SIGNAL FAIRING (OUTER)	Cut	150.00 FL	*140.00 FL
5	1		*RHS FRONT SIGNAL FAIRING (OUTER)	Cracked	150.00 FL	*140.00 FL
6	1		*FRONT V PANEL	Broken	130.00 FL	*90.00 FL
7	1		*RHS FOOT PLATFORM UNDERCOVER	Cut	150.00 FL	*50.00 FL
8	1		*RHS CENTRE PANEL (GLOSS BLACK)	Cut	150.00 FL	*150.00 FL
9	1		*LHS FRONT SIGNAL FAIRING (INNER)	Not Necessary	150.00 FL	*- FL
10	1		*RHS FRONT SIGNAL FAIRING (INNER)	Cracked	150.00 FL	*65.00 FL
11	1		*METER FAIRING COVER (GLOSS BLACK)	Cracked	120.00 FL	*60.00 FL
12	1		*METER FAIRING COVER (MATTE BLACK)	Cracked	120.00 FL	*60.00 FL
13	1		*FRONT MUDGUARD	Cut	120.00 FL	*95.00 FL
14	1		*FRONT INNER SPLASHGUARD	Deformed	180.00 FL	*50.00 FL
15	1		*EXHAUST COVER	Not Necessary	160.00 FL	*- FL
16	1		*RADIATOR COVER	Not Necessary	180.00 FL	*- FL
17	1		*TAILLIGHT FAIRING (CENTRE PIECE)	Broken	130.00 FL	*130.00 FL
18	1		*AIRBOX COVER	Cut	200.00 FL	*200.00 FL
19	1		*SET REAR SIGNAL LIGHT	Cut	220.00 FL	*50.00 FL
20	1		*SET SIDE MIRROR	Broken	220.00 FL	*30.00 FL
21	1		*SET BRAKE LEVER	Broken	180.00 FL	*24.00 FL
22	1		*SET BALANCER	Cut	160.00 FL	*30.00 FL
23	1		*BREMBO MASTER BRAKE PUMP	Distorted	1,550.00 FL	*285.00 FL
24	1		*BREMBO MASTER BRAKE RESERVOIR	Not Necessary	180.00 FL	*- FL
25	1		*BRAKE HOSE LINE	Cut	320.00 FL	*110.00 FL
26	1		*FORK SET	Bent	680.00 FL	*500.00 FL
27	1		*FRONT WHEEL AXLE SHAFT	Cut	80.00 FL	*35.00 FL
28	1		*FRONT WHEEL AXLE NUT	Cut	20.00 FL	*20.00 FL
29	1		*SET PILLION FOOT REST	Cut	120.00 FL	*75.00 FL
30	1		*HANDLEBAR	Bent	180.00 FL	*64.00 FL
31	1		*BRAKE SWITCH	Damaged	120.00 FL	*120.00 FL
32	1		*ABS SENSOR FRONT	Not Necessary	450.00 FL	*- FL
33	1		*FRONT ROTOR	Bent	280.00 FL	*150.00 FL
34	1		*FORK UNDER BRACKET	Bent	450.00 FL	*180.00 FL
35	1		*STEERING CONE BEARING	Necessary	360.00 FL	*90.00 FL
36	1		*HORN	Not Working	50.00 FL	*50.00 FL
37	1		*RHS FRONT LOWER SIGNAL	Cracked	120.00 FL	*38.00 FL
38	1		*RADIATOR	Not Necessary	380.00 FL	*- FL
39	1		*HEADLIGHT	Cracked	850.00 FL	*160.00 FL
40	1		*ECU	Damaged	850.00 FL	*750.00 FL
41	1		*METER	Cracked	680.00 FL	*500.00 FL
42	1		*REAR NUMBER PLATE	Cut	45.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,265.00 4,761.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (S\$)					1,122.00	475.10
Total Parts (S\$)					10,143.00	4,285.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	120.00	50.00
2	TO DIAGNOSE AND RESET FAULT CODE	New	500.00	100.00
3	LABOUR FEE	New	800.00	450.00
Gross Labour Cost (S\$)			1,420.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >