

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006759/AGS3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800038568

Claimant
Vehicle No : SLU9666S **Insured Vehicle No :** SKQ5708P

Date of Loss: 26/06/2020 Nature of Claim: TP Claim No: 3932550363SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU9666S		
Make & Model:	TOYOTA COROLLA AXIO, 1.5 HYBRID D/AIRBAG 2WD (A)	Engine No:	1NZR484043
Reg. Date:	19/12/2017 (Man. Year: 2017)	Chassis No:	NKE1657143052
Colour:	White	Odometer:	88349 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,002.37	3,466.85	4,535.52	56.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,130.00	2,110.00	3,020.00	58.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,132.37	5,576.85	7,555.52	57.53
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	13,132.37	4,400.00	8,732.37	66.50
+ GST 7.00/7.00% (S\$)	919.27	308.00	611.27	66.50
Nett Amount (S\$)	14,051.64	4,708.00	9,343.64	66.50
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,094.45		

INSPECTION

Date of Assignment: 29/06/2020

Date Inspected: 01/07/2020 Inspected At:

Dynamic Autowork Pte. Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @
Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	947.50 FL	*821.00 FL
2	1		*BOOTLID INSULATOR	Not Necessary	168.30 FL	*- FL
3	2		*BOOT LID HINGE	Not Necessary	251.60 FL	*- FL
4	1		*BOOT LID LOCK	Damaged	98.60 FL	*98.60 FL
5	1		*BOOT LID LOWER CATCH	Not Necessary	42.00 FL	*- FL
6	1		*BOOT LID LOGO	Necessary	63.80 FL	*63.80 FL
7	1		*BOOT LID EMBLEM AXIO	Necessary	48.60 FL	*48.60 FL
8	1		*BOOT LID EMBLEM COROLLA	Necessary	47.70 FL	*47.70 FL
9	1		*BOOT LID WEATHERSTRIP	Cut	185.20 FL	*185.20 FL
10	1		*REAR BUMPER	Deformed	1,249.60 FL	*780.00 FL
11	2		*REAR BUMPER REFLECTOR	Not Necessary	117.20 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	191.60 FL	*191.60 FL
13	2		*REAR BUMPER BRACKET	Not Necessary	170.40 FL	*- FL
14	1		*TAIL LAMP	O/s Cracked	1,158.80 FL	*450.00 FL
15	1		*TAIL LAMP LOWER BRACKET	O/s Cracked	117.20 FL	*58.60 FL
16	1		*TAIL LAMP PANEL RH	Not Necessary	245.80 FL	*- FL
17	2		*REAR FENDER INNER COWLING	Not Necessary	159.20 FL	*- FL
18	2		*REAR FENDER INNER TRIM	Not Necessary	659.80 FL	*- FL
19	1		*REAR END PANEL	Dented	682.10 FL	*682.10 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	226.70 FL	*226.70 FL
21	1		*REAR FLOOR PANEL	Repair	762.90 FL	*- FL
22	1		*REAR FLOOR PANEL TOP BOARD	Deformed	461.90 FL	*461.90 FL
23	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
24	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
25	1		*BOOT LID SEALANT	Not Necessary	150.00 FS	*- FS
26	1		*SET BOOTLID OUTER MOULDING CLIP	Not Necessary	30.00 FS	*- FS
27	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
28	1		*BOOT LID EMBLEM HYBRID	Necessary	180.00 FS	*70.00 FS
29	1		*SET TAILLAMP CLIP	Necessary	30.00 FS	*10.00 FS
30	1		*TAIL LAMP PANEL LH SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
32	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
34	1		*REAR END PANEL INSULATION SEAL	Necessary	180.00 FS	*60.00 FS
35	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
36	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
37	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,016.50	4,495.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,014.13	1,028.95
Total Parts (\$\$)	8,002.37	3,466.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,800.00	900.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	900.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	250.00	60.00
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
7	REAR CHASSIS ALIGNMENT	New	250.00	0.00
8	TRANSFER BOOTLID MECHANISM	New	80.00	60.00
9	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
10	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
11	REMOVE AND REFIX FUEL TANK TO FACILIATE FLOOR PANEL REPLACEMENT	New	80.00	0.00
12	REMOVE AND REFIX REVERSE SENSOR	New	120.00	50.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,130.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >