

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20006761/UES3Q2
Date: 17/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100484439
Claimant
Vehicle No : GBG2194A **Insured Vehicle No :** SLG3758Z
 Date of Loss: 22/06/2020 Nature of Claim: TP Claim No: 7500945465SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG2194A**
 Make & Model: TOYOTA HIACE, 3.0 D DX (A) Engine No: 1KD2685660
 Reg. Date: 28/06/2017 (Man. Year: 2017) Chassis No: KDH2010216161
 Colour: Silver Odometer: 83008 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,366.00	4,035.20	3,330.80	45.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,740.00	1,190.00	40.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,296.00	5,775.20	4,520.80	43.91
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	10,296.00	4,600.00	5,696.00	55.32
+ GST 7.00/7.00% (S\$)	720.72	322.00	398.72	55.32
Nett Amount (S\$)	11,016.72	4,922.00	6,094.72	55.32
+ Car Rental (5.0 x S\$80.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,352.00		

INSPECTION

Date of Assignment: 29/06/2020
 Date Inspected: 29/06/2020 Inspected At: Stytech Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2 #02-30, Kaki Bukit
 Autohub
 Singapore 417921
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,718.40 F	*1,718.40 FL
2	1		*REAR TAILGATE VIEW MIRROR	Not Necessary	312.80 F	*- FL
3	1		*REAR TAILGATE GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
4	1		*EMBLEM	Necessary	59.00 F	*59.00 FL
5	1		*HIACE STICKER	Not Necessary	56.00 F	*- FL
6	1		*1250KG STICKER	Not Necessary	48.00 F	*- FL
7	1		*REAR TAILGATE LOCK	Twisted / Jammed	298.40 F	*298.40 FL
8	1		*REAR RIGHT TAILLAMP	Scratched	487.50 F	*366.00 FL
9	1		*REAR RIGHT CORNER PANEL GARNISH	Dented	128.40 F	*128.40 FL
10	1		*REAR RIGHT CORNER PANEL RETAINER	Not Necessary	95.80 F	*- FL
11	1		*REAR END PANEL	Badly Dented	1,275.00 F	*788.10 FL
12	1		*REAR END PANEL STICKER	Not Necessary	95.00 F	*- FL
13	1		*REAR BUMPER	Distorted	687.40 F	*687.40 FL
14	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
15	2		*REAR BUMPER RETAINER (LEFT & RIGHT)	Serviceable	177.00 F	*- FL
16	1		*REAR BUMPER INNER STEP BRACKET	Bent	316.80 F	*316.80 FL
17	1		*RIGHT AIR VENTILATION DUCT	Not Necessary	85.80 F	*- FL
18	1		*TAILLAMP LOWER PANEL O/S	Bent	296.00 F	*296.00 FL
19	1		*REAR EXHAUST PIPE	Repair	583.60 F	*- FL
20	1		*SET REVERSE SENCER	Shorted	200.00 FS	*200.00 FS
21	1		*PANEL JOINT SEALANT	Necessary	60.00 FS	*50.00 FS
22	1		*TAILGATE WEATHERSTRIP	Twisted	295.10 F	*295.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,366.00	5,273.60
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,238.40
Total Parts (S\$)	7,366.00	4,035.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER REAR GLASS	New	120.00	100.00
2	TRANSFER TAILGATE	New	150.00	60.00
3	TRANSFER GLASSREMOVE & FITTING EXHAUST PIPE	New	80.00	0.00
4	CHECK WIRING	New	80.00	20.00
5	ANTI RUST PROOFING	New	100.00	60.00
6	PANEL BEATING	New	1,200.00	800.00
7	PAINT WORK	New	1,200.00	700.00
			Gross Labour Cost (\$\$)	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >