

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2020 Edit Reg		29 Jun 2020 00:00 Edit Adj Rpt	S\$12,000.00 Edit Estimates	S\$12,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured: -, Co. Reg. No.: -									
Vehicle Reg. No.: GBH7503D		Date of Loss: 28/06/2020 00:00 - :59 [21 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / MFL2020D0001191		Policy/Cover Note No.: D19MFL0005549 (Comprehensive)							
		Excess: S\$1,500.00							
Repairer: Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building, 508775 Loyang - Tel: 63416758 / 62840827									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 08/07/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
III_SG (03/07/2020): Alert - Adj Mandate Approved (S\$12000.00) - GBH7503D - Claim Handler: Sundari Na...									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH7503D (MFL2020D0001191)

OD

Jun 28 2020 12:00AM

[-]

Efficient Motor & Engineering Works Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/07/20 10:31	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/06/20 21:02	General View	Load JPG	☒
2	30/06/20 21:02	General View	Load JPG	☒
3	30/06/20 21:02	General View	Load JPG	☒
4	30/06/20 21:02	General View	Load JPG	☒
5	30/06/20 21:02	General View	Load JPG	☒
6	30/06/20 21:02	General View	Load JPG	☒
7	30/06/20 21:02	General View	Load JPG	☒
8	30/06/20 21:02	General View	Load JPG	☒
9	30/06/20 21:02	General View	Load JPG	☒
10	30/06/20 21:02	General View	Load JPG	☒
11	30/06/20 21:02	General View	Load JPG	☒
12	30/06/20 21:02	General View	Load JPG	☒
13	30/06/20 21:02	General View	Load JPG	☒
14	30/06/20 21:02	General View	Load JPG	☒
15	30/06/20 21:02	General View	Load JPG	☒
16	30/06/20 21:02	General View	Load JPG	☒
17	30/06/20 21:02	General View	Load JPG	☒
18	30/06/20 21:02	General View	Load JPG	☒
19	30/06/20 21:02	General View	Load JPG	☒
20	30/06/20 21:02	General View	Load JPG	☒
21	30/06/20 21:02	General View	Load JPG	☒
22	30/06/20 21:02	General View	Load JPG	☒
23	30/06/20 21:02	General View	Load JPG	☒
24	30/06/20 21:02	General View	Load JPG	☒
25	30/06/20 21:02	General View	Load JPG	☒
26	30/06/20 21:02	General View	Load JPG	☒
27	30/06/20 21:02	General View	Load JPG	☒
28	30/06/20 21:02	General View	Load JPG	☒
29	30/06/20 21:02	General View	Load JPG	☒
30	30/06/20 21:02	General View	Load JPG	☒
31	30/06/20 21:02	General View	Load JPG	☒
32	30/06/20 21:02	General View	Load JPG	☒
33	30/06/20 21:02	General View	Load JPG	☒
34	30/06/20 21:02	General View	Load JPG	☒
35	30/06/20 21:02	General View	Load JPG	☒
36	30/06/20 21:02	General View	Load JPG	☒
37	30/06/20 21:02	General View	Load JPG	☒
38	30/06/20 21:02	General View	Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
39	30/06/20 21:02	General View		Load JPG	☒
40	30/06/20 21:02	General View		Load JPG	☒
41	30/06/20 21:02	General View		Load JPG	☒
42	30/06/20 21:02	General View		Load JPG	☒
43	30/06/20 21:02	General View		Load JPG	☒
44	30/06/20 21:02	General View		Load JPG	☒
45	30/06/20 21:02	General View		Load JPG	☒
46	30/06/20 21:02	General View		Load JPG	☒
47	30/06/20 21:02	General View		Load JPG	☒
48	30/06/20 21:02	General View		Load JPG	☒
49	30/06/20 21:02	General View		Load JPG	☒
50	30/06/20 21:02	General View		Load JPG	☒
51	30/06/20 21:02	General View		Load JPG	☒
52	30/06/20 21:02	General View		Load JPG	☒
53	30/06/20 21:02	General View		Load JPG	☒
54	30/06/20 21:02	General View		Load JPG	☒
55	30/06/20 21:02	General View		Load JPG	☒
56	30/06/20 21:02	General View		Load JPG	☒
57	30/06/20 21:02	General View		Load JPG	☒
58	30/06/20 21:02	General View		Load JPG	☒
59	30/06/20 21:02	General View		Load JPG	☒
60	30/06/20 21:02	General View		Load JPG	☒
61	30/06/20 21:02	General View		Load JPG	☒
62	30/06/20 21:02	General View		Load JPG	☒
63	30/06/20 21:02	General View		Load JPG	☒
64	30/06/20 21:02	General View		Load JPG	☒
65	30/06/20 21:02	General View		Load JPG	☒
66	30/06/20 21:02	General View		Load JPG	☒
67	30/06/20 21:02	General View		Load JPG	☒
68	30/06/20 21:02	General View		Load JPG	☒
69	30/06/20 21:02	General View		Load JPG	☒
70	30/06/20 21:02	General View		Load JPG	☒
71	30/06/20 21:02	General View		Load JPG	☒
72	30/06/20 21:02	General View		Load JPG	☒
73	30/06/20 21:02	General View		Load JPG	☒
74	30/06/20 21:02	General View		Load JPG	☒
75	30/06/20 21:02	Odometer Reading		Load JPG	☒
76	30/06/20 21:02	Chassis Number		Load JPG	☒
77	30/06/20 21:02	General View		Load JPG	☒
78	30/06/20 21:02	General View		Load JPG	☒
79	30/06/20 21:02	General View		Load JPG	☒
80	30/06/20 21:02	General View		Load JPG	☒
81	30/06/20 21:02	General View		Load JPG	☒
82	30/06/20 21:02	General View		Load JPG	☒
83	30/06/20 21:02	General View		Load JPG	☒
84	30/06/20 21:02	General View		Load JPG	☒
85	30/06/20 21:02	General View		Load JPG	☒
86	30/06/20 21:02	General View		Load JPG	☒
87	30/06/20 21:02	General View		Load JPG	☒
88	30/06/20 21:02	General View		Load JPG	☒
89	30/06/20 21:02	General View		Load JPG	☒
90	30/06/20 21:02	General View		Load JPG	☒
91	30/06/20 21:02	General View		Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
92	30/06/20 21:02	General View		Load JPG	☒
93	30/06/20 21:02	General View		Load JPG	☒
94	30/06/20 21:02	General View		Load JPG	☒
95	30/06/20 21:02	General View		Load JPG	☒
96	30/06/20 21:02	General View		Load JPG	☒
97	30/06/20 21:02	General View		Load JPG	☒
98	30/06/20 21:02	General View		Load JPG	☒
99	30/06/20 21:02	General View		Load JPG	☒
100	30/06/20 21:02	General View		Load JPG	☒
101	30/06/20 21:02	General View		Load JPG	☒
102	30/06/20 21:02	General View		Load JPG	☒
103	30/06/20 21:02	General View		Load JPG	☒
104	30/06/20 21:02	General View		Load JPG	☒
105	30/06/20 21:02	General View		Load JPG	☒
106	30/06/20 21:02	General View		Load JPG	☒
107	30/06/20 21:02	General View		Load JPG	☒
108	30/06/20 21:02	General View		Load JPG	☒
109	30/06/20 21:02	General View		Load JPG	☒
110	30/06/20 21:02	General View		Load JPG	☒
111	30/06/20 21:02	General View		Load JPG	☒
112	30/06/20 21:02	General View		Load JPG	☒
113	30/06/20 21:02	General View		Load JPG	☒
114	23/07/20 16:42	After Repair Photo		Load JPG	☒
115	23/07/20 16:42	After Repair Photo		Load JPG	☒
116	23/07/20 16:42	After Repair Photo		Load JPG	☒
117	23/07/20 16:42	After Repair Photo		Load JPG	☒
118	23/07/20 16:42	After Repair Photo		Load JPG	☒
119	23/07/20 16:42	After Repair Photo		Load JPG	☒
120	23/07/20 16:42	After Repair Photo		Load JPG	☒
121	23/07/20 16:42	After Repair Photo		Load JPG	☒
122	23/07/20 16:42	After Repair Photo		Load JPG	☒
123	23/07/20 16:42	After Repair Photo		Load JPG	☒
124	23/07/20 16:42	After Repair Photo		Load JPG	☒
125	23/07/20 16:42	After Repair Photo		Load JPG	☒
126	23/07/20 16:42	After Repair Photo		Load JPG	☒
127	23/07/20 16:42	After Repair Photo		Load JPG	☒
128	23/07/20 16:42	After Repair Photo		Load JPG	☒
129	23/07/20 16:42	After Repair Photo		Load JPG	☒
130	23/07/20 16:42	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	30/06/20 08:57	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III20006767/ESF3S2**Date:** 29/07/2020**REFERENCE**

Insured/Claimant: - Policy No: D19MFL0005549
Date of Loss: 28/06/2020 Nature of Claim: OD Claim No: MFL2020D0001191

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH7503D**
Make & Model: NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M) Engine No: YD25426840A
Reg. Date: 19/09/2018 (Man. Year: 2017) Chassis No: JN1MC2E26Z0009130
Colour: White/Blue Odometer: 44342 km
Engine Capacity: 2488 cc
Market Value/New Car Price: S\$48,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: 4 mm Rear Left Side: 4 mm
Front Right Side: 4 mm Rear Right Side: 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,092.00	18,742.00	6,350.00	25.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,070.00	5,030.00	2,040.00	28.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,162.00	23,772.00	8,390.00	26.09
Approved Total (Overridden) (S\$)		12,000.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	30,662.00	10,500.00	20,162.00	65.76
+ GST 7.00/7.00% (S\$)	2,146.34	735.00	1,411.34	65.76
Nett Amount (S\$)	32,808.34	11,235.00	21,573.34	65.76

INSPECTION

Date of Assignment: 29/06/2020
Date Inspected: 30/06/2020 Inspected At: Efficient Motor & Engineering Works Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang Enterprise Building
Singapore 508775
Estimated Period of Repair: 20.0 days

Adjuster: CHEN TSUE YEE**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$48,000.00-LTA REIMBURSEMENT VALUE: \$22,995.00=NETT VALUE: \$25,005.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Jul 2020)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5MT 5DR (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH7503D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Broken	280.00 F	*280.00 F
2	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Broken	75.00 F	*75.00 F
3	1		*FRONT FOG LAMP LH (WCP)	Not Necessary	230.00 F	*- F
4	1		*FRONT FOG LAMP GARNISH LH (WCP)	Cut	65.00 F	*65.00 F
5	1		*FRONT GRILLE (WCP)	Broken	260.00 F	*260.00 F
6	1		*HEADLAMP ASSY LH (WCP)	Cut	195.00 F	*195.00 F
7	1		*FRONT CORNER PANEL LH (WCP)	Repair	195.00 F	*- F
8	1		*FRONT FENDER LOWER PROTECTOR LH (WCP)	Crushed	50.00 F	*50.00 F
9	1		*DASHBOARD (WCP)	Cut	600.00 F	*600.00 F
10	1		*GLOVE BOX ASSY TOP (WCP)	Not Necessary	125.00 F	*- F
11	1		*FRONT WINDSCREEN GLASS (WCP)	Broken	650.00 F	*650.00 F
12	2		*FRONT WINDSCREEN GLASS MOULDING (WCP)	Necessary	100.00 F	*100.00 F
13	1		*ROOF PANEL (WCP)	Dented	2,200.00 F	*2,200.00 F
14	1		*ROOF HEAD LINING FRONT (WCP)	Crushed	1,785.00 F	*1,785.00 F
15	1		*FRONT PILLAR HANDLE GRIP ASSIST LH (WCP)	Not Necessary	65.00 F	*- F
16	1		*FRONT SIDE PANEL OUTER LH (WCP)	Dented	850.00 F	*850.00 F
17	1		*FRONT PILLAR INNER UPPER PANEL LH (WCP)	Dented	200.00 F	*200.00 F
18	1		*FRONT STEP ASSY LH (WCP)	Dented	80.00 F	*80.00 F
19	1		*FRONT STEP GARNISH LH (WCP)	Missing	45.00 F	*45.00 F
20	1		*FRONT FENDER MUDGUARD LH (WCP)	Not Necessary	75.00 F	*- F
21	1		*FRONT PILLAR BODY WEATHERSTRIP (WCP)	Torn	60.00 F	*60.00 F
22	1		*FRONT PILLAR UPPER GARNISH LH (WCP)	Broken	70.00 F	*70.00 F
23	1		*FRONT DOOR SCUFF PLATE LH (WCP)	Not Necessary	95.00 F	*- F
24	1		*FRONT DOOR LH (WCP)	Dented	620.00 F	*620.00 F
25	2		*FRONT DOOR HINGE LH (WCP)	Bent	80.00 F	*80.00 F
26	1		*FRONT DOOR GLASS LH (WCP)	Broken	390.00 F	*390.00 F
27	1		*FRONT DOOR SIDE MIRROR LH (WCP)	Missing	380.00 F	*380.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT DOOR CHECKER LH (WCP)	Not Necessary	35.00 F	*- F
29	1		*FRONT DOOR WEATHERSTRIP (WCP)	Torn	70.00 F	*70.00 F
30	1		*FRONT DOOR RUBBER LOWER LH (WCP)	Torn	20.00 F	*20.00 F
31	1		*FRONT DOOR WINDOW REGULATOR LH (WCP)	Not Necessary	120.00 F	*- F
32	1		*FRONT DOOR WINDOW MOTOR LH (WCP)	Not Necessary	220.00 F	*- F
33	1		*FRONT DOOR LOCK LH (WCP)	Jammed	105.00 F	*105.00 F
34	1		*FRONT DOOR RUN CHANNEL LH (WCP)	Cut	65.00 F	*65.00 F
35	1		*FRONT DOOR OUTER MOULDING LH (WCP)	Missing	100.00 F	*100.00 F
36	1		*FRONT DOOR INNER MOULDING LH (WCP)	Cut	65.00 F	*65.00 F
37	1		*FRONT DOOR INNER TRIM BOARD (WCP)	Cut	400.00 F	*400.00 F
38	1		*FRONT DOOR OUTER HANDLE LH (WCP)	Cut	45.00 F	*45.00 F
39	2		*STEEL WHEEL LH (WCP)	Not Necessary	500.00 F	*- F
40	1		*FRONT SHOCK ABSORBER LH (WCP)	Not Necessary	90.00 F	*- F
41	1		*FRONT WHEEL BEARING RH (WCP)	Not Necessary	140.00 F	*- F
42	1		*FRONT WHEEL HUB RH (WCP)	Not Necessary	350.00 F	*- F
43	1		*FRONT LOWER ARM RH (WCP)	Not Necessary	140.00 F	*- F
44	1		*FRONT LOWER ARM BALL JOINT RH (WCP)	Not Necessary	65.00 F	*- F
45	1		*FRONT KNUCKLE ARM RH (WCP)	Not Necessary	300.00 F	*- F
46	1		*FRONT UPPER ARM RH (WCP)	Not Necessary	195.00 F	*- F
47	1		*FRONT LH DOOR SPEAKER (WCP)	Not Necessary	180.00 F	*- F
48	1		*WASHER TANK (WCP)	Not Necessary	155.00 F	*- F
49	1		*ROOF HEADLINING REAR (WCP)	Crushed	1,500.00 F	*1,500.00 F
50	1		*CENTER PILLAR OUTER LH (WCP)	Repair	850.00 F	*- F
51	1		*REAR SIDE PANEL OUTER LH (WCP)	Dented	950.00 F	*950.00 F
52	1		*REAR SIDE PANEL OUTER UPPER LH (WCP)	Dented	300.00 F	*300.00 F
53	1		*REAR SIDE PANEL INNER LH (WCP)	Dented	950.00 F	*950.00 F
54	1		*REAR PILLAR BACK REINFORCEMENT (WCP)	Dented	250.00 F	*250.00 F
55	1		*REAR ROOF RAIL BRACE PANEL LH (WCP)	Dented	150.00 F	*150.00 F
56	1		*SLIDING DOOR LH (WCP)	Dented	750.00 F	*750.00 F
57	1		*SLIDING DOOR RAIL GUIDE LH (WCP)	Not Necessary	380.00 F	*- F
58	1		*SLIDING DOOR WEATHERSTRIP LH (WCP)	Not Necessary	95.00 F	*- F
59	1		*SLIDING DOOR ROLLER UPPER LH (WCP)	Not Necessary	100.00 F	*- F
60	1		*SLIDING DOOR ROLLER LOWER LH (WCP)	Not Necessary	150.00 F	*- F
61	1		*SLIDING DOOR LOCK LH (WCP)	Not Necessary	110.00 F	*- F
62	1		*TAIL LAMP LH (WCP)	Broken	110.00 F	*110.00 F
63	1		*REAR BUMPER (WCP)	Broken	250.00 F	*250.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
64	1		*TAILGATE (WCP)	Dented	1,100.00 F	*1,100.00 F
65	2		*TAILGATE HINGE (WCP)	Not Necessary	80.00 F	*- F
66	1		*TAILGATE WEATHERSTRIP (WCP)	Not Necessary	100.00 F	*- F
67	1		*REAR SHOCK ABSORBER (WCP)	Not Necessary	110.00 F	*- F
68	1		*REAR AXLE BEARING LH (WCP)	Not Necessary	150.00 F	*- F
69	1		*REAR RAIL ROOF (WCP)	Dented	120.00 F	*120.00 F
70	1		*REAR FENDER MUDGUARD LH (WCP)	Crushed	85.00 F	*85.00 F
71	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
72	1		*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
73	1		*SET FRONT DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*20.00 FS
74	1		*FRONT DOOR CO. REG. STICKER	Necessary	30.00 FS	*30.00 FS
75	1		*COOLANT & AIRCON GAS	Necessary	100.00 FS	*100.00 FS
76	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
77	1		*WINDSCREEN INNER SEAL	Necessary	30.00 FS	*30.00 FS
78	1		*WINDSCREEN ERP BRACKET	Necessary	20.00 FS	*20.00 FS
79	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*30.00 FS
80	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
81	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
82	1		*70 KM/H STICKER	Necessary	30.00 FS	*20.00 FS
83	1		*PAN PACIFIC METAL PLATE	Necessary	80.00 FS	*50.00 FS
84	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
85	2		*TYRE FRONT / REAR LH	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	22,910.00	17,100.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	2,182.00	1,642.00
Total Parts (\$\$)	25,092.00	18,742.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE.	New	70.00	60.00
2	TO CUT & WELD DAMAGED PANELS LH PORTION, ROOF PANEL, SIDE PANEL, TO PANEL BEAT & ALIGN SLIDE DOOR, INNER PANELS & REPLACE DAMAGED PARTS.	New	2,500.00	2,200.00
3	TO APPLY ANTI-RUST COAT AND TUFF KOTE AFFECTED AREAS.	New	250.00	50.00
4	TO CHECK AND RECTIFY LIGHTING & WIRING HARNESS.	New	150.00	30.00
5	TO PUTTY & SPRAY PAINTING FRONT & LH PORTIONS, ROOF & AFFECTED PARTS.	New	2,000.00	1,500.00
6	TO TRANSFER FRONT DOOR & SLIDING DOOR COMPONENTS.	New	200.00	80.00
7	TO REMOVE & REPLACE LH FRONT UNDERCARRIAGE.	New	250.00	200.00
8	TO REMOVE & REPLACE LH REAR UNDERCARRIAGE.	New	150.00	0.00
9	TO DO TYRE BALANCING & WHEEL ALIGNMENT.	New	100.00	60.00
10	TO REMOVE AND REFIT DASHBOARD, SEAT, CARPET, INNER TRIMS TO FACILITATE REPAIR.	New	250.00	100.00
11	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS.	New	150.00	120.00
12	TO REMOVE & REFIT ROOF LINING, INNER TRIM TO ASSIST WORK LOAD	New	250.00	80.00
13	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	New	100.00	30.00
14	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	150.00	120.00
15	TO DO ART WORK COMPANY STICKER.	New	500.00	400.00
Gross Labour Cost (\$\$)			7,070.00	5,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >