



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2007547
INV Date 11/11/2020
Reference CC6/CTI20006778/Ues3s2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SMQ 2213X
Insured Veh. GBD 387P
Claim No. SNM20D202272/C02
Policy No. DMCVSN3079331900
Accident Date 25/06/2020
Inspection Date 29/06/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20006778/Ues3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 11-11-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 387P	Veh. Inspected	SMQ 2213X
Policy No.	DMCVSN3079331900	Coverage (\$)	0.00
Claim No.	SNM20D202272/C02	Excess (\$)	0.00
Assign From		Assign Date	29/06/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER PREMIUM (A)	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZSU600091295	Colour	WHITE
Odometer	56361	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R18	PIRELLI	6 mm
L/H Front Tyre	235/55 R18	PIRELLI	6 mm
R/H Rear Tyre	235/55 R18	PIRELLI	6 mm
L/H Rear Tyre	235/55 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/06/2020	Inspection Date	29/06/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 2213X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN	NOT NECESSARY	1,488.10	-
1	REAR WINDSCREEN MOULDING	NECESSARY	188.20	113.10
1	TAILGATE	DENTED / BENT	1,866.10	1,712.05
1	TAILGATE OUTER GARNISH	NOT NECESSARY	981.00	-
1	TAILGATE REAR LOGO	NOT NECESSARY	85.00	-
2	TAILGATE REFLECTORS @ \$785.10	NOT NECESSARY	1,570.20	-
1	TAILGATE 'HARRIER' EMBLEM	NECESSARY	105.00	68.10
1	TAILGATE INNER LOCK	DENTED / SHORTED	499.20	459.10
1	TAILGATE INNER TRIM	NOT NECESSARY	699.10	-
1	SET TAILGATE INNER TRIM CLIPS	NOT NECESSARY	50.00	-
2	TAILGATE DAMPERS @ \$455.00	NOT NECESSARY	910.00	-
1	REAR BUMPER	DENTED / DEFORMED	1,245.10	955.10
2	REAR BUMPER SIDE RETAINERS @ \$125.00	N/S BENT	250.00	88.10
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER REFLECTORS @ \$145.00	NOT NECESSARY	290.00	-
1	REAR BUMPER SKIRTING	NOT FITTED	1,050.00	-
2	REAR BUMPER PDC SENSORS @ \$313.00	SHORTED	626.00	450.00
1	REAR ANTENNA SENSOR	CRACKED	488.10	399.00
1	REAR END PANEL	DENTED / BENT	831.00	803.10
1	REAR END PANEL TOP GARNISH	TWISTED	540.50	360.89
1	REAR FLOOR PANEL	NOT NECESSARY	1,166.00	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	988.10	-
2	REAR FENDERS @ \$1245.00	NOT NECESSARY	2,490.00	-
2	REAR FENDER INNER TRIM BOARDS @ \$799.10	NOT NECESSARY	1,598.20	-
1	REAR AIR VENT N/S	NOT NECESSARY	88.90	-
2	TAILLAMPS @ \$1045.00	NOT NECESSARY	2,090.00	-
1	REAR BUMPER SPONGE	TORN	188.50	188.50
1	REAR EXHAUST	NOT NECESSARY	995.90	-
1	TAILGATE WEATHERSTRIP	TWISTED	412.10	341.65

Report Ref No. CC6/CTI20006778/Ues3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-	-1,497.17
			23,830.30	4,491.52
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR REVERSE CAMERA (SN)	NOT NECESSARY	450.00	-
1	REAR BUMPER TOP CHROME MOULDING (SN)	BENT	500.00	350.00
			1,050.00	440.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	30.00
	TO DISMANTLE & REPLACING REAR PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO TRANSFER TAILGATE COMPONENTS.		120.00	60.00
	TO SPRAY RUST PROOFING.		150.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.		1,800.00	680.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	900.00
			4,450.00	1,980.00
GRAND TOTAL			29,330.30	6,911.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,500.00

Report Ref No. CC6/CTI20006778/Ues3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.