

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20006784/T1RA3Q2
Date: 18/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800072346
Claimant Vehicle No :	SHC8991B	Insured Vehicle No :	SMA7927X
Date of Loss:	26/06/2020	Nature of Claim:	TP
		Claim No:	2561821630SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8991B		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDFU528055
Reg. Date:	19/05/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU089827
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,270.50	952.40	318.10	25.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	670.00	510.00	160.00	23.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,940.50	1,462.40	478.10	24.64
Approved Total (Overridden) (S\$)		1,150.00		

(S\$)	1,940.50	1,150.00	790.50	40.74
+ GST 7.00/7.00% (S\$)	135.84	80.50	55.34	40.74
Nett Amount (S\$)	2,076.34	1,230.50	845.84	40.74
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$55.34/day) (S\$)		221.36		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,659.35		

INSPECTION

Date of Assignment: 29/06/2020

Date Inspected: 29/06/2020

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,106.00 FL	*1,106.00 FL
2	1		*REAR BUMPER UNDER COVER	Repair	228.00 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REVERSE SENSOR	Not Necessary	135.70 FS	*- FS
5	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS
					Sub Total (\$)	1,541.70
					- List Item Discount on L Items 20.00/20.00% (\$)	225.60
					Total Parts (\$)	952.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAYPAINT CHARGE	New	250.00	200.00
3	R/I REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			670.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >