

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20006785/APA3Q2

Date: 08/09/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2020-00006363

Claimant
Vehicle No : SJE2935U **Insured Vehicle No :** SKT6234S

Date of Loss: 27/06/2020 Nature of Claim: TP Claim No: 1202000018713

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE2935U	Engine No:	3ZZ4756910
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106106010
Reg. Date:	21/04/2008 (Man. Year: 2008)	Odometer:	210001 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,315.87	3,987.22	3,328.65	45.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,740.00	2,200.00	3,540.00	61.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,055.87	6,187.22	6,868.65	52.61
Approved Total (Overridden) (\$\$)		4,800.00		
(\$\$)	13,055.87	4,800.00	8,255.87	63.23
+ GST 7.00/7.00% (\$\$)	913.91	336.00	577.91	63.23
Nett Amount (\$\$)	13,969.78	5,136.00	8,833.78	63.23
+ Loss of Use (9.0 x S\$60.00/day) (\$\$)		540.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		5,683.45		
Global Sum Settlement (\$\$)		5,600.00		

INSPECTION

Date of Assignment: 29/06/2020

Date Inspected: 29/06/2020 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE2935U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	520.00 FL	*520.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	130.00 FL	*130.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Dented	365.00 FL	*365.00 FL
4	1		*FRONT BUMPER LOWER GRILLE	Cracked	130.00 FL	*130.00 FL
5	1		*FRONT GRILLE	Cracked	311.20 FL	*311.20 FL
6	1		*FRONT GRILLE LOGO	Necessary	55.20 FL	*55.20 FL
7	2		*HEADLAMP	Not Necessary	860.00 FL	*- FL
8	1		*FRONT SUPPORT PANEL	Not Necessary	1,985.00 FL	*- FL
9	1		*BOOTLID	Dented	769.60 FL	*769.60 FL
10	1		*BOOTLID EMBLEM 1.6	Necessary	44.00 FL	*44.00 FL
11	1		*BOOTLID EMBLEM COROLA	Necessary	36.00 FL	*36.00 FL
12	1		*BOOTLID EMBLEM ALTIS	Necessary	35.00 FL	*35.00 FL
13	2		*BOOTLID HINGE	Not Necessary	157.20 FL	*- FL
14	1		*BOOTLID TOP LOCK	Damaged	79.00 FL	*79.00 FL
15	1		*BOOTLID LOWER LOCK	Not Necessary	42.00 FL	*- FL
16	1		*BOOTLID WEATHERSTRIP	Cut	157.00 FL	*157.00 FL
17	1		*BOOTLID REFLECTOR	O/S Cracked	280.00 FL	*140.00 FL
18	1		*REAR BUMPER	Distorted	563.00 FL	*563.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	116.00 FL	*116.00 FL
20	2		*REAR BUMPER REFLECTOR	Not Necessary	176.00 FL	*- FL
21	1		*REAR BUMPER BRACKET	O/S Dented	206.00 FL	*103.00 FL
22	1		*REAR END REINFORCEMENT BAR WITH SPONGE	Cracked	211.30 FL	*211.30 FL
23	1		*TAILLAMP	O/S Cracked	750.00 FL	*375.00 FL
24	2		*TAILLAMP PANEL	Repair	360.00 FL	*- FL
25	1		*REAR END PANEL	Dented	530.00 FL	*530.00 FL
26	1		*REAR END PANEL TOP GARNISH	Deformed	126.00 FL	*126.00 FL
27	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
28	1		*SET FRONT BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
29	1		*SET FRONT GRILLE CLIP	Necessary	20.00 FS	*20.00 FS
30	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
31	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
32	1		*SET TAILLAMP CLIPS	Necessary	20.00 FS	*10.00 FS
33	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
34	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
35	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,564.50	5,186.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,248.63	1,199.08
Total Parts (\$\$)	7,315.87	3,987.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,000.00	200.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	200.00
3	WIRING CHECK	New	150.00	30.00
4	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	800.00
5	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
6	TUFF COAT	New	350.00	60.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
8	TRANFER BOOTLID MECHANISM	New	80.00	60.00
9	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
Gross Labour Cost (\$\$)			5,740.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >