

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20006787/APA3Q2

Date: 06/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070087677

Claimant
Vehicle No : SMN905L **Insured Vehicle No :** SLC2761R

Date of Loss: 29/06/2020 Nature of Claim: TP Claim No: 9381240677SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SMN905L | Engine No: | CHZC27357 |
| Make & Model: | AUDI A3, 999cc TFSI S TRONIC (LED) (A) | Chassis No: | WAUZZZ8V0K1024973 |
| Reg. Date: | 24/07/2019 (Man. Year: 2019) | Odometer: | 17538 km |
| Colour: | Grey | | |
| Engine Capacity: | 999 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Bridgestone 6 mm | Rear Left Side: | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 4,310.00 | 2,486.00 | 1,824.00 | 42.32 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 8,502.00 | 3,852.00 | 4,650.00 | 54.69 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 12,812.00 | 6,338.00 | 6,474.00 | 50.53 |
| + GST 7.00/7.00% (\$\$) | 896.84 | 443.66 | 453.18 | 50.53 |
| Nett Amount (\$\$) | 13,708.84 | 6,781.66 | 6,927.18 | 50.53 |
| + Loss of Use (6.0 x S\$60.00/day) (\$\$) | | 360.00 | | |
| + Doc/Search Fee (\$\$) | | 2.00 | | |
| Nett Liability (\$\$) | | 7,143.66 | | |

INSPECTION

Date of Assignment: 29/06/2020

Date Inspected: 29/06/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|--|---------------|-------------|--------------|
| 1 | 1 | *REAR BUMPER | Deformed | 1,851.00 FS | *1,480.80 FS |
| 2 | 4 | *REAR BUMPER STICKY PAD | Not Necessary | 22.00 FS | *- FS |
| 3 | 1 | *REAR BUMPER FIXING PARTS | Not Necessary | 182.00 FS | *- FS |
| 4 | 2 | *REAR BUMPER GUIDE SECTION -LH/RH | Not Necessary | 30.00 FS | *- FS |
| 5 | 2 | *REAR BUMPER LOCKING MECHANISM | Not Necessary | 55.00 FS | *- FS |
| 6 | 1 | *REAR BUMPER SPOILER -LH | Cut | 223.00 FS | *178.40 FS |
| 7 | 2 | *REAR LIGHT REFLECTOR -LH/RH | Not Necessary | 78.00 FS | *- FS |
| 8 | 1 | *REAR BUMPER SIDE REINFORCEMENT BEAM | Not Necessary | 538.00 FS | *- FS |
| 9 | 1 | *REAR BUMPER BRACKET -LH | Necessary | 26.00 FS | *20.80 FS |
| 10 | 1 | *REAR BUMPER BRACKET -RH | Necessary | 27.00 FS | *21.60 FS |
| 11 | 2 | *REAR PARKING AID SENSOR -INNER /OUTER (NPA) | Not Necessary | 0.00 FS | *- FS |
| 12 | 4 | *REAR PARKING AID SEAL RING | Not Necessary | 14.00 FS | *- FS |
| 13 | 1 | *AUDI EMBLEM | Not Necessary | 117.00 FS | *- FS |
| 14 | 1 | *A3 INSCRIPTION | Not Necessary | 90.00 FS | *- FS |
| 15 | 1 | *PACKING ADHESIVE | Not Necessary | 18.00 FS | *- FS |
| 16 | 1 | *SUNDRIES | Not Necessary | 200.00 FS | *- FS |
| 17 | 1 | *REAR END PANELLING OUTER | Dented | 339.00 FS | *284.40 FS |
| 18 | 1 | *ACRYLIN SEALANT | Necessary | 180.00 FS | *180.00 FS |
| 19 | 1 | *CAVITY WAX | Necessary | 140.00 FS | *140.00 FS |
| 20 | 1 | *STONE CHIP | Necessary | 180.00 FS | *180.00 FS |

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,310.00** **2,486.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL AND AUDIO EQUIPMENT | New | 480.00 | 480.00 |
| 2 | TO CUT OUT AND WELD REAR END PANELLING OUTER | New | 2,800.00 | 1,000.00 |
| 3 | TO RESPRAY REAR END PANELLING OUTER | New | 1,000.00 | 550.00 |
| 4 | TO REAPPLY PAINT COATING (BY OWNER) | New | 350.00 | 300.00 |
| 5 | TO REMOVE AND TRANSFER REAR PARKING AID .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE | New | 280.00 | 280.00 |
| 6 | TO DISMANTLE AND RENEW REAR BUMPER .TO REPAIR REAR LID .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED | New | 1,400.00 | 500.00 |
| 7 | TO RESPRAY REAR BUMPER AND REAR LID | New | 2,000.00 | 550.00 |
| 8 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| Gross Labour Cost (S\$) | | | 8,502.00 | 3,852.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >