

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20006790/ADA3Q2

Date: 26/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700051065

Claimant
Vehicle No : SME3401B **Insured Vehicle No :** SGS8328U

Date of Loss: 28/06/2020 Nature of Claim: TP Claim No: 6998037244SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME3401B	Engine No:	G4FGJU274634
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU764518
Reg. Date:	27/09/2018 (Man. Year: 2018)	Odometer:	36469 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,838.90	12,553.04	7,285.86	36.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,790.00	4,140.00	3,650.00	46.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,628.90	16,693.04	10,935.86	39.58
Approved Total (Overridden) (S\$)		13,300.00		
(S\$)	27,628.90	13,300.00	14,328.90	51.86
+ GST 7.00/7.00% (S\$)	1,934.02	931.00	1,003.02	51.86
Nett Amount (S\$)	29,562.92	14,231.00	15,331.92	51.86
+ Loss of Use (17.0 x S\$80.00/day) (S\$)		1,360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		15,598.45		
Global Sum Settlement (S\$)		15,500.00		

INSPECTION

Date of Assignment: 29/06/2020

Date Inspected: 29/06/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,782.00 F	*1,782.00 FL
2	2		*REAR BOOT LID HINGE	Bent	168.60 F	*168.60 FL
3	1		*REAR BOOT LID EMBLEM LOGO	Necessary	28.80 F	*28.80 FL
4	1		*REAR BOOT LID ELANTRA LOGO	Necessary	38.50 F	*38.50 FL
5	1		*REAR BOOT LID S LOGO	Necessary	22.80 F	*22.80 FL
6	2		*REAR BOOT LID SIDE REFLECTOR	Cracked	705.60 F	*705.60 FL
7	1		*REAR BOOT LID CAMERA	Damaged	680.00 FS	*400.00 FS
8	1		*REAR BOOT LID NUMBER PLATE	Bent	50.00 F	*50.00 FL
9	2		*REAR BOOT LID NUMBER PLATE LAMP	Cracked	62.00 F	*62.00 FL
10	1		*REAR BOOT LID LOCK	Damaged	116.20 F	*116.20 FL
11	1		*REAR BOOT LID WEATHERSTRIP	Cut	80.60 F	*80.60 FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Crumpled	349.00 F	*195.80 FL
13	8		*REAR BOOT LID INNER TRIM BOARD CLIP	Necessary	52.00 F	*30.00 FL
14	1		*REAR BOOT LID TOP SPOILER	Deformed	680.00 FS	*450.00 FS
15	2		*REAR TAIL LAMP	Cracked	1,172.00 F	*1,172.00 FL
16	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
17	2		*REAR TAIL LAMP LOWER BRACKET	Not Necessary	56.00 F	*- FL
18	2		*REAR TAIL LAMP PANEL	Dented	414.00 F	*414.00 FL
19	1		*REAR BUMPER	Distorted	585.00 F	*585.00 FL
20	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
21	2		*REAR BUMPER SIDE RETAINER	Necessary	80.00 F	*80.00 FL
22	2		*REAR BUMPER SIDE REFLECTOR	Cut	116.00 F	*116.00 FL
23	1		*REAR BUMPER LOWER	Distorted	850.00 FS	*500.00 FS
24	1		*REAR BUMPER REINFORCEMENT	Distorted	328.00 F	*328.00 FL
25	2		*REAR BUMPER REINFORCEMENT BRACKET	Damaged	68.00 F	*68.00 FL
26	5		*REAR BUMPER REINFORCEMENT TOP & LOWER BRACKET	Damaged	180.00 F	*180.00 FL
27	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
28	1		*REAR END PANEL	Distorted	545.00 F	*545.00 FL
29	1		*REAR END PANEL TOP GARNISH	Deformed	105.00 F	*105.00 FL
30	1		*REAR END PANEL LOWER SENSOR	Damaged	260.00 F	*182.20 FL
31	2		*REAR FENDER	Buckled	3,537.20 F	*3,537.20 FL
32	1		*REAR L/H FENDER INNER PANEL	Not Necessary	899.00 F	*- FL
33	2		*REAR FENDER INNER TRIM BOARD	Torn	574.00 F	*574.00 FL
34	16		*REAR FENDER INNER TRIM BOARD CLIP	Necessary	104.00 F	*60.00 FL
35	1		*REAR FENDER COWLING	N/S Torn	379.00 F	*189.50 FL
36	16		*REAR FENDER COWLING CLIP	Necessary	104.00 F	*20.00 FL
37	1		*REAR FENDER AIR DUCT	N/S Cracked	72.00 F	*36.00 FL
38	1		*REAR SPARE TYRE PANEL	Buckled	789.00 F	*789.00 FL
39	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	225.00 F	*225.00 FL
40	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Necessary	450.00 FS	*200.00 FS
41	1		*REAR EXHAUST	Bent	798.30 F	*695.00 FL
42	2		*REAR EXHAUST MOUNTING	Not Necessary	110.00 F	*- FL
43	1		*REAR CENTRE EXHAUST	Not Necessary	886.30 F	*- FL
44	1		*REAR WINDSCREEN	Not Necessary	599.00 F	*- FL
45	1		*REAR WINDSCREEN SEAL	Necessary	105.00 F	*105.00 FL
46	1		*REAR WINDSCREEN MOULDING	Necessary	155.00 F	*155.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	19,838.90	15,253.80
				- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	2,700.76
				Total Parts (S\$)	19,838.90	12,553.04
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
2	GUM	New	50.00	50.00
3	TO REMOVE & REFIT PETROL TANK	New	280.00	80.00
4	TO REMOVE & REFIT CUSHION ,TRIM BOARD & BODYKIT	New	380.00	100.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE & REFIT REVERSE CAMERA	New	180.00	50.00
7	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	80.00
8	TO CHECK WIRING	New	100.00	30.00
9	TOWING FEE	New	150.00	60.00
10	TUFF KOTE	New	150.00	120.00
11	PANEL BEATING	New	3,500.00	1,900.00
12	SPRAY PAINTING	New	2,400.00	1,500.00
Gross Labour Cost (\$\$)			7,790.00	4,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >