Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20006792/R1BA3Q2

Date: 11/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SFZ821P

Insured Vehicle No: SHD3212U Vehicle No:

Date of Loss: Nature of Claim: ΤP 28/06/2020 Claim No: MCT20060332

DESCRIPTION & IDENTIFICATION OF VEHICLE

SFZ821P Reg No:

Make & Model: BMW X1 SDRIVE18I, 1.5 LED NAV (A) Engine No: 38245458B38B15A Chassis No: Reg. Date: 29/10/2018 (Man. Year: 2018) WBAJG120403G76761

Colour: Odometer: 11637 km Black

Engine Capacity: 1499 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Yes Footbrake (Serviceable): General Condition: Steering (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Front Right Side: Rear Right Side: Pirelli 6 mm Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,420.05	2,235.85	1,184.20	34.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,494.00	5,739.00	755.00	11.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,914.05	7,974.85	1,939.20	19.56
+ GST 7.00/7.00% (S\$)	693.98	558.24	135.74	19.56
Nett Amount (S\$)	10,608.03	8,533.09	2,074.94	19.56
+ Loss of Use (1.0	x S\$60.00/day) (S\$)	60.00		
L Cor Dontal /4 0 v CC400 00/day	7 000/ CCT\ /CC\	429.00		

+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$) 428.00

Nett Liability (S\$) 9,021.09

INSPECTION

Date of Assignment: 20/07/2020

20/07/2020 Inspected At: Performance Motors Limited Date Inspected:

(Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair: 5.0 days Adjuster Report Page 2 of 4

Adjuster: MOHD RASUL Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2020)		
Parts:	M1-SUV	BMW X1 SDRIVE18I 1.5 LED NAV (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	le: (Unsubmitted, no print-code for SFZ821P)			
Validity:	Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TYRE	Not Necessary	500.00 FS	*- FS
2	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
3	1		*ALLOY RIM 7.5X17 V SPK 560	Scratched	814.00 FS	*814.00 FS
4	1		*REAR LH BUMPER MOUNT	Serviceable	161.40 FS	*- FS
5	1		*RR BUMPER LH CORNER MOUNTING	Serviceable	142.65 FS	*- FS
6	1		*REAR BUMPER PANEL PRIMED	Scratched	903.40 FS	*903.40 FS
7	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Scratched	265.65 FS	*265.65 FS
8	1		*FRT LH MOULDING ROCKER PANEL	Serviceable	79.95 FS	*- FS
9	1		*REAR LH MOULDING ROCKER PANEL	Serviceable	64.55 FS	*- FS
10	1		*LH SIDE SKIRT TRIM (BASIS)	Serviceable	235.65 FS	*- FS
11	1		*REAR LH WHEEL ARCH TRIM	Scratched	151.80 FS	*151.80 FS
12	15		*EXPANDING RIVET BLACK	Necessary	21.00 FS	*21.00 FS
F=Fra	anchise	part. S=Spc	Nett.			
				Total Parts (S\$)	3,420.05	2,235.85

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPLACE BUMPER REAR COVER ,SIDE SILL TRIM AND ATTACHMENTS TO REPAIR REAR LEFT SIDE PANEL	New	3,400.00	2,550.00
2	TO SPRAY PAINT BUMPER REAR COVER ,REAR LEFT SIDE PANEL AND WHEELARCH TRIM	New	2,292.00	2,508.00
3	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
4	TO REPLACE WHEEL RIM LEFT REAR INCLUDING BALANCING	New	94.00	80.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
	Gross Labour Cost (S\$)		6,494.00	5,739.00
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >