

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20006798/KSF3Q2

**Date:** 30/10/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNA00010232002	
<b>Claimant Vehicle No :</b> GBD5355Z	<b>Insured Vehicle No :</b> GBD6508T	
Date of Loss: 23/06/2020	Nature of Claim: TP	Claim No: SNM20D202246/C02/TAYHP

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBD5355Z</b>	
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No: ZD30342334K
Reg. Date:	28/11/2014 (Man. Year: 2014)	Chassis No: JN1SC2F24Z0856526
Colour:	Pink	Odometer: 275929 km
Engine Capacity:	2953 cc	
Market Value/New Car Price:	N/A	
Sum Insured (\$):	<b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Delium 8 mm	Rear Left Side:	West Lake 3/3 mm
Front Right Side:	Delium 8 mm	Rear Right Side:	West Lake 3/3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,105.00	1,105.00	0.00	0.00
Miscellaneous Items	1,820.00	1,720.00	100.00	5.49
Labour	1,720.00	1,830.00	-110.00	-6.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$)</b>	<b>4,645.00</b>	<b>4,655.00</b>	<b>-10.00</b>	<b>-0.22</b>
<b>Approved Total (Overridden) (\$)</b>		<b>3,700.00</b>		
<b>(\$)</b>	4,645.00	3,700.00	945.00	20.34
<b>+ GST 7.00/7.00% (\$)</b>	325.15	259.00	66.15	20.34
<b>Nett Amount (\$)</b>	<b>4,970.15</b>	<b>3,959.00</b>	<b>1,011.15</b>	<b>20.34</b>

### INSPECTION

Date of Assignment:	04/07/2020 Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	03/07/2020 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 30 Oct 2020)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBD5355Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT RH DOOR	Bent	780.00 F	*780.00 F
2	1		*1 PC FRT RH WHEEL GARNISH MUDGUARD	Dented / Cut	195.00 F	*195.00 F
3	1		*1 PC RADIATOR SPARE TANK	Mtg Distorted	40.00 F	*40.00 F
4	1		*1 PC FRT RH DOOR OUTER HANDLE	Cut	90.00 F	*90.00 F
					<b>Total Parts (S\$)</b>	<b>1,105.00 1,105.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	1 PC FREEZER BOX RH SIDE DOOR (BENT / CRACKED)	1,800.00	1,700.00
2	1	1 PC FRT RH DOOR COY STICKER (NECESSARY)	20.00	20.00
<b>Sub Total (\$\$)</b>			<b>1,820.00</b>	<b>1,720.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REWRITE ADVERTISEMENT	New	800.00	650.00
2	REMOVE & REFIX FRT RH DOOR,TRANSFER DOORS ATTACHMENT,FRT RH MUDGUARD,RADIATOR SPARE TANK	New	380.00	320.00
3	PUTTY & RESPRAY ON FRT RH DOOR,FREEZER BOX FRT RH PILLAR,RH DOOR	New	480.00	400.00
4	REMOVE & REFIX FRT RH DOOR GLASS	New	60.00	60.00
5	TO FIBERGLASS REPAIR ON FREEZER BOX RH SIDE PANEL DAMAGED AREA AND MAKE GOOD	New	-	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,720.00</b>	<b>1,830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >