

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 8489S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE (CONSISTENT)	TO REPAIR SEE LABOUR	1,952.00	-
1	TAIL GATE SUBARU EMBLEM (CONSISTENT)	NECESSARY	98.00	68.00
1	TAIL GATE AWD EMBLEM (CONSISTENT)	NECESSARY	72.00	58.00
1	TAIL GATE FORESTER EMBLEM (CONSISTENT)	NECESSARY	98.00	60.00
1	TAIL GATE CENTRE BADGE (CONSISTENT)	NOT NECESSARY	84.00	-
1	TAIL GATE SYMMETRICAL EMBLEM (CONSISTENT)	NECESSARY	58.00	58.00
1	TAIL GATE INNER LOCK MECHANISM (CONSISTENT)	NOT NECESSARY	320.00	-
1	TAIL GATE INNER LOCK CATCH (CONSISTENT)	NOT NECESSARY	92.00	-
2	TAIL GATE DAMPERS (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	TAIL GATE INNER TRIM BOARD (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	TAIL GATE LOCK ACTUATOR (CONSISTENT)	NOT NECESSARY	498.00	-
1	TAIL GATE WIPER MOTOR (CONSISTENT) (NPA)	NOT NECESSARY	-	-
1	TAIL GATE WIPER BLADE (CONSISTENT) (NPA)	NOT NECESSARY	-	-
1	REAR BOOT EDGE WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	325.00	-
1	REAR WINDSCREEN MOULDING (CONSISTENT)	NOT NECESSARY	62.70	-
1	LHS TAIL LAMP (CONSISTENT)	CRACKED	752.00	455.00
1	REAR BUMPER (CONSISTENT)	DENTED	1,248.00	945.20
2	REAR BUMPER SIDE RETAINER RH & LH (CONSISTENT)	NOT NECESSARY	198.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	DENTED	798.00	320.60
1	REAR BUMPER TOW COVER (CONSISTENT)	DEFORMED	72.00	20.00
1	REAR BUMPER LOWER COVER (CONSISTENT)	NO SUCH PARTS	982.00	-
2	REAR BUMPER REFLECTOR @\$92.00 (CONSISTENT)	NOT NECESSARY	184.00	-
1	REAR END PANEL (CONSISTENT)	DENTED	782.00	425.30
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	325.00	-
	LESS 20% DISCOUNT		-1,800.14	-
	LESS 50% DISCOUNT		-	-1,205.05
			7,200.56	1,205.05
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	280.00	200.00
1	REVERSE CAMERA (SN) (CONSISTENT) (NPA)	NOT NECESSARY	-	-

Report Ref No. CC4/ASM20006803/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR BUMPER TOP MAT (CHROME PLATE) (SN) (CONSISTENT)	BENT	220.00	220.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	120.00	50.00
1	TAIL GATE INNER TRIM BOARD CLIPS (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	60.00	40.00
1	TAIL GATE TOP SPOILER (SN) (CONSISTENT) (NPA)	NOT NECESSARY	-	-
			840.00	510.00
	LABOUR			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF TAIL GATE .		1,200.00	600.00
	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS.		800.00	750.00
	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION .		180.00	20.00
	TO REMOVE/REFIT INNER TRIMS ,FITTINGS ,GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR .		150.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	140.00	-
	TO REMOVE AND REPLACE REVERSE SENSORS AND REFIX REVERSE CAMERA AND CHECK FOR PROPER FUNCTION .		150.00	50.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		120.00	30.00
			-	-
			-	-
			-	-
			2,740.00	1,510.00
	GRAND TOTAL		10,780.56	3,225.05

RECOMMENDED COST OF LUMP SUM REPAIRS	3,200.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM20006803/Upa3q2





Report Ref No. CC4/ASM20006803/Upa3q2

CHUA KANG SENG
Licensed Appraiser