

not Authorized
hall

30/6/20

1/5 * 3200 / 5 days.

Page No. 1

VEHICLE NO. SLZ 8489S

SUBARU FORESTER

Take photo After repair

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Tail Gate		12 1952.00	X
1	Tail Gate SUBARU Emblem		neu 98.00	68
1	Tail Gate AWD Emblem		neu 72.00	58
1	Tail Gate FORESTER emblem		neu 98.00	60
1	Tail Gate centre badge		neu 84.00	X
1	Tail Gate SYMMETRICAL emblem		neu 58.00	✓
1	Tail Gate Inner Lock Mechanism		11 320.00	X
1	Tail Gate inner lock catch		11 92.00	X
2	Tail Gate dampers	REFIX	11 0.00	X
1	Tail Gate inner trim board	REFIX	11 0.00	X
1	Tail Gate lock actuator		11 498.00	X
1	Tail Gate wiper motor	REFIX	11 0.00	X
1	Tail Gate wiper blade	REFIX	11 0.00	X
1	Rear boot edge weatherstrip		11 325.00	X
1	Rear Windscreen Moulding		11 62.70	X
1	LHS Tail Lamp		neu 752.00	455.00
1	Rear Bumper		neu 1248.00	945.00
2	Rear Bumper Side Retainer RH & LH		11 198.00	X
1	Rear Bumper Reinforcement		neu 798.00	320.60
1	Rear Bumper tow cover		neu 72.00	20.00
1	Rear Bumper lower cover		neu 982.00	X
2	Rear Bumper reflector @92.00		11 184.00	X
1	Rear End Panel		neu 782.00	425.30
1	Rear End Panel top garnish		11 325.00	X
			9000.70	
less 20%			1800.14	20%
			7200.56	50%
<u>SPECIAL NETT ITEMS</u>				
1	Reverse sensor		1set should 280.00	200
1	Reverse camera	REFIX	11 0.00	X
1	Rear Windscreen Sealant		11 100.00	X
1	Rear bumper top mat (chrome plate)		1set 220.00	✓
1	Rear End panel sealant		neu 120.00	50
1	Tail Gate inner trim board clips		11 60.00	X
1	Rear bumper clips		neu 60.00	40
1	Tail Gate top spoiler	REFIX	11 0.00	X
TOTAL PARTS			8040.56	

P-2410.1

50%

P-1205.25

S-N 510.00

L-1510.00

3225.05

VEHICLE NO. SLZ 8489S SUBARU FORESTER

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1200.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	800.00	750
3	To remove, refix wiring system at accident damaged areas and check for proper function	180.00	20
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	150.00	60
5	To remove and refix rear windscreen	140.00	11X
6	To remove and replace reverse sensors and refix reverse camera and check for proper function	150.00	50
7	To perform anti-rust treatment on affected areas	120.00	30
	Labour Total :	2740.00	
	TOTAL (PARTS & LABOUR):	10780.56	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: