

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 5006B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	DEFORMED	1,106.00	1,106.00
2	REAR BUMPER BRACKET SIDE LH / RH @\$35.60	NOT NECESSARY	71.20	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER COVER	TO REPAIR SEE LABOUR	228.00	-
1	BOOTLID CRDI PLATE	NOT NECESSARY	27.90	-
1	BOOTLID I-40 PLATE	NOT NECESSARY	21.10	-
	LESS 20% DISCOUNT		-295.24	-225.60
			1,180.96	902.40
<u>SPECIAL NETT ITEMS</u>				
1	BOOTLID COMFORT LOGO (SN)	NOT NECESSARY	30.00	-
1	BOOTLID COMFORT TEL NO (SN)	NOT NECESSARY	30.00	-
1	REVERSE SENSOR (SN)	NOT WORKING	135.70	135.70
			195.70	135.70
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER UNDER COVER.		540.00	280.00
	SPRAY PAINTING CHARGE.		400.00	200.00
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	CHECK LIGHTING.		60.00	30.00
			1,120.00	540.00
GRAND TOTAL			2,496.66	1,578.10

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,250.00
---	--	--	-----------------

Report Ref No. NS/INC20006813/T1qf3e2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.