

ASS. REC. BY: Taufik

REF:

ALG ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

CO / TP / WS / TP RES / CO RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Sumen

Veh No: SHC 780X Yr Regn: 2015 / Aug.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Myndu 140 c.c. 1685

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 683032 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM HLB4 / UM6 4077168

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / \$Rim / STD A/Rim or

Tyre Size: F: 205 / 60 R16

R: 2 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A.

D.O.I.

29/6/20

Survey held at

Comfatdelgar Leguina

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roottop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Rep. Formet: _____

Lump Sum / L.B.I. (\$