



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2005843
INV Date 26/08/2020
Reference CC4/FCI20006822/Uda3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. FBH 3071J
Insured Veh. SHA 9340J
Claim No. D20002582MFSH
Policy No. D-20094921MFSH
Accident Date 26/06/2020
Inspection Date 30/06/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20006822/Uda3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-08-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9340J	Veh. Inspected	FBH 3071J
Policy No.	D-20094921MFSH	Coverage (\$)	0.00
Claim No.	D20002582MFSH	Excess (\$)	0.00
Assign From	ERIC	Assign Date	30/06/2020

2. Vehicle Particulars & Condition

Make & Model	YAMAHA YBR 125	c.c	124
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	LBPKE1789D0014310	Colour	BLUE
Odometer	4921	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	2.75-18	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	3.00-18	PIRELLI	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	26/06/2020	Inspection Date	30/06/2020
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 3071J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BAR HANDLE	BENT	75.00	75.00
1	BOX SIDE (GIVI) E21N W/BASE-BLACK	BROKEN	378.00	378.00
1	BRACKET MUDGUARD FRONT	TO REPAIR SEE LABOUR	27.00	-
1	BRACKET UNDER FORK	BENT	192.00	192.00
2	BUSH SWINGARM (METAL) @\$5.00	NOT NECESSARY	10.00	-
2	BUSH SWINGARM (METAL) @\$5.00	NOT NECESSARY	10.00	-
2	BUSH SWINGARM (RUBBER)@\$13.00	NOT NECESSARY	26.00	-
1	COVER TANK SIDE LH (GREY)	CRACKED	128.00	128.00
1	COWLING FRONT (BLUE)	BROKEN	143.00	143.00
1	GRIP HANDLE SET (GPR) F2	TORN	15.00	15.00
1	HEADLAMP ASSY	BROKEN	159.00	159.00
1	LEVER BRAKE (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	20.00	-
1	LEVER CLUTCH	BROKEN	20.00	20.00
1	METER ASSY	CUT	283.00	283.00
1	MIRROR LH	CUT	38.00	38.00
1	MIRROR RH	NOT NECESSARY	38.00	-
1	MUDUGARD FRONT (BLACK)	BROKEN	128.00	128.00
1	PLATE FRONT COWLING	TO REPAIR SEE LABOUR	28.00	-
2	RUBBER FOOTREST FRONT @\$16.00	TORN	32.00	32.00
1	SET STEERING CONE	NECESSARY	72.00	72.00
1	SWING ARM	NOT NECESSARY	147.00	-
	LESS 10% DISCOUNT		-	-166.30
			1,969.00	1,496.70
<u>SPECIAL NETT ITEMS</u>				
1	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT (SN)	NECESSARY	20.00	10.00
			20.00	10.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TRANSPORT CHARGES . LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.INCLUSIVE OF THE REPAIR OF BRACKET MUDGUARD FRONT AND PLATE FRONT COWLING .		56.00 552.00 608.00	35.00 300.00 335.00
	GRAND TOTAL		2,597.00	1,841.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,450.00

Report Ref No. CC4/FCI20006822/Uda3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBH 3071J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBH 3071J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

