

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20006829/KDA3Q2

**Date:** 28/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900161653

**Claimant**  
**Vehicle No :** SKH7431X **Insured Vehicle No :** SMP2500Y

Date of Loss: 28/06/2020 Nature of Claim: TP Claim No: 7861942911SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKH7431X</b>	Engine No:	CTH004409
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI 1623Q5 (A)	Chassis No:	WVWZZZ16ZDM021302
Reg. Date:	11/01/2013 (Man. Year: 2012)	Odometer:	194719 km
Colour:	Metallic Silver		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,381.64	1,954.95	2,426.69	55.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	485.00	1,115.00	69.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,981.64</b>	<b>2,439.95</b>	<b>3,541.69</b>	<b>59.21</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,950.00</b>		
<b>(\$\$)</b>	5,981.64	1,950.00	4,031.64	67.40
<b>+ GST 7.00/7.00% (\$\$)</b>	418.71	136.50	282.21	67.40
<b>Nett Amount (\$\$)</b>	<b>6,400.35</b>	<b>2,086.50</b>	<b>4,313.85</b>	<b>67.40</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (\$\$)</b>		240.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>2,328.50</b>		

### INSPECTION

Date of Assignment: 30/06/2020

Date Inspected: 30/06/2020 Inspected At:

Kgc Workshop Pte Ltd (AMK)  
14 Ang Mo Kio Street 63, Blk B  
Singapore 569116

Estimated Period of Repair: 3.0 days

---

**Adjuster:** KENNETH KONG**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Dented	1,388.75 FL	*1,268.37 FL
2	2		*REAR BUMPER RETAINER	Serviceable	220.80 FL	*- FL
3	1		*REAR BUMPER SPOILER	Mtg Cracked	686.75 FL	*626.02 FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	606.50 FL	*- FL
5	1		*LHS TAILLAMP	Serviceable	388.85 FL	*- FL
6	1		*LHS REAR BUMPER REFLECTOR LIGHT	Serviceable	66.55 FL	*- FL
7	1		*RHS REAR BUMPER REFLECTOR LIGHT	Serviceable	66.55 FL	*- FL
8	1		*REAR EXHAUST PIPE	Repair	1,054.85 FL	*- FL
9	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
10	1		*NO PLATE WITH CASING	Serviceable	50.00 FS	*- FS
11	1		*SET REVERSE SENSOR	Dented	250.00 FS	*200.00 FS
					<b>Sub Total (\$\$)</b>	<b>4,829.60      2,144.39</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>447.96      189.44</b>
					<b>Total Parts (\$\$)</b>	<b>4,381.64      1,954.95</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE,REPLACE,CUT,WELD,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS,INCLUSIVE OF REPLACEMENT PARTS	New	600.00	200.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS	New	600.00	220.00
3	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	100.00	15.00
4	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	100.00	0.00
5	REMOVE AND INSTALL REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE AND REFIT EXHAUST PIPE	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,600.00</b>	<b>485.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >