

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006836/KGA3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900163205

Claimant
Vehicle No : SMS3899A **Insured Vehicle No :** SJK2564A

Date of Loss: 28/06/2020 Nature of Claim: TP Claim No: 2296146642SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS3899A		
Make & Model:	HONDA ODYSSEY HYBRID ABSOLUTE, 2.0 CVT (A)	Engine No:	LFA1914357
Reg. Date:	29/10/2019 (Man. Year: 2019)	Chassis No:	RC41164321
Colour:	Metallic Pearl Blue	Odometer:	11036 km
Engine Capacity:	1993 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	225/45Z R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,756.00	1,862.96	6,893.04	78.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,910.00	1,220.00	2,690.00	68.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,666.00	3,082.96	9,583.04	75.66
Approved Total (Overridden) (\$\$)		2,450.00		
(\$\$)	12,666.00	2,450.00	10,216.00	80.66
+ GST 7.00/7.00% (\$\$)	886.62	171.50	715.12	80.66
Nett Amount (\$\$)	13,552.62	2,621.50	10,931.12	80.66
+ Car Rental (5.0 x S\$128.40/day) (\$\$)		642.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		3,265.50		
Global Sum Settlement (\$\$)		3,250.00		

INSPECTION

Date of Assignment: 30/06/2020

Date Inspected: 27/07/2020 Inspected At:

MBM Wheelpower Pte Ltd (HQ)
160 Sin Ming Drive #06-02, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,700.00 FL	*1,193.00 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
3	1		*TAILGATE WEATHERSTRIPE	Serviceable	200.00 FL	*- FL
4	1		*TAILGATE SPOILER GARNISH ASSY	Serviceable	1,300.00 FL	*- FL
5	1		*TAILGATE MOLDING ASSY ,RR.LICENSE GARNISH -TOP	Serviceable	400.00 FL	*- FL
6	1		*TAILGATE MOLDING ASSY ,RR.LICENSE GARNISH -LOWER	Serviceable	300.00 FL	*- FL
7	1		*TAILGATE EMBLEM H LOGO	Necessary	50.00 FL	*50.00 FL
8	1		*TAILGATE EMBLEM ODYSSEY	Necessary	80.00 FL	*80.00 FL
9	1		*TAILGATE EMBLEM ABSOLUTE	Necessary	100.00 FL	*100.00 FL
10	1		*TAILGATE EMBLEM HYBRID	Necessary	150.00 FL	*102.00 FL
11	1		*REAR BUMPER	Dented / Buckled	1,500.00 FL	*583.70 FL
12	1		*REAR BUMPER GARNISH LH	Serviceable	150.00 FL	*- FL
13	1		*REAR BUMPER GARNISH RH	Serviceable	150.00 FL	*- FL
14	1		*REAR BUMPER SPOILER ASSY ,R.RR. SIDE	Serviceable	150.00 FL	*- FL
15	1		*REAR BUMPER REFLECTOR LH	Serviceable	70.00 FL	*- FL
16	1		*REAR BUMPER REFLECTOR RH	Serviceable	70.00 FL	*- FL
17	10		*REAR BUMPER RIVET	Necessary	50.00 FL	*50.00 FL
18	1		*REAR BUMPER SENSOR	Serviceable	500.00 FL	*- FL
19	1		*TAILLIGHT ASSY ,R	Serviceable	1,200.00 FL	*- FL
20	1		*REAR LIGHT ASSY ,R.LID	Serviceable	600.00 FL	*- FL
21	1		*TAILLIGHT ASSY .L	Serviceable	1,200.00 FL	*- FL
22	1		*REAR LIGHT ASSY ,L.LID	Serviceable	600.00 FL	*- FL
23	1		*REAR LIGHT ASSY ,LICENSE	Serviceable	80.00 FL	*- FL
24	1		*NUMBER PLATE & HOLDER	Serviceable	50.00 FS	*- FS
25	1		*BODY SEALANT	Serviceable	50.00 FS	*- FS
26	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,900.00	2,318.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,144.00	455.74
Total Parts (\$\$)	8,756.00	1,862.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS ,INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,600.00	450.00
2	TO DISMANTLE & TRANSFER TAILGATE FITTINGS & MECHANISM TO NEW TAILGATE	New	60.00	60.00
3	TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	New	50.00	0.00
4	TO REMOVE & REPLACE REAR WINDSCREEN	New	150.00	120.00
5	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	120.00	20.00
6	TO REMOVE & REPLACE BUMPER SENSORS	New	40.00	40.00
7	TO REALIGN EXHAUST PIPE	New	40.00	0.00
8	TO APPLY ANTI RUST COATING	New	250.00	30.00
9	TO SPRAY PAINTING ON THE AFFECTED AREAS	New	1,600.00	500.00
Gross Labour Cost (\$\$)			3,910.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >