

ASS. REC. BY:

REF:

A/G / 20006836/kk

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

MBM

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

201.5%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMP 3899A

Yr Regn:

10, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey

c.c.

1993

Colour

M.P. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

11036

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RC4

1164321

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

28/6/20

D.O.I.

27/7/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/8 11:15pm @ 2450h. Confirmed

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SJK2564A

OUR REF.: SMS3899A

TO: AIG Asia Pacific Insurance Pte Ltd

CC:

FAX:

ESTIMATE FOR VEHICLE NO.: SMS3899A

DATE: 29/6/2020

FROM: Lee Shirley

FAX: 64525333

CONTACT: 86865188

MAKE & MODEL: HONDA ODYSSEY ABSOLUTE
7-SEATER 2.0 CVT

CHASSIS NO.: RC41164321

ENGINE NO.: H41287502

YEAR MADE: 2019

ACCIDENT DATE: 28 June 2020

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAILGATE → 1193.00	PR	1	\$ 1,700.00 ✓
2	TAILGATE WINDSCREEN MOULDING	PR	1	\$ 120.00 ✓
3	TAILGATE WEATHERSTRIPE	PR	1	\$ 200.00 X
4	TAILGATE SPOILER GARNISH ASSY	PR	1	\$ 1,300.00 X
5	TAILGATE MOLDING ASSY., RR. LICENSE GARNISH - TOP	PR	1	\$ 400.00 X
6	TAILGATE MOLDING ASSY., RR. LICENSE GARNISH - LOWER	PR	1	\$ 300.00 X
7	TAILGATE EMBLEM "H" LOGO	PR	1	\$ 50.00 ✓
8	TAILGATE EMBLEM "ODYSSEY"	PR	1	\$ 80.00 ✓
9	TAILGATE EMBLEM "ABSOLUTE"	PR	1	\$ 100.00 ✓
10	TAILGATE EMBLEM "HYBRID" 102	PR	1	\$ 150.00 ✓
11	REAR BUMPER → 583.70	PR	1	\$ 1,500.00 ✓
12	REAR BUMPER GARNISH LH	PR	1	\$ 150.00 X
13	REAR BUMPER GARNISH RH	PR	1	\$ 150.00 X
14	REAR BUMPER SPOILER ASSY., R. RR. SIDE	PR	1	\$ 150.00 X
15	REAR BUMPER REFLECTOR LH	PR	1	\$ 70.00 X
16	REAR BUMPER REFLECTOR RH	PR	1	\$ 70.00 X
17	REAR BUMPER RIVET	PR	10	\$ 50.00 ✓
18	REAR BUMPER SENSOR	PR	1	\$ 500.00 X ✓
19	TAILLIGHT ASSY., R	PR	1	\$ 1,200.00 X
20	REAR LIGHT ASSY., R. LID	PR	1	\$ 600.00 X
21	TAILLIGHT ASSY., L.	PR	1	\$ 1,200.00 X
22	REAR LIGHT ASSY., L. LID	PR	1	\$ 600.00 X
23	REAR LIGHT ASSY, LICENSE	PR	1	\$ 80.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL: \$ 10,720.00
LESS 20%: \$ (2,144.00)
PARTS TOTAL: \$ 8,576.00

MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-02

SIN MING AUTOCITY

SINGAPORE 575722

t 6262 8888 f 6452 5333

COMPANY REG. NO.: 200204110W

SPECIAL NETT

NUMBER PLATE & HOLDER
 BODY SEALANT
 WINDSCREEN SEALANT

<i>Sn</i>	1	\$	<i>X</i>	50.00
<i>Sn</i>	1	\$	<i>X</i>	50.00
<i>Sn</i>	1	\$	<i>401n</i>	80.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$	<i>4501</i>	1,600.00
----	-------------	----------

TO DISMANTLE & TRANSFER TAILGATE FITTINGS & MECHANISM TO NEW TAILGATE

\$	<i>✓</i>	60.00
----	----------	-------

TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR

<i>nn</i>	\$	<i>X</i>	50.00
-----------	----	----------	-------

TO REMOVE & REPLACE REAR WINDSCREEN

\$	<i>1201</i>	150.00
----	-------------	--------

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$	<i>201</i>	120.00
----	------------	--------

TO REMOVE & REPLACE BUMPER SENSORS

\$	<i>✓</i>	40.00
----	----------	-------

TO REALIGN EXHAUST PIPE

<i>nn</i>	\$	<i>X</i>	40.00
-----------	----	----------	-------

TO APPLY ANTI RUST COATING

\$	<i>301</i>	250.00
----	------------	--------

TO SPRAY PAINT ON THE AFFECTED AREAS

\$	<i>5001</i>	1,600.00
----	-------------	----------

Total:	\$	12,666.00
--------	----	-----------

7% GST:	\$	886.62
---------	----	--------

Grand Total:	\$	13,552.62
--------------	----	-----------

MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-02

SIN MING AUTOCITY

SINGAPORE 575722

t 6262 8888 f 6452 5333

COMPANY REG. NO.: 200204110W